District [1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

ZRP-3208

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Dalaca Natification and Commenting Action													
Release Notification and Corrective Action OPERATOR Initial Report Final Report													
							OPERATOR [l Report	_Ц	Final Report	
Name of Company: BOPCO, L.P. Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Contact: Amy Ruth Telephone No. 575-887-7329							
						Facility Type: Exploration and Production							
located 2996 ft. SW of Well #1 ApI 30-015-24968)													
Surface Owner: Federal Mineral Owner: F							Federal API No. 30-015-24968						
<u></u>							redetai AFT No. 30-013-24908						
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
Unit Letter Section Township Range Feet from the North.				/South Line	East/West Line County East Eddy			•					
300 1000							2150						
Latitude32.433935°Longitude104.055036°													
NATURE OF RELEASE													
Type of Release Produced Water							Volume of Release 145 bbls Volume Recovered 85 bbls						
Source of Release 1/2" fitting on SWD pump											our of Discovery		
Was Immediate Notice Given?							015 unknown time 8/8/2015 11:30 pm						
Was immediate Notice Given?							If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)						
By Whom? Tony Savoie							Date and Hour 8/9/2015 7:33 am						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No							N/A						
If a Watercourse was Impacted, Describe Fully.* N/A N/A N/A N/M OIL CONSERVATION ARTESIA DISTRICT AUG 17 2015 Describe Cause of Problem and Remedial Action Taken.* A ½" inch fitting on the discharge side of the SWD pump failed. Pump shut down and fitting was repaired. RECEIVED													
Describe Area Affected and Cleanup Action Taken.* The leak affected approximately 2,250 square ft. area of caliche pad directly south of the SWD containment. A vac truck recovered fluids from the zero perm containment as well as from the ground. The leak on the caliche is within an area previously lined with 20-mil plastic. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: OIL CONSERVATION DIVISION													
Signature: // nur (LIC)							Approved by Environmental Specialist:						
Printed Nam	e: Amy Rut	inj											
Title: Assistant Remediation Foreman						Approval Da	te: 6/19]	5 E	xpiration	Date: N	1H		
E-mail Addr	ess: ACRut	h@basspet.co	m			Conditions o				Attache	d 🔲		
Date: 8/	17/21	215	Phone	432-661-0571	Rer	nediation	per O.C.D. Ru	ıles & C	Buideli	nės			

ATER THAN:

Patterson, Heather, EMNRD

From:

Ruth, Amy C. <ACRuth@BassPet.Com>

Sent:

Monday, August 17, 2015 11:06 AM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc:

jamos@blm.gov

Subject:

Initial C-141 BOPCO Indian Flats Bass Federal SWD leak 8-8-2015

Attachments:

Initial C-141 Indian Flats Bass Federal SWD 8-8-15.pdf

Here is the initial report for the leak on 8-8-15. Another will follow for 8-14-15 (this one was not as large, but happened in the exact same spot!)



Amy C. Ruth BOPCO, L.P. EH&S Remediation Specialist 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office: (575)887-7329

Fax: (575)887-7473 Cell: (432)661-0571