



Burnett Oil Co. Spill Report

2RP-3344

10/29/15 onsite meeting OLD, BLM, Burnett

Date: 10/14/15

Lease Name Gissler A 42 Person Completing Report Johnny Titsworth
GPS Reading Date Spill Discover: 10/12/15 Time 9:37 AM
County Eddy State: New Mexico
API/RRC #

1 Type of material spilled: Amount Oil (bbls) 3 Amount Water (bbls):
Amount of Condensate (bbls) Total Water Recovered:
Total Oil or Condensate Recovered 0

2 Cause of Spill: packing leaked from well head

3 Any waterway nearby? Yes No x If yes, name of waterway:

4 Did spill enter waterway? Yes No x

5 How was spill contained? spill was found by lease operator, and repaired

7 Extent of damages. (Attach map if necessary).

8 Area effected (length - width): 3'x50' on pad & 6"x100' in pasture

9 Estimate of clean up costs: (\$) Cost of Damaged Equipment:

10 Landowner informed? Yes No (All Spills)
Date: Time Contact

11 RRC informed? Yes No Name/Time

12 NMOCD informed? Yes x No Name/Time Heather Patterson

13 BLM informed? Yes x No Name/Time Jim Amos

14 NRC informed? Yes No Name/Time

15 EPA informed? Yes No Name/Time
Date: Time: Contact:

16 Did any regulatory official inspect spill or help clean up? Yes x No


Date: 10/13/15 Time: 9:00 AM Contact:

17 Clean up action taken: Area on pad will be scraped. Area in pasture will be sampled and blended with a tiller.

Remarks: Discussed spill with BLM/NMOCD representatives, and we decided to use a tiller to blend impacted area with surrounding clean material. This will eliminate the amount of vegetation that will be disturbed.

Signature: [Signature] Date: 10/14/15

A
N



AH-1	0-1'	1-1'
	1-1.5'	
	2-2.5'	
AH-2	0-1'	
	1-1.5'	
	2-2.5'	
AH-3	0-1'	
	1-1.5'	
	2-2.5'	

