

late C-141
Submission

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1531631260

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	432-685-5771
Facility Name	Cedar Canyon 15 SWD #001	Facility Type	Battery
Surface Owner	Brantley- McDonald	Mineral Owner	
		API No.	30-015-42797

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	15	24S	29E					Eddy

Latitude 32.21710 Longitude 103.97642

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	200 bbls	Volume Recovered	0 bbls
Source of Release	Failure of a transfer line clamp	Date and Hour of Occurrence	10/11/15	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson, Mike Bratcher		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	10/13/15 11:45 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 11 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A transfer line clamp caused 200 bbls of produced water to leak on to the ground. No fluids were recovered and the clamp was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 100' x 250' on and off location. Remediation will be completed in accordance with the remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Dusty Wilson	Approved by Environmental Specialist:	
Title: Environmental Advisor	Approval Date: 11/12/15	Expiration Date: N/A
E-mail Address: : Dusty.Wilson@oxy.com	Conditions of Approval:	
Date: 11/11/15	Remediation per O.C.D. Rules & Guidelines	
Phone:	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 12/12/15

2RP. 3384

Patterson, Heather, EMNRD

From: Jennifer Gilkey <jgilkey@bbcinternational.com>
Sent: Wednesday, November 11, 2015 8:13 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Dusty Wilson; Jennifer_duarte@oxy.com; Frank_Barnett@oxy.com; Cliff Brunson ; Ken Swinney; Kathy Purvis
Subject: Initial C-141, Cedar Canyon 15 SWD #001
Attachments: Initial C-141, Cedar Canyon 15 SWD #001.pdf

Attached is the initial C-141 for a leak that occurred at the Cedar Canyon 15 SWD #001 on 10/11/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

.....
Jennifer Gilkey

Administrative Manager

BBC International, Inc.

Phone: (575) 397-6388

Fax: (575) 397-0397

E-mail: jgilkey@bbcinternational.com

1324 W. Marland Blvd.

Hobbs, NM 88240
.....

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, October 13, 2015 11:45 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: dusty_wilson@oxy.com; Jennifer_duarte@oxy.com; frank_barnett@oxy.com;
cbrunson@bbcinternational.com; kswinney@bbcinternational.com;
jgilkey@bbcinternational.com; kathy@bbcinternational.com
Subject: Cedar Canyon 15 SWD #001

This is to inform you that Oxy Permian had a leak at the Cedar Canyon 15 SWD #001 on October 11, 2015. Oxy spilled 200 bbls of produced water due to failure of a transfer line clamp. The preliminary report shows the leak measuring approximately 100' x 250' both on and off location. No fluids were recovered. The release is located in U/L K, Section 15, T24S, R29E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: Go south out of Carlsbad on US285 to Malaga, turn east on Duarte Rd and go 1.5 miles, turn right on McDonald Rd, cross the river, go through the "S" curve, turn left at 2nd cattleguard, turn right at the next intersection, take left, turn left at 1st pumpjack and go through cattleguard, turn right, take immediate left, take road until it ends at the facility. API# 30-015-42797 GPS coordinates are unavailable at this time.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com