

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-41
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1532364189

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy 11/22/83	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Glycerin 10 Fed Com 1	Facility Type	production
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-36359

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	10	16S	29E	825	N	330	E	Eddy

Latitude 32.06587 Longitude -103.68969

NATURE OF RELEASE

Type of Release	Produced water/crude	Volume of Release	15 bbls PW/5 bbls crude	Volume Recovered	14 bbls PW/4 bbls crude
Source of Release	heater treater	Date and Hour of Occurrence	11/11/2015	Date and Hour of Discovery	11/11/2015
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/ Shelly Tucker		
By Whom?	Christine Alderman	Date and Hour	11/19/2015 11:30 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The fire tube on the heater treater developed a hole due to corrosion

Describe Area Affected and Cleanup Action Taken.*

All fluids were contained within a dirt berm. Samples will be collected and a work plan will be developed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: [Signature]	
Title: ESH Supervisor	Approval Date: 11/19/15	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 11/19/2015 Phone: 432-853-7059	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 12/20/15

2RP-3407

Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Thursday, November 19, 2015 9:14 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: mburton@diversifiedfsi.com
Subject: FW: Glycerin 10 Fed Com #1 (API 30-015-36359)
Attachments: 20151119094527881.pdf

Here is the C-141.

Thank you!

Christine Alderman

ESH Supervisor – Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982



From: Christine Alderman
Sent: Wednesday, November 18, 2015 11:11 AM
To: mike.bratcher@state.nm.us; Patterson, Heather, EMNRD (Heather.Patterson@state.nm.us); stucker@blm.gov
Subject: Glycerin 10 Fed Com #1 (API 30-015-36359)

All,

We had a release on 11/11/2015 at the above location. The fire tube of the heater treater developed a hole due to corrosion. All fluids were contained inside an unlined berm. Approximately 5 bbls of crude oil and 15 bbls of produced water were released, and the majority of the fluids were recovered.

I will send C-141 shortly.

Christine Alderman

ESH Supervisor – Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982

