7GRL Ø9Ø583398

06/16/2009 11:14

#838 P.002/002

2088

Revised October 10, 2003

Form C-141

District I 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Azlec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

"Erom:4326860600

State of New Mexico Energy Minerals and Natural Resources

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

side of form


			Rele	ease Notific	atior	and Co	rrective A	ction			
•						OPERAT	ror			Report Fina	l Repo
Name of Com	pany Bo	C Operating,	Inc	10		Contact Tami Parker					
Address PO				10			io. (432) 684-90	696 ext	218		
Pacility Name	Facility Name South Langlie Jal Unit #11					Facility Typ	e riowine				<del></del>
Surface Owne	Surface Owner Clay Osbourne Mineral Owner			wner				Lease N	o. 27321		
			,			OF REL		·			_
1	Section 8	Township 258	Range 37E	Feet from the 990'	North South	South Line	Feet from the 2310'	East/V West	Vest Line	County Lea	
LatitudeLongitude											
-			200		URE	OF RELE					
Type of Release	: Lease	Oil		•			Release 20 bbls	$\neg \neg$	Volume Ri	ecovered 0 bbls	
Source of Relea	se	line for well #	'1]			2/4/09	our of Occurrence		Date and J 2/4/09	four of Discovery	
Was Immediate	Notice G		Yes 🛭	No Not Rec	quired	If YES, To	Whom?		, -		
By Whom?						Date and Ho					
Was a Watercou	rse React		Yes ⊠	No		If YES, Vol	ume Impacting th	e Water	course.		
If a Watercourse	was Imn	acted Describ	ne Fully.*			<u> </u>					
Describe Cause Rupture in 2-3/8						:	<del></del>		·····		
	•				•	•	٠		•		
Describe Area A 30' x 40' affecte	ffected and area. H	nd Cleanup Ae aul off contar	ction Take ninated so	en.* il and back fill w/	soil off	lease to clear	up location of sp	nill.	•		
	·-···		· · · · · · · · · · · · · · · · · · ·	<del></del>	,			<i>-</i>			
regulations all op public health or t should their open	perators and the environations have attentions have attentions have attentions at the attention at the att	e required to nment. The a re failed to ad lition, NMOC	report and cceptance lequately i D accepta	l/or file certain rel of a C-141 report nvestigate and rer	ease not by the nediate	tifications and NMOCD mar contamination es not relieve	perform correctives as "Final Report that pose a threa	ve action ont" doc t to grow	ns for relea es not reliev and water, :	ant to NMOCD rules and ses which may endanger we the operator of liabilit surface water, human he npliance with any other	r ty
Signature:	-2ar	ni Par	Kon	)			OIL CONSI	<u>ERVA</u>	TION I	DIVISION	
Printed Name: Tami Parker  Approved by District Supervisor:											
Title:	Regulat	ory Analyst	·		_   A	pproval Date:		Ex	piration Da	ite:	
E-mail Address: tparker@blackoakres.com C			c	Conditions of Approval:		Attached [	 				
Date: 2/13/09		Ph	one: (43	32) 684-9696 x 21	8						
Artach Addition	ttach Additional Sheets If Necessary						<del></del>			·- <u></u>	

* *			_
			1
			_
		<i>&lt;</i>	
			5
	, · · ·	•	
			i
•			<b>=</b>
			<b>≡</b> i
			#
		·	
	,		. 1
		,	
	•		<b>=</b>
		,	
			-
			ŀ
	•		
		•	_
			•
			_
			_
			_
	1		

BC Operating, Inc.
South Langlie Jal Unit #11
Unit N, Section 8, Township 25S, Range 37E
Lea County, New Mexico

**Work Plan** 

**August 10, 2009** 



Prepared for:

BC Operating, Inc. PO Box 50820 Midland, Texas 79710

By:

Safety & Environmental Solutions, Inc. 703 East Clinton Street Hobbs, New Mexico 88240 (575) 397-0510

### I. Company Contacts.

NAME	Company	Telephone	E-mail
Gary Stevens	BC Operating, Inc.	432-894-7113	g.stevens2@att.net
Bob Allen	SESI	575-397-0510	ballen@sesi-nm.com

### II. Background

Safety and Environmental Solutions, Inc. (SESI) was engaged by BC Operating, Inc. to perform a site assessment at the South Langlie Jal Unit #11. This is an active well site located in Unit N, Section 8, Township 25 South, Range 37 East. On February 4, 2009, a release occurred from a rupture in a 2-3/8" steel flowline for well #11. Approximately 20 barrels of lease oil was released with no recovery.

### III. Surface and Ground Water

According the database provided by the U.S. Geological Survey (USGS) online database, the average depth of water in this area is 49'.

### IV. Work Performed

On June 5, 2009, SESI was onsite to map the area. The area was mapped using a Trimble Geo XM GPS. The affected area is 30 feet x 40 feet.

On July 15, 2009, SESI was onsite with Watson Construction to attempt to delineate the release. Two test trenches were installed within the affected area. Historic hydrocarbon staining was encountered at 4' to 5' bgl, below the floor of the excavated area. Field TPH samples were collected and indicated elevated hydrocarbon levels. The vertical extent of the contamination was unable to be determined at this time.

On July 21, 2009, SESI was onsite with Eco-Enviro Drilling to further delineate the release utilizing an auger rig. A total of three boreholes were installed within the affected area. Samples were collected at intervals of 5'. A hard rock layer was encountered at borehole #2 at 30' bgl and was unable to penetrate. All the boreholes were plugged to surface with bentonite and hydrated. The grab samples that were collected were transported under chain of custody to Cardinal Laboratories of Hobbs New Mexico, for analysis. In compliance to the New Mexico Oil Conservation Division (NMOCD) set of required sampling conditions, the samples were analyzed for Chlorides (EPA Method 4500-Cl¯B), Total Petroleum Hydrocarbons (EPA Method 8015), and Benzene, Toluene, Ethyl Benzene, and Xylenes (BTEX) (EPA Method SWA-846 8021 B). The results were as follows:

Sample ID	Chlorides (mg/kg)	GRO (C6 – C10) (mg/kg)	DRO (C10 – C28) (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl Benzene (mg/kg)	Xylenes (mg/kg)
Analysis Date:	7/21/09	7/21/09	7/21/09	7/21/09	7/21/09	7/21/09	7/21/09
BH#1 8'BGL	2560	<10.0	1210	<0.050	<0.050	0.191	0.365
BH#1 13' BGL	352	<10.0	66.7	<0.050	< 0.050	<0.050	<0.300
BH#1 18' BGL	144	<10.0	<10.0	< 0.050	<0.050	< 0.050	< 0.300
BH#2 9' BGL	1060	548	8030	0.054	1.56	5.36	8.51
BH#2 14' BGL	144	786	8510	< 0.050	0.403	5.08	6.58

				_
	•			-
				•
		•		
				_
				_
				.==
				_
				-
				- 8
				-
				_
	•		•	
			•	
				•
				-
	•			_
		•		_
				_
	,			
				- 5
				-
·				
				- 5
				-
			•	-
				-

BH#2 19' BGL	96	665	7860	<0.050	0.421	6.03	9.43
BH#2 24' BGL	<16	311	2510	<0.050	<0.050	10.1	10.7
BH#2 29' BGL	80	341	4830	<0.050	0.157	2.30	3.87
BH#2 30' BGL	464	524	8420	<0.050	0.241	1.83	4.99
BH#3 6' BGL	3080	2410	6580	0.181	2.42	8.05	18.0
BH#3 11' BGL	384	<10.0	643	<0.050	<0.050	0.223	0.820
BH#3 16' BGL	464	<10.0	84.1	<0.050	<0.050	<0.050	<0.300
BH#3 21' BGL	400	<10.0	<10.0	<0.050	<0.050	<0.050	<0.300


### V. Action Plan

It is requested that the affected area be excavated to a depth of 10' bgl. The most highly contaminated soils will be transported to Sundance Services, a New Mexico Oil Conservation Division (NMOCD) approved facility for disposal. The excavated area will then be backfilled and domed to 4' bgl with like soils. A 20 mil plastic liner will be installed to prevent any of the historic contamination that was discovered from further migrating. The excavation will then be backfilled to surface and contoured to grade.


### VI. Figures & Appendices

Figure 1 – Vicinity Map Figure 2 – Site Plan Appendix A – Analytical Results Appendix B—Site Photos Appendix C –C-141


					-
					-
					_
			•		
					_
	•				
					•
					-
					-
					_
					-
					_
					_
		•			
					•
					_
•					-
					•
					-
					_
					_
					•
					-
					-
					1



			-
			=
			I
			1
			1
	•		•
			ţ
			I
			1
			1
		·	-
			I
			1
•			ı
			I
			1
			•
			•



			•
			•
			Į.
			•
			I
			•
			_
			_
			_
			<del></del>
			I
			1
			-
			1
			•
			1
	•		•
			1
			1
			•
•			1
			•
			1
			•



			1
		•	1
·			!
		•	1
			1
			1
			1
	•		I
	•		1
			1
·			1
			•
			. 1
			1
			I



ANALYTICAL RESULTS FOR

SAFETY & ENVIRONMENTAL SOLUTIONS

ATTN: BOB ALLEN 703 E. CLINTON, #102 HOBBS, NM 88240 FAX TO: (575) 393-4388

Receiving Date: 07/21/09 Reporting Date: 07/22/09

Project Number: BCO-09-001 (BC OPERATING)

Project Name: SOUTH LANGLIE #11

Project Location: JAL, NM

Analysis Date: 07/22/09 Sampling Date: 07/21/09

Sample Type: SOIL

Sample Condition: COOL & INTACT @ 5.5°C

Sample Received By: ML

Analyzed By: HM

		Cl
LAB NO.	SAMPLE ID	(mg/kg)
H17850-1	BH#1. 8' BGS	2,560
H17850-4	BH#29' BGS	1,060
H17850-10	BH#3. 6' BGS	3,080
	<del></del>	
Quality Contro	<u> </u>	500
True Value QC	;	500
% Recovery		100
Relative Perce	nt Difference	< 0.1

METHOD: Standard Methods 4500-CIB

Note: Analyses performed on 1:4 w:v aqueous extracts. Not accredited for Chloride.

Chemist )

Date

07/28/09

H17850 SESI

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whather such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

. . • . · •



ANALYTICAL RESULTS FOR SAFETY & ENVIRONMENTAL SOLUTIONS

ATTN: BOB ALLEN 703 E. CLINTON, #102 HOBBS, NM 88240 FAX TO: (575) 393-4388

Receiving Date: 07/21/09 Reporting Date: 07/30/09

Project Number: BCO-09-001 (BC OPERATING)

Project Name: SOUTH LANGLIE #11

Project Location: JAL, NM

Analysis Date: 07/30/09 Sampling Date: 07/21/09

Sample Type: SOIL

Sample Condition: COOL & INTACT @ 5.5°C

Sample Received By: ML

Analyzed By: HM

		Cl
LAB NO.	SAMPLE ID	(mg/kg)
H17850-2	BH#1, 13' BGS	352
H17850-3	BH#1. 18' BGS	144
H17850-5	BH#2. 14' BGS	144
H17850-6	BH#2. 19' BGS	96
H17850-7	BH#2. 24' BGS	< 16
H17850-8	BH#2. 29' BGS	80
H17850-9	BH#2. 30' BGS	464
H17850-11	BH#3. 11' BGS	384
H17850-12	BH#3. 16' BGS	464
H17850-13	BH#3. 21' BGS	400
Quality Cont	rol	500
True Value (	QC	500
% Recovery		100
Relative Per	cent Difference	< 0.1

METHOD: Standard Methods 4500-CIB

Note: Analyses performed on 1:4 w:v aqueous extracts. Not accredited for Chloride.

Chemist

Date

### H17850B SESI

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

					-
					_
					I
					•
					•
					<b>5</b>
					•
		•			_
					1
					•
					•
			•		
					Mina
					_
					1
					•
					•
			•		l l
					<b>.</b>
					•
					_
			•		•
					#
			•		•
					· •
					1
				•	
					•
-					<b></b>
•					I
					•
	•				•



ANALYTICAL RESULTS FOR

SAFETY & ENVIRONMENTAL SOLUTIONS, INC.

ATTN: BOB ALLEN 703 E. CLINTON, #102 HOBBS, NM 88240 FAX TO: (575) 393-4388

Receiving Date: 07/21/09 Reporting Date: 07/28/09 Sampling Date: 07/21/09 Sample Type: SOIL

Project Owner: BC OPERATING (BCO-09-001)

Sample Condition: COOL & INTACT @ 5.5°C

Project Name: SOUTH LANGLIE #11

Sample Received By: ML Analyzed By: AB/ZL

Project Location: JAL, NM

LAB NO. SAMPLE ID GRO DRO ETHYL TOTAL  $(C_6-C_{10})$  (> $C_{10}-C_{28}$ ) BENZENE TOLUENE BENZENE XYLENES (mg/kg) (mg/kg) (mg/kg) (mg/kg) (mg/kg) (mg/kg)

ANALYSIS DATE:	07/23/09	07/23/09	07/24/09	07/24/09	07/24/09	07/24/09
H17850-1 BH #1, 8' BGL	<10.0	1,210	<0.050	<0.050	0.191	0.365
H17850-2 BH #1. 13' BGL	<10.0	66.7	<0.050	<0.050	<0.050	<0.300
H17850-3 BH #1. 18' BGL	<10.0	<10.0	<0.050	<0.050	<0.050	<0.300
H17850-4 BH #2. 9' BGL	548	8,030	0.054	1.56	5.36	8.51
H17850-5 BH #2. 14' BGL	784	8,510	<0.050	0.403	5.08	6.58
H17850-6 BH #2. 19' BGL	665	7,860	<0.050	0.421	6.03	9.43
H17850-7 BH #2. 24' BGL	311	2,510	<0.050	<0.050	10.1	10.7
H17850-8 BH #2. 29' BGL	341	4,830	<0.050	0.157	2.30	3.87
H17850-9 BH #2. 30' BGL	524	8,420	<0.050	0.241	1.83	4.99
H17850-10 BH #3. 6' BGL	2,410	6,580	0.181	2.42	8.05	18.0
H17850-11 BH #3, 11' BGL	<10.0	643	<0.050	<0.050	0.223	0.820
H17850-12 BH #3. 16' BGL	<10.0	84.1	<0.050	<0.050	<0.050	<0.300
H17850-13 BH #3. 21' BGL	<10.0	<10.0	<0.050	<0.050	<0.050	<0.300
Quality Control	528	541	0.056	0.056	0.053	0.168
True Value QC	500	500	0.050	0.050	0.050	0.150
% Recovery	106	108	112	112	106	112
Relative Percent Difference	6.3	2.9	<1.0	1.8	2.6	<1.0

METHODS: TPH GRO & DRO - EPA SW-846 8015 M; BTEX - SW-846 8021B.
TEXAS NELAP ACCREDITATION T104704398-08-TX FOR BENZENE, TOLUENE, ETHYL BENZENE, AND TOTAL XYLENES. Reported on wet weight. Not accredited for GRO/DRO.

+ H17850-1 and H17850-11 TPH GRO/DRO surrogate outside historical limits due to matrix interference.

\*\* H17850-4 BTEX surrogate outside historical limits due to matrix interference.

Lab Director

H17850 TPHETEX SESI

07/28/09 Date

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential demages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its substituties, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

		•
		1
		I
		-
		•
	1	•
•		1
		_
		•
		I
		1
	•	•
		I
		·
		I
		•
		•
		•
		1
•		
		1
		_
		•
		ı
		i
		•

# CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

ARDINAL LABORATORIES, INC.

2111 Beechwood, Abilene, TX 78603 101 East Mariand, Hobbs, NM 88240

30 days pack due at the rate of 24% per annount from the original date of theories and all costs of calculations, producting attorney's hear. 90 ANALYSIS REQUEST 5108 Phone Result: Fax Result: REMARKS: 5/60 ŝ 90 10/ BILL TO SAME **Z**lb: ; ABHTO ICE / COOF (505) 393-2326 Fax (505) 393-2476 Company: Phone #: Address: CID/BYZE: P.O. #: Fax#: State: Attn: City: : ABHTO SLUDGE Operating QI,F POIL 393-4388 SOLUTIONS HELAWETSAW 88240 GROUNDWATER Zip: d ď 4MO(0) HO BAR(0) IJ ত (915) 673-7001 Fax (915) 673-7020 (505)50/17/km SAFETY & ENVIRONMENTAL Project Owner: State: NM Time Fax # #102 Sample I.D. (505) 397-0510 E. CLINTON, Project #: 1500-09-00 150 V Project Name: Sout Sampler Relinquishe 703 Project Location: HOBBS Project Mariagen 9 Sampler Name: Company Name: TEXSE HOTE LABLE FOR LAB USE ONLY Lab I.D. Address: Phone #: CIty:

t Cardinal cannot accept verbal changes. Please fax written changes to (915) 673-7020.

Deliverad By: (Circle One) Sampler - UPS - Bus - Other:

Checked By: (Initials)

Sample Condition

Date: Time:

Relinguished By

Temp

**が** 

14C1-added 7130109 as per Susana.

	•			
				_
				. 7
				- 8
				-
		•		9
				-
				•
				- 8
		•		
				<b>1</b>
				1
				-
				-
				_
				1
				<b>4</b>
			,	_
				-
•				
•				-
				_
				_
•				
		•		
				4
4		•		
				_
•				
				_
				-
				<b>*</b>
•				•
				_
•				<b>#</b>
				-
				-
				•
			•	_
				. <u></u>
				-
				-
				-
				-

## CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

|--|

	•
	•
•	
	1
	•
	1
	1
	1
	1
	ï
	•

## CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST  BE ANALYSIS REQUEST  ANALYSIS ANALYSIS REQUEST  ANALYSIS REQUEST  ANALYSIS ANALYSIS ANALYSIS ANALYSIS REQUEST  ANALYSIS ANALYS	Terms and Charleshere: Interest will be charged on all amounts more than 300 days post down it the rate of 21% per amount than the original data of freedom and all costs at Cookections, including attenting a heart.  1 Yes 1 No
Company Name:   SAFETY & ENVIRONMENTAL SOLUTIONS   Company   SAME   CLINTON, #102   Clinton   Company   SAME   CLINTON, #102   Clinton   Company   Clinton   Clin	PRINTE I standy and Dumpart Cardinals fability and clearly reclaims namely by eyothern aring whether based o certained of the clearly and Charles and any other council to be specified to the clear of the clear and the clear an


		1
	:	I
		1
		I
		Î
		I
		I
		Î
•		
		1
	•	1
		1
		<del></del>







	-
	Ĭ
	•
·	ł
	<del></del>
	è
•	
•	•
	_
	Ĭ
	I
	_
	I
	•
	1
	1
	_
	I
•	
	ļ
	1
	Ē
	1
	-






		Ť
		•
		Į
		į
		ı
		•
·		
		<b>#</b>
		I
		Ĭ
		Î
•		Ĩ
		•
		e E
		•





,			•
			I
. •			<b>1</b>
		•	
			Ì
·			
			I
			ı
	•		
	•		1
			Đ
			Ä
			H
•			Ĩ
			~
			•
			ų.
			Ħ





	•
	•
	·
	•
	·
	<b>.</b>
	mi en
	•
	The state of the s
•	■
	I I
	<del>ः ।</del>
·	II.
	1
	<u> </u>
	_
	· •
	•
	•
	■
·	
·	_
	•
	<b>.</b>
	<b>ú</b>
	***
	-
	<u></u>
	in the state of th
•	
	_
	•
	g .
	2
	~
	fis.
	H







Í


• . • . . .







	1
	_
	Ţ
	-
	•
,	<b>a</b>
	•
·	
	15
	Ì
•	
•	100
	5
	•
	¥
$\cdot$	1
	-
	Æ
	ŀ
	· *=
•	





	_
	•
•	•
-	
	_
	Ì
•	
·	
	•
	_
	8
	<b>50</b>
	•
	_
	10
	į
	5
	-
•	Î
	ł
	<del>-</del>
·	
	_





,

				•				
								_
								- 1
								-
			•	•				
		•						
								_
								- 8
				i				7
					•			
								_
								_
		•						- 2
								=
								-
								_
								_
				•		,		
					,			
								-
							•	
								_
								_
						•		- V
						•		_
								_
					•			
								- 5
								-
								•
•								
								1
								-
								-
	•			•	•			. ,
								•
_								
								_



			- 1
	·		-
		·	3
			i
			1
			ı
			•
			1
			I
			-
			•
			# -
			•
			ŧ
			1
			1