

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

JAN 28 2016 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1602952102

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU #012H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-22162
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22S	30E	1450	North	1830	East	Eddy

Latitude 32.380851° Longitude -103.883785°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	Volume Recovered
Source of Release	Discharge flow line	22 bbls pw	5 bbls pw
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Date and Hour of Occurrence	Date and Hour of Discovery
By Whom?	Amy Ruth	1/18/2016 time unknown	1/18/2016 4:30 pm
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, To Whom?	
		Mike Bratcher/Heather Patterson (NMOCD)	
		Date and Hour	1/19/2016 at 8:21 am
		If YES, Volume Impacting the Watercourse.	N/A

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

The discharge line from the triplex pump to the well head developed a leak below ground surface. Line was isolated, then excavated and repaired.

Describe Area Affected and Cleanup Action Taken.*

The leak affected 7,135 ft² of well pad. Standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: 	
Title: EHS Remediation Specialist	Approval Date: 1/29/16	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 1/27/2016 Phone: 432-661-0571	SUBMIT REMEDIATION PROPOSAL NO 31116	

* Attach Additional Sheets If Necessary

LATER THAN: 3/1/16

2RP-3524

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Wednesday, January 27, 2016 4:39 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: RE: JRU 12H 1-18-16
Attachments: Initial C-141 JRU 12H 1-18-16.pdf

Please find the associated initial form C-141 for this spill event. We have sprayed the pasture down with microblaze and have scraped saturated soils away from the central part of the well pad. Those soils are temporarily stockpiled on plastic at the location. They will be removed to disposal and the site will be remediated. Again, feel free to call me with any questions/concerns.

From: Ruth, Amy C.
Sent: Tuesday, January 19, 2016 8:21 AM
To: Mike Bratcher; EMNRD Patterson Heather
Subject: JRU 12H 1-18-16

I was informed of an accidental release at our referenced location that occurred yesterday. Please see details below. I will follow up with a form C-141. Please call me with any questions/concerns. Thank you.

Amy Ruth
432-661-0571

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" <DJFuqua@BassPet.Com>
To: "Ruth, Amy C." <ACRuth@BassPet.Com>, "Blevins, Bradley" <BBlevins@BassPet.Com>, "Cottle, Richard" <RCottle@BassPet.Com>, "Johnson, Steve F" <SJohnson@BassPet.Com>, "Hanna, Wesley W." <WWHanna@BassPet.Com>
Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: james ranch unit 012h bopco l.p.
Description: API: 3001522162
Latitude: 32.380966
Longitude: -103.883559

See a Map of this Well<<http://maps.google.com/maps?saddr=&daddr=32.380966,-103.883559>>

For additional information regarding the Wellsite Navigator app check us out in the Google Play Store<<https://play.google.com/store/apps/details?id=com.sitefinder.wellsitenavigatorusa>> or in the iTunes App Store<<https://itunes.apple.com/us/app/wellsite-navigator-usa-pro/id594298510?mt=8&uo=4>>

[image2.jpeg] [image3.jpeg] Lease operator reported release due to discharge line rupture from triplex pump to WH used to operate jet pump. Failed line was isolated and vac truck in route.

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Wednesday, January 27, 2016 4:42 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: RE: JRU 12H 1-18-16

Apologies! This summary was in reference to our other leak at the BEU DI-9 Battery for 1-21-2016. I will forward shortly. This attached C-141 is correct though. Thank you ☺

From: Ruth, Amy C.
Sent: Wednesday, January 27, 2016 4:38 PM
To: Mike Bratcher; EMNRD Patterson Heather
Subject: RE: JRU 12H 1-18-16

Please find the associated initial form C-141 for this spill event. We have sprayed the pasture down with microblaze and have scraped saturated soils away from the central part of the well pad. Those soils are temporarily stockpiled on plastic at the location. They will be removed to disposal and the site will be remediated. Again, feel free to call me with any questions/concerns.

From: Ruth, Amy C.
Sent: Tuesday, January 19, 2016 8:21 AM
To: Mike Bratcher; EMNRD Patterson Heather
Subject: JRU 12H 1-18-16

I was informed of an accidental release at our referenced location that occurred yesterday. Please see details below. I will follow up with a form C-141. Please call me with any questions/concerns. Thank you.

Amy Ruth
432-661-0571

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" <DJFuqua@BassPet.Com>
To: "Ruth, Amy C." <ACRuth@BassPet.Com>, "Blevins, Bradley" <BBlevins@BassPet.Com>, "Cottle, Richard" <RCottle@BassPet.Com>, "Johnson, Steve F" <SJohnson@BassPet.Com>, "Hanna, Wesley W." <WWHanna@BassPet.Com>
Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: james ranch unit 012h bopco l.p.
Description: API: 3001522162
Latitude: 32.380966
Longitude: -103.883559

See a Map of this Well<<http://maps.google.com/maps?saddr=&daddr=32.380966,-103.883559>>

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Tuesday, January 19, 2016 8:21 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: JRU 12H 1-18-16
Attachments: image2.jpeg; image3.jpeg

I was informed of an accidental release at our referenced location that occurred yesterday. Please see details below. I will follow up with a form C-141. Please call me with any questions/concerns. Thank you.

Amy Ruth
432-661-0571

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" <DJFuqua@BassPet.Com<mailto:DJFuqua@BassPet.Com>>
To: "Ruth, Amy C." <ACRuth@BassPet.Com<mailto:ACRuth@BassPet.Com>>, "Blevins, Bradley" <BBlevins@BassPet.Com<mailto:BBlevins@BassPet.Com>>, "Cottle, Richard" <RCottle@BassPet.Com<mailto:RCottle@BassPet.Com>>, "Johnson, Steve F" <SJohnson@BassPet.Com<mailto:SJohnson@BassPet.Com>>, "Hanna, Wesley W." <WWHanna@BassPet.Com<mailto:WWHanna@BassPet.Com>>
Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: james ranch unit 012h bopco l.p.
Description: API: 3001522162
Latitude: 32.380966
Longitude: -103.883559

See a Map of this Well<<http://maps.google.com/maps?saddr=&daddr=32.380966,-103.883559>>

For additional information regarding the Wellsite Navigator app check us out in the Google Play Store<<https://play.google.com/store/apps/details?id=com.sitefinder.wellsitenavigatorusa>> or in the iTunes App Store<<https://itunes.apple.com/us/app/wellsite-navigator-usa-pro/id594298510?mt=8&uo=4>>
[image2.jpeg] [image3.jpeg] Lease operator reported release due to discharge line rupture from triplex pump to WH used to operate jet pump. Failed line was isolated and vac truck in route. Lease operator verified pin hole in steel discharge line.

Sent from my iPhone
[cid:5:2382:0]
[cid:5:2382:1]