

## **AE Order Number Banner**


## **Report Description**


This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.




**App Number:** pGRL1318656118


1RP - 2935 CRAIN'S HOT OIL SERVICE, INC.





12-11-2012 - REPRINT - CRAIN HOT OIL SERVICE - GULF DEEP OOT SWD






12-11-2012 REPRINT - CRAIN HOT OIL SURVICE-GULF DEEP #1 SWD

## RE: GUILF DEEP OOI

PENTROC TOOK CONTRUL WELL LATER SOLD


Submit 1 Copy To Appropriate District Office	State of New Mo	exico 70 <	iain hot oil	Form C-103
District 1	Energy, Minerals and Natu	ral Resources	WELLADING	October 13, 2009
1625 N. French Dr., Hobbs, NMP CEI	/ED	DURMON	WELL API NO. ; 30-005-012	10
			7. Indicate Type of Lease	
District (III 1000 Rto Brazos Rd . Aztec. NM 87310 Santa Fe NM 87505				EE 🗍
District IV 1220 S. St. Francis Dr., Santa Fe, MOBBSO 87505	Santa Fe, NM 87	7303	7. State Oil & Gas I.	ease No.
	AND REPORTS ON WELLS		7. Lease Name or Unit Ag	reement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Gulf Decg	,
1. Type of Well: Oil Well Gas Well Other SWD		8. Well Number 001		
2. Name of Operator			9. OGRID Number	,
Penroc Oil Corporation			17213	
3. Address of Operator P.O. Box 2769 Hobbs, New Mexico 88241-2769			10. Pool name or Wildcat SWD; San An	dres
4. Well Location				
	feet from theNorth			stline
Section 34 Township 14S Range 31E NMPM Chaves County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
			[2] 李寶寶 以編纂 (100-83)	學問題 (2.77.16) 的 (3.88)
12. Check Appro	priate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
				NG CASING 🔲
TEMPORARILY ABANDON   CHA	<del>-</del>			Α 🔲
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB			T JOB 🔲	
DOWNHOLE COMMINGLE				
OTHER:		OTHER:		
13. Describe proposed or completed of		pertinent details, an		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.  Per NMOCD SWD-1158-0				
Per NMOCD SWD-1138-0				
Set and test anchors Move in Joes Well Service 10/1/2009				,
Dig out cellar and remove PA marker x Weld on 9 5/8" x 3000 psi well head equipped with 2-2" outlets and visives				
Nipple up BOP				
Drill cement plugs Surface x 405ft x 2350ft x tag plug at 3743ft x pressure test casing to 500psi x OK				
Drill out cement plugs to total depth of 4700ft				
Circulate clean x Lay down DC x ND BOP x Hang 2 7/8" tubing in well at 3700ft				
Shut in pending acquisition of downhole disposal equipment x New Mexico State Land Office SWD casement Will notify NMOCD of pending MIT				
will notify (who eld of pending with				
Snud Data:	Rig Release Da	ta		
Spud Date:	Kig Kelease Da			
			,	
I hereby certify that the information above	is true and complete to the be	st of my knowledg	e and helief	
·	13 true una comprete to the ce	accorning amounted	c and owner.	
SIGNATURE De Chid	fee Ct TITLE Presi	dent	DATE 😂	tober 20, 2009
Type or print name _M.Y.(Merch)Mercha				
For State Use Only	PETE	ENGINE	isti no	T 26 2009
APPROVED BY: Conditions of Approval (if any):	TITLE		DATE	<del>-</del>



12-11-2012 REPRINT - CRAIN HOT OIL SERVICE - GULF DEEP #1 SWD









CRAIN WOLL OIL

