

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 08 2016

Form C-141
Revised August 8, 2011

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

NAB1606931025 Release Notification and Corrective Action

FAB1606931366

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Regency Field Services <u>298751</u>	Contact: Johnnie Bradford
Address: 600 N. Marienfeld Street	Telephone No. (432) 250-5542 (cell) (817) 302-9812 (off)
Facility Name: California 1943 Lateral	Facility Type: Pipeline
Surface Owner:	Mineral Owner:
API No.	

LOCATION OF RELEASE

Unit Letter M	Section 23	Township 26S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 1.3433 N Longitude 103 51.5241 W

NATURE OF RELEASE

Type of Release: Liquid/Gas	Volume of Release: 8 bbls liquid/144.43 Mscf	Volume Recovered: None
Source of Release: Damaged Clamp	Date and Hour of Occurrence: 03/07/2016 12:30	Date and Hour of Discovery: 03/07/2016 12:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Pair - BLM/Mike Bratcher - NMOCD	
By Whom? Johnnie Bradford	Date and Hour: 03/08/2016 09:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
Water Course was not impacted.

Describe Cause of Problem and Remedial Action Taken.*

A 4" pipeline lateral that had been clamped previously developed a leak on the clamp where the rubber seal came loose from the clamp. The affected area will be remediated until no apparent contamination exists. All the spoils from remedial activities will be placed on plastic prior to disposal classification and removal to an NMOCD approved landfill. The remediated area will be sampled from the bottom of the excavation to ensure cleanup has been achieved by ensuring that contaminant levels are at or below the NMOCD RRAL.

Describe Area Affected and Cleanup Action Taken.*

The affected area is a path beginning at the lateral pipeline in the western corner of the pad site extending to the north east approximately 200 feet. Clean up of the affected area will begin once a one call has been cleared.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Johnnie Bradford</u>	OIL CONSERVATION DIVISION	
Printed Name: Johnnie Bradford	Signed By: <u>Mike Bratcher</u> Approved by Environmental Specialist:	
Title: Sr. Environmental Specialist	Approval Date: <u>3/9/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: johnnie.bradford@energytransfer.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 03/08/2016 Phone: 432-250-5542	SUBMIT REMEDIATION PROPOSAL NO <u>4110116</u> LATER THAN: <u>4/10/16</u>	

* Attach Additional Sheets If Necessary

2RP-3602

Bratcher, Mike, EMNRD

From: Bradford, Johnnie <Johnnie.Bradford@energytransfer.com>
Sent: Tuesday, March 08, 2016 10:05 AM
To: Randal Pair; Bratcher, Mike, EMNRD
Cc: Johnson, Rachel
Subject: California 1943 Lateral Leak
Attachments: 03072016-C-141-AsSub.pdf

Randy/Mike,

Attached is a C-141 for the leak described in our conversation this morning. I will follow-up within the next few days with a work plan for your approval.

If you should have any questions, please don't hesitate to give me a call.

Sincerely,

Johnnie Bradford



Johnnie Bradford | Sr. Environmental Specialist
600 N. Marienfeld Suite 700: Midland, TX 79701
O: 817.302.9812 | M: 432.250.5542
johnnie.bradford@energytransfer.com