District 1	state of New Mexico						Form C-141				
1625 N. French Dr.	. Hobbs. NM 88240	)	Energy Minerals and Natural Resources			es	Revised June 10, 2003				
District II	, 10000, 1011000.										
1301 W. Grand Ave	mue, Artesia, NM 8	8210							,		
Distric III Oil Conservation Division Submit 2 Copies to approp									Copies to appropriate		
					St. Francis Dr.			District Office in accordance			
					NM 87505			with Rule 116 on back			
									side of form.		
30 0/5-26386 Release Notification and Corrective Action											
OPERATOR Initial Report I Final Report											
			nergy Corporation		Contact Gene B		Brookshire				
Address P.O. Box 69			Loco Hills, NM 88255	Telephone No. 505-420							
Facility Name         Turner B South Well #85         Facility Type         Oil Well											
Surface Owner BLM			Mineral Owner NA		NA		Lease N	o. LC-02	9395-B		
LOCATION OF RELEASE											
Unit Letter	Section	Township	p Range Fee	t from	Feet from	Longi	tude-W	Latitude-N	County		
В	29	175	I SEK I	h Line	West Line				Eddy		
		· · · · ·	3	975	3945	<u> </u>					
NATURE OF RELEASE											
Type of Release					of Release	1.1.1	Volume	Recovered	1.1.1		
Crude Oil Source of Release					d Hour of Occ	bbl	Date on	<u>0</u> i Hour of Disco	bbl		
Well head					11/23/04 10:30 AM			11/23/04 10:30 AM			
Was Immediate Notice Given?					If YES, To Whom?						
	YES										
By Whom? NA					Date and Hour						
Was a Watercourse Reached?					If YES, Volume Impacting the Watercourse						
If a Waternourse	una Immastad	NA									
If a Watercourse was Impacted, Describe Fully*											
Describe Cause of Problem and Remedial Action Taken. *											
1" nipple on pumping tee broke, repaired by pumper on-site at time of release. Approximately 4-bbl of crude oil released before repair											
was facilitated. Clean soil was blended in to absorb liquids and material was stockpiled.											
Describe Area A	ffected and Cle	anum Action	Taken *								
				Footad by	v "A-bbl omda	ail mia	ee Cont	ominated soil :	was blanded on		
Approximate 1000-ft <sup>2</sup> area (5' X 200') southwest of the well head affected by ~4-bbl crude oil release. Contaminated soil was blended on site to below action levels; utilized to construct downgradient berms to prevent future off-site migration.											
SAC IN DEION ACTION REVERS, MIMARA OF CONSIGNACION DETAIS IN PREVENT AUTOR OTI-SAC MABIANOL											
	÷		plete to the best of my knowledge and		•		-		•		
certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment.											
In addition, NMOCD ad	cceptance of a C-141 r	eport does not relie	eve the operator of responsibility for or	mpliance wi	h any other federal, s	tate, or local	laws and/or n	egulations.			
· · · · ·			A n		011	CONSET		NDIVISION			
Signature: Ohn Land					T. Gram by Wile Brother						
Printed Name: John Good					by Mile Brother						
					Approved by District Supervisor:						
Title:	tle: SESI - Project Consultant					Approval Date: 2/10/05 Expiration Date: N/A					
E-Mail Address: <u>ballen@sesi-nm.com</u>					Conditions of Approval:						
Date:	1/6/2005	Phone:	505-397-0510								
				1							

]]

]

]

]

٦.