District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

JUN 1 4 2016 Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action	
NAB1416737278	OPERATOR
Name of Company: BOPCO, L.P. 247731	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329 Facility Name: Legg Federal 001 Facility Type: Exploration and Production	
Surface Owner: Federal Mineral Owner	er: Federal API No. 30-015-04734
LOCATION OF RELEASE	
Unit Letter Section Township Range Feet from the No B 27 22S 30E 540 No	rth/South Line Feet from the East/West Line County East Eddy
Latitude 32.368906° Longitude -103.867843°	
NATURE OF RELEASE	
Type of Release Crude Oil and Produced Water	Volume of Release 45 bbls oil Volume Recovered 30 bbls oil
Source of Release Three phase vessel	18 bbls pw 10 bbls pw
The phase vesser	6/3/2016 time unknown 6/3/2016 7 pm
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Requir	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Shelly Tucker (BLM)
By Whom? Amy Ruth	Date and Hour 6/4/2016 11:14 am
Was a Watercourse Reached? ☐ Yes ☑ No	If YES, Volume Impacting the Watercourse. N/A
If a Watercourse was Impacted, Describe Fully.* N/A	
Describe Cause of Problem and Remedial Action Taken.* JRU 12H well surged and the three phase vessel gas supply pot failed. Fluids exited the pressure relief valve on the vessel. The three phase vessel was isolated for repair and the well was left flowing to the two phase vessel of the test train.	
Describe Area Affected and Cleanup Action Taken.* The leak affected 14.940 sq. ft. of location caliche pad. Standing fluids were recovered.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Signature: Amy C. Ruth	OIL CONSERVATION DIVISION Approved by Environmental Specialist:
Title: EHS Remediation Specialist	Approval Date: 4 1416 Expiration Date: NA
E-mail Address: ACRuth@basspet.com Date: 6/14/2016 Phone: 432-661-0571	Conditions of Approval: Remediation per O.C.D. Rules & Guidelinds SUBMIT REMEDIATION PROPOSAL NO
* Attach Additional Sheets If Necessary	SUBMIT REMEDIATION PROPOSALING PRO-3741

Patterson, Heather, EMNRD

From:

Ruth, Amy C. < ACRuth@BassPet.Com>

Sent:

Tuesday, June 14, 2016 10:32 AM

To:

Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD

Cc:

Shelly Tucker

Subject:

RE: Legg Federal 001 accidental release 6-3-16 notice

Attachments:

Initial C-141 Legg Federal 001 6-3-16.pdf

Hello Everyone,

Here is the C-141 for the release notification below. I wanted to be sure our internal spill report recently released confirmed our initial assessment of the cause of the leak before releasing the form. Apologies for the delay. Thanks and have a good day.

From: Ruth, Amy C.

Sent: Saturday, June 04, 2016 11:14 AM

To: Heather.Patterson@state.nm.us; Mike Bratcher

Cc: Shelly Tucker

Subject: Legg Federal 001 accidental release 6-3-16 notice

All, BOPCO EHS has recently been notified of an accidental release associated with our Legg Federal 001 battery. We are sending this email to provide immediate notice and will submit a form C-141 with all pertinent follow up information. Please call with any questions. Thank you.

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" < DJFuqua@BassPet.Com >

Date: June 4, 2016 at 10:19:01 AM MDT

To: "Ruth, Amy C." < <u>ACRuth@BassPet.Com</u>>, "Blevins, Bradley" < <u>BBlevins@BassPet.Com</u>>, "Cottle, Richard" < RCottle@BassPet.Com>, "Johnson, Steve F" < SJohnson@BassPet.Com>,

"Hanna, Wesley W." < WWHanna@BassPet.Com >, "Dach, Michael M."

<MDDach@BassPet.Com>, "Fuentes, Frank O." <FOFuentes@BassPet.Com>

Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: legg federal 001 bopco, l.p. Description: API: 3001504734

Latitude: 32.368584 Longitude: -103.866852

See a Map of this Well

For additional information regarding the Wellsite Navigator app check us out in the <u>Google Play</u> Store or in the iTunes App Store

Contractor unloading at JRU 21 SWD station reported fluid spraying from vessel inside Legg Fed Btry at 7 pm MST. Night lease operator was dispatched to location. The release was exiting

PRV of JRU #12H three phase vessel due to gas supply pot failure and well surging. The well was left flowing to two phase vessel of test train and three phase vessel isolated. Lease operator contacted vac truck which recovered 30 BO & 10 BW of standing fluid.

Sent from my iPhone