NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 14 2016 ۰.

Form C-141 Revised August 8, 2011

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410

State of New Mexico

Energy Minerals and Natural Resources

District III 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505					Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505			RÉ	<b>RECEIVED</b> by to appropriate District Office in accordance with 19.15.29 NMAC.					
Release Notification and Corrective Action														
NABIU   [074]   7]   OPERATO     Name of Company: BOPCO, L.P.   340737   Contact: Amy F									$\boxtimes$	Initial Re	port		Final Report	
Name of C	Contact: Amy Ruth													
Address: 52	Telephone No. 575-887-7329													
Facility Name: Legg Federal 001 Facility Type: Exploration and Production   Surface Owner: Federal Mineral Owner: Federal														
Surface Ow	Federal			API No. 30-015-04734										
				LOC	ATIO	N OF REI	EASE							
Unit Letter B	Section 27	Township 22S	Range 30E	Feet from the 540	North	South Line	Feet from 2300	the East East	st/West I	Line   Cou   Edd	-			
<u> </u>		223	<u></u>	······				t,t,	<u>.                                    </u>		<u>y</u>			
Latitude <u>32.369037°</u> Longitude <u>-103.867859°</u>														
Type of Release   Crude Oil and Produced Water   Volume of Release   0.5 bbl oil   Volume Recovered   0 bbl														
Type of Rele	ease	Crude Oil and	a Produced	l Water		Volume of Release 0.5 bbl o 9 bbls F			1	ume Recov	erea u	001		
Source of Re	elease	Test Heater	r			Date and H 6/9/2016 ti			ce Date and Hour of Discovery 6/9/2016 7 pm					
Was Immedi	Was Immediate Notice Given?						Whom?	/11	0/9/	2010 7 pm				
	Yes No X Not Required													
By Whom? N/A						Date and Hour N/A								
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse. N/A								
If a Waterco N/A	urse was In	pacted, Descr	ibe Fully.*	•					<u></u>					
Describe Cause of Problem and Remedial Action Taken.* A manway gasket failed on the test heater unit. Unit was drained and isolated for repair.														
Describe Area Affected and Cleanup Action Taken.* The leak affected 4,056 sq. fl. of caliche pad, most of which was an overspray.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local faws and/or regulations.														
Signature: Printed Marin	Approved by Environmental Speciality													
Title. El	HS Remedia	ation Specialis	st			Approval Dat	e: 614	116	Expir	ation Date:	N/A	1		
E-mail Addr	Conditions of Approval: Remediation per O.C.D. Rules & Guidelineed SUBMIT REMEDIATION PROPOSAL NO													
	4/2016 itional She	ets If Necess		2-661-0571		SUBMIT F	<u>{EMEUI/</u> 14N:	7/15/	14			$\lambda D \overline{c}$	)- TTAL	
			-				·····				U	ncr	· 0 147	

## Bratcher, Mike, EMNRD

From:	Ruth, Amy C. <acruth@basspet.com></acruth@basspet.com>
Sent:	Tuesday, June 14, 2016 12:54 PM
То:	Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc:	Tucker, Shelly
Subject:	Initial C-141 Legg Federal 6-9-2016
Attachments:	Initial C-141 Legg Federal 001 6-9-16.pdf; DSCF4583.JPG; IMG_0808.MOV.mov

Hello again everyone,

There was another release from the Legg Federal Battery on June 9<sup>th</sup>. A gasket on a test heater failed and misted fluids upward and out onto the location. Most of the pooling took place within the bermed area. This also occurred mostly over the same area that was impacted by the recent leak that happened on June 3<sup>rd</sup> for which I submitted the C-141 earlier today. Please find the attached initial form for the new leak and please call me with any questions. Thank you...

## \*

Amy C. Ruth BOPCO, L.P. EH&S Remediation Specialist 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office: (575)887-7329 Fax: (575)887-7473 Cell: (432)661-0571