

# **AE Order Number Banner**

#### Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pGRL0935754494

1RP - 2366

**PURVIS OIL CORP** 

## Purvis Operating Co.

3101 N. Pecos Street - 79705

Email: land@purvisop.com

PO Box 51990 Midland, TX 79710-1990

432-682-7346

## RECEIVED

Via E-Mail and US Mail

February 15, 2010

FEB 1 7 2010 HOBBSOCD

Mr. Geoffrey Leking Oil Conservation Division 1625 North French Drive Hobbs, New Mexico 88240

RE:

Gladiola SWD Section 26 Release Site

T-12S, R-37E, Section 26, Unit Letter J, NMOCD # 09-16-2366

Dear Mr. Leking:

As you know, Purvis Operating Co. is resigning as operator of the Gladiola SWD. The purpose of this letter is to describe the status of outstanding issues with NMOCD to facilitate the transition to the new operator.

### Gladiola SWD Section 26 Release Site T-12S R-37E Section 26, Unit Letter J,

NMOCD #1RP 09-16-2366 (Property owner: Dean Kinsolving)

Purvis recently submitted a revised investigation plan to NMOCD District 1 with copies to the surface owner and their attorney. We anticipate that the new operator will implement the investigation and then submit a remedial plan consistent with Part 29 of NMOCD Regulations. We have been delayed in our investigative efforts due to problems with access. We believe these problems will be resolved shortly.

## Gladiola SWD Section 26 Release Site T-12S, R-37E Section 26, Unit Letter J, NMOCD # 1RP-09-9-2284 (attached)

This is the same site as 2366 discussed above. This case refers to the second release at this location within the original spill foot print. As stated in our C-141 relating to this second release, we recovered 250 barrels of produced water from this second spill.

We are concerned by the attached notes associated with the NMOCD Online file for this case (No. 2366). We have no record of a request by NMOCD to cease using this pipeline. The notes appear to be associated with a release in Section 5 T12S 38E Unit Letter H. We have no record of a release at this location. Could these notes be associated with another operator?

### Gladiola NE Release Site, T 12S R38E Section 18 Unit Letter O,

NMOCD Case # 1R-498 (Property owner: Dean Kinsolving)

Purvis recently submitted an investigation plan to NMOCD Environmental Bureau with copies to the surface owner and their attorney. We anticipate that the new operator will implement the investigation and then submit a remedial plan consistent with Part 29 of NMOCD Regulations.

#### Gladiola SWD Release Site, T 12S R37E Section 25 Unit Letter A,

NMOCD Case # 1R- 1739 (Property owner: Tommy Burrus)

Purvis recently submitted an investigation plan to NMOCD Environmental Bureau with copies to the surface owner and their attorney. We anticipate that the new operator will implement the investigation and then submit a remedial plan consistent with Part 29 of NMOCD Regulations.

### Gladiola No. 2 Release Site, T 12S R38E Section 30 Unit Letter D,

NMOCD Case # Not Assigned (Property owner: Tommy Burrus)

This release occurred on February 3, 2010, within a valve box of the Gladiola SWD system pipeline. It is located just east of the Gladiola SWD release described above (1R-1739). Purvis recently completed an initial investigation and a Characterization Plan will be sent to your office with copies to the surface owner and their attorney. We anticipate that the new operator will implement the investigation and then submit a remedial plan consistent with Part 29 of NMOCD Regulations.

Sincerely,

Donnie Brown

Purvis OperatingCo.

c: Mr. Tommy Burrus

Mr. Dean Kinsolving

Mr. Patrick B. McMahon, Esq.

Mr. Robert Lang, Chaparral Operating

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rto Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fc, NM 87505

State of New Mexico RECEIVED
Energy Minerals and Natural Resources
DEC 14 2009


Oil Conservation Division, 1220 South St. Francis Dr. 1220 South St. Francis Dr. 1220 Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

### Release Notification and Corrective Action

	Release Notific	auon	and Co	orrective A	Cuon	l			
			<b>OPERA</b>	TOR		x Initi	al Report		Final Report
Name of Company	Purvis Operating Co.		Contact	Donnie I	E. Brow	'n	-		
Address	PO Box 51990, Midland, TX 79710	1	Telephone 1	No. 432-682	-7346				
Facility Name	Gladiola SWD System	F	Facility Typ	e Saltwate	r Dispo	sal Syster	n		
Surface Owner	Dean Kinsolving Mineral O	wner	Unknown			Lease N			
	LOCA	TION	OF RE	LEASE		30	.025.		07141
Unit Letter Section 26			South Line	Feet from the 2200' approx.	East/V East	Vest Line	County		
(See Attached Map)		Souui	Long		East		Lea		
(See Attached Map)		UDE				-			
To a CD I		UKE	OF REL			Malara F	· · · · · · · · · · · · · · · · · · ·	_	-
Type of Release	Produced Saltwater		Volume of	. 250-300 bbls.			Recovered N x. 250 h		
Source of Release	6" PVC Pipe Line			of Occurrence:			Hour of Dis		
Source of Itelease	o o . ipe 2o			.m. of 12-9-09		Daily and	11:25 a.m. o		0-2009
Was Immediate Notice			If YES, To						
By Whom? De		quired	Date and H	Geoffrey Leking our 3:30 p.m	12-10	2000			
Was a Watercourse Ro				lume Impacting t					
,	Yes No		None	in parting i					
If a Watercourse was l	Impacted, Describe Fully.*								
Net Imparts							1	1 1	
Not Impacte	a.						1		
					٠.,	· GIW	9 37		
Describe Cause of Pro	blem and Remedial Action Taken.*								
A coller on a	6" PVC saltwater disposal line failed that leak	kad saltu	unter The ni	so was dua un an	d rapaire	d The soil	that was du	~	
	uled to a land farm and replaced with fresh so							a	
1									
Describe Area Affecte	d and Cleanup Action Taken.*				:	*1			
The area affe	ected is approximately the same area that was	s reporte	ed on Form C	-141 dated Augus	t 21 20	09 Vertica	and lateral		
	ion of the affected area will be done before re								
I been been and Control of		1	4-1-6		1 1	. 14.		111.404	op 1 1
	he information given above is true and com- ors are required to report and/or file certain								
	nvironment. The acceptance of a C-141 rep								
	s have failed to adequately investigate and re								
	In addition, NMOCD acceptance of a C-14 laws and/or regulations.	1 report	t does not re	lieve the operato	r of res	ponsibility	for complia	ince w	ith any other
rederal, state, or local	laws and/or regulations.	1		OIL CONS	EDV	ATION	DIVISIO	NI	
47	782			OIL CON	0/			14	
Signature:	melloun	_	-		_	ohu	Som		
Printed Name: Do	onnie E. Brown	A	approved by	District Supervisor	ONME	NTAL E	NGINEER	?	
Title: Pe	troleum Engineer			: 12-16-09			Date: 2 · 11		
E-mail Address: eng	g@purvisop.com	C	conditions of	Approval:			Attached		
Date: December 10.	2000 . Dhana 122 692 7246						IRP# 8	Va. 14	. 2366
Date: December 10.					-		141 - 5	7.10	1 60 60



file gat RBOMS	egorts Yew Becords		500 260	00108	Type	question for help
Inspections	in in	Incidents	1 2 m	TO CHARLES D	a de la granda de l La granda de la gra	
Oeneral Spil / ReicheniNo- IncidentiNo- Inci	Splied GALI r 300 BBL 1   1   1   1   1   1   1   1   1   1	of 1 Aging infrastructur Dimensions	t Source  Di Pipeline (Arry) Equip  Area Affected  Areal Extense  Est 22,599 [St	Cause ment Falure  Water way		
Method of Cleanup, Ev		Long	g Calc GO	P Affected?		
ak on 6" transite trun mierous, repetious lea			OCD to cease useage of the bigs.	this line due to		
				this line due to		
merous, reputious le		nd water depth to 2	V bgs.			NLM.