District I 1625 N. French Dr., Hobbs, NM 88240				State of New Mexico ARTESIA DISTRICT Form C-141									
District II 811 S. First St., Artesia, NM 88210				Energy Minerals and Natural Resources					2 6 2016			igust 8, 2011	
District III 1000 Rio Brazos Road, Aztec, NM 87410					Oil Conservation Division Submit 1 Copy to appropriate accordance with						ute Distri th 19.15.	ct Office in 29 NMAC.	
District IV 1220						uth St. Francis Dr.							
	, NM 875	· · · · · · · · · · · · · · · · · · ·											
Release Notification and Corrective Action													
NAB1024241470 11,01,02						OPERATOR Initial Report Final Report							
Name of Company Cimarex Energy						Contact Christine Alderman Telephone No. 432-853-7059							
Facility Na			o whulan			Facility Type production							
				Minanal (									
Surface Owner BLM     Mineral Owner     API No. 30-015-34109       LOCATION OF RELEASE													
· Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/	West Line	County			
		-	245	1600		·	1200						
H	01	25S	25E			N		i	Е	Eddy			
Latitude32.16200 Longitude -104.34468													
NATURE OF RELEASE													
Type of Release Source of Re							Release 104 bb. lour of Occurrence		Volume Recovered 100 Date and Hour of Discovery				
Source of Re	icase inderg	51235 talik				Bale and Hold of Occurrence         Date and Hold of Discovery           8/25/2016         8/25/2016					.oreiy		
Was Immedia	ate Notice (		No 🗌 Not Re	equired	If YES, To Whom? d Shelly Tucker/Heather Patterson								
By Whom?	Christine A	Iderman			-	Date and Hour 8/26/2016							
Was a Watero		hed?	Yes 🛛	L Ma		If YES, Volume Impacting the Watercourse.							
			NO										
If a Watercourse was Impacted, Describe Fully.													
Describe Cau					ohtning	The tank wa	is blown out of co	ntainm	cut outo the	nod. The w	eil is shi	at in and	
							a lined berm which			pad. the w	un la ant		
Describe Area	a Affected a	and Cleanup A	ction Tak	en.									
All fluids were removed from the berm and the liner will be checked for breaches. Rainwater was also in the containment.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
or the enviror federal, state,				tance of a C-141	report do	es not reliev	e the operator of i	respons	ibility for co	mpliance w	ith any o	ther	
icultur, and,	A		OIL CONSERVATION DIVISION										
Signature: Christine alderman													
			<u>un</u>		/	Approved by Environmental Specialist:							
Printed Name	: Constine	Algerman					9 nalil		(]-		λ		
Title: ESH S	upervisor					Approval Dat			Expiration 1	1	<u>n</u>		
E-mail Address: calderman@cimarex.com						Conditions of Approval: Remediation per O.C.D. Rules & Guidelinesd							
Date: 8/26/2016 Phone: 432-853-7059						SUGMIT REMEDIATION PROPOSAL NO							
* Attach Additional Sheets If Necessary ATER THAN:										D. 3851			

## Patterson, Heather, EMNRD

From:	Christine Alderman <calderman@cimarex.com></calderman@cimarex.com>
Sent:	Friday, August 26, 2016 10:49 AM
То:	stucker@blm.gov; Amos, James A (jamos@blm.gov); Patterson, Heather, EMNRD
Subject:	Vern 1 Fed 1 (30-015-34109)
Attachments:	20160826113428654.pdf

At the above location we had lightning strike a fiberglass PW tank. It blew the tank out of LINED containment onto the pad. The well had been shut in for several days and was not producing; the last gauging of the tank showed 104 bbls of PW. It did not appear that any PW was on location and stayed inside the containment.

Please call if you have any questions. Thanks!

**Christine Alderman** 

Cimarex Energy Co.

ESH Supervisor - Permian Basin Midland TX Cell - 432.853.7059