



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number: pJXK1624354770**

**1RP - 4422**

**GRAND BANKS ENERGY CO**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD** State of New Mexico  
Energy Minerals and Natural Resources  
AUG 26 2016  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

X Initial Report  Final Report

Name of Company	Grand Banks Energy	Contact	Denise Jones
Address	10 Desta Drive, Ste 300-E, Midland, TX 79705	Telephone No.	432-620-9181
Facility Name	Anderson Ranach Unit # 16 ✓	Facility Type	Disposal

Surface Owner	Mineral Owner	API No.	30-025-00368 ✓
---------------	---------------	---------	----------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
X L	2	16S	32E	1980	South	660	West	Lea

Latitude 32.9489403 Longitude -103.7435379

**NATURE OF RELEASE**

Type of Release	Spill of oil and water	Volume of Release	2000 bbls	Volume Recovered	10 bbls oil
Source of Release	SWD Water Tank	Date and Hour of Occurrence	8/10/16 6:00 AM	Date and Hour of Discovery	8/10/16 2:00PM
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes		
By Whom?	Denise Jones	Date and Hour	08/10/16 3:00PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Storm in the area turned the pump off and shut down the automation thus causing the tanks to overflow

Describe Area Affected and Cleanup Action Taken.\*  
750'x15' around facility. Oil was recovered and we are removing contaminated soil. Hungry Horse Environmental is working on the clean-up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Denise Jones</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Denise Jones	Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Title: Regulatory Analyst	Approval Date: <i>8/30/16</i>	Expiration Date: <i>10/30/16</i>
E-mail Address: <a href="mailto:djones@cambridgmgmt.com">djones@cambridgmgmt.com</a>	Conditions of Approval: <i>Discrete samples only. Delicately remediate per NMOCD Guidelines.</i>	Attached <input type="checkbox"/> <i>LRP 4422</i>
Date: 08/10/16 Phone: 432-620-9181		

\* Attach Additional Sheets If Necessary

*njk/1624352/668*  
*njk/1624354770*