										IL CONSERVATION RTESIA DISTRICT	
1023 N. FICHCH LIT., HONDS, INVI 88240						f New Mexico			SEF	2 8, 2016 CEIVED Form C-141 Revised August 8, 2011	
811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 So						s and Natural Resources ervation Division hth St. Francis Dr.			Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.		
1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505											
Release Notification and Corrective Action											
Name of Company Beach Exploration, Inc. 1903						OPERATOR Initial Report					
Address 800 N. Marienfeld, Suite 200, Midland, TX 79701 Facility Name Eastland Queen Unit						Telephone No. 432/683-6226					
;					Facility Type Waterflood Satellite test Battery						
Surface Ow	ner State			Mineral C	Jwner :	State			API No. 30-015-26095 Unit Number: 300337		
LOCATION OF RELEASE											
Unit Letter C				Feet from the 990	he North/South Linc Feet from North 990		Feet from the 990	East/V West	West Line	County Eddy	
Latitude32.681395_° Longitude104.046659°											
The CD of				NAT	URE	OF RELI					
Type of Release 3 bbls oil/water mix Source of Release Cattle knocked over fence around battery and rubbed						Volume of Release Est. 3 bbi Volume Recovered 3 bbi Date and Hour of Occurrence Date and Hour of Discovery					
on ¼" valve on tester Murphy switch. Was Immediate Notice Given?						Est 9/6/16 11:30a.m. 9/6/16 4:00 pm If YES. To Whom?					
		No Not R	equired	Beach Exploration, Inc. from OCD							
By Whom? OCD Was a Watercourse Reached?						Date and Hour 9/20/16 3:17pm If YES, Volume Impacting the Watercourse.					
Yes X No											
If a Watercourse was Impacted, Describe Fully.* NA											
Describe Cau	ise of Proble	em and Reme	dial Actio	n Taken *I eak di	e to catt	le knocking o	ver fence around	battery	and rubbed	1 on 1/2" valve on tester Murphy	
Describe Cause of Problem and Remedial Action Taken.*Leak due to cattle knocking over fence around battery and rubbed on 1/4" valve on tester Murphy switch opening and releasing 3 bbls oil/water onto caliche well pad. Cleaned area and netted tank.											
		and Cleanup A						<u> </u>	<u> </u>		
	Three barrels of oil/water mix leaked. We closed 1/2" valve. Oil/water was cleaned up and we put netting on open tank. Please see attached pictures (3).										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
l Sant Ch.						OIL CONSERVATION DIVISION					
Signature: JACK ////////////////////////////////////						Approved by Environmental Specialist:					
Title: Engineer						Approval Date: 9 28 16 Expiration Date: N/A					
E-mail Addr	ess: bmartin	n@beachexp.c			Conditions of Approval: Remediation per O.C.D. Rules & Guidelinesched						
	Date: 9/20/2016 Phone:432/683-6226 BMIT REMEDIATION PROPOSAL NO									0	
* Attach Addi	itional She	ets If Necess	ary			ATER THA	IN:	1116	2	2RP. 3915	

. .

Patterson, Heather, EMNRD

From:	Brenda Martin bmartin@beachexp.com>
Sent:	Tuesday, September 20, 2016 2:45 PM
То:	Patterson, Heather, EMNRD
Subject:	C-141 for API 30-015-26095
Attachments:	Resized952016090995115411 (3).jpg; Resized952016090995120303 (3).jpg;
	Resized952016090995120514 (3).jpg; C-141 EQU 24 - API 30-015-26095.pdf
Importance:	High

Categories:

watch

Heather,

Sorry for the delay.

Thank you,

 c_{i}^{r}

Brenda Martín Production Beach Exploration, Inc. 800 North Marienfeld Suite 200 Midland, Texas 79701 (432) 683-6226 Telephone (432) 683-1038 Fax e-mail: bmartin@beachexp.com