District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## NM OIL CONSERVATION ARTESIA DISTRICT

OCT 1 9 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

<b>Release Notification and Corrective Action</b>							
NAB1429554325	A	OPERATOR	Initial Report	Final Report			
Name of Company: BOPCO, L.P.	260731	Contact: Bradley Blevins					
Address: 522 W. Mermod, Suite 704 Carlsba	Telephone No. 575-887-7329						
Facility Name: PLU 261	Facility Type: Exploration and Production						
Surface Owner: Federal	Mineral Owne	er: Federal	API No. 30-015-3	34877			

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	21	245	30E		1980	1880		Eddy

Latitude: 32.20171 Longitude: 103.88377

## NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 20 barrels	Volume Recovered: 2 barrels				
Source of Release: Failed Gasket on Heater Treater	Date and Hour of Occurrence:	Date and Hour of Discovery:				
	10-18-16 @ 1:00pm	10-18-16 @ 1:25pm				
Was Immediate Notice Given?	If YES, To Whom?					
🗌 Yes 🔲 No 🖾 Not Required						
By Whom?	Date and Hour					
Was a Watercourse Reached?	If YES, Volume Impacting the Wat	ercourse.				
🗋 Yes 🖾 No						
If a Westmann I and A Density Delle *						
If a Watercourse was Impacted, Describe Fully.*						
		Ň				
Describe Cause of Problem and Remedial Action Taken.*						
Lease operator reported a release at the PLU 261 due to a failed heater tr						
equipment. A vacuum truck was called to the location and was able to re	cover 2 barrels of oil from the ground	surface.				
Describe Area Affected and Cleanup Action Taken.*						
A vacuum truck was called to the location and was able to recover 2 bar	els of ail from the around surface					
A vacuum truck was caned to the location and was able to recover 2 barrels of on from the ground surface.						
I hereby certify that the information given above is true and complete to	the best of my knowledge and understa	ind that pursuant to NMOCD rules and				
regulations all operators are required to report and/or file certain release						
public health or the environment. The acceptance of a C-141 report by t	he NMOCD marked as "Final Report"	does not relieve the operator of liability				
should their operations have failed to adequately investigate and remedia						
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other						
federal, state, or local laws and/or regulations.						
	OIL CONSERV	ATION DIVISION				
Signature: Tradley Blowing						
Signature: Tradley Blow	Approved by Environmental Brail 1/4 Brancescon					
Printed Name: Bradley Blevins	Approved by Environmental Specialist 11/4 Drawterless					
Title: Assistant Remediation Foreman	Approval Date: [D][9]][0]	Expiration Date: N/A				
E-mail Address: bblevins@basspet.com	Conditions of Approval:					
	Remediation per O.C.D. R					
Date: 10/19/2016 Phone: 432-214-3704	SUBMIT REMEDIATION P					
Attach Additional Sheets If Necessary	LATER THAN:	17/ DOD XANT				
•		The arriver				

State of New Mexico Energy Minerals and Natural Resources

Sume CEnvery appropriate District Office in accordance with 19.15.29 NMAC.

## Bratcher, Mike, EMNRD

From: Sent: To: Cc: Subject: Attachments: Blevins, Bradley <BBlevins@BassPet.Com> Wednesday, October 19, 2016 1:20 PM Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; jamos@blm.gov Blevins, Bradley Initial C-141 PLU 261 Initial C-141 PLU 261 10-18-16.pdf

All,

BOPCO EHS was notified of a release that occurred at the PLU 261 due to a failed heater treater gasket, 18 barrels of oil was released with 2 barrels recovered by vacuum truck. If you have any questions please let me know.

Thanks

Brad Blevins BOPCO, LP 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office-575-887-7329 Cell-1-432-214-3704 bblevins@basspet.com

÷