WIN OIL CONSERVATION

Form C-141 Revised April 3, 2017

ARTESIA DISTRICT OCT 2 4 2017

State of New Mexico **Energy Minerals and Natural Resources**

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

District III 1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

811 S. First St., Artesia, NM 88210

District II

District IV

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in **RECEIVED** NMAC.

Release Notification and Corrective Action

NAB17				GRID-#37	12096	OPERA'	TOR	7.00		al Report	\boxtimes	Final Report		
Name of Co				$\overline{}$	Contact Raquel Chacon									
			exas 77056		Telephone No. 281-910-0441 (cell) 575-297-0988 (office)									
Facility Nar	ne: Red Li	ght 27-34 St	ate Com	2H	Facility Type Oil and gas production facilities									
Surface: Ov	ner: state		Owner:	state			API No. :3001543917							
LOCATION OF RELEASE														
Unit Letter Section Township Range Feet from the North D 27 23S 26E 150 North						1 1			West Line County Eddy					
D		233	20E				west		Eddy					
32. 28208 Latitude See list Longitude See list NAD83 NATURE OF RELEASE														
Type of Release Fire							Volume of Release di minus Volume Recovered NA							
Source of Release: braided steel line pin hole											Date and Hour of Discovery			
Was Immediate Nation City 2							10/16/2017 2:30 am 10/16/2017 2:30 am							
Was Immediate Notice Given? ☐ Yes ☑ No ☐ Not Required							If YES, To Whom? Crystal Weaver voice mail and by email after discovery of gas leak as cause							
By Whom? Jenifer Van Curen							Date and Hour 10/18/2017 9:27 am (email)							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.							
☐ Yes ☒ No														
If a Watercourse was Impacted, Describe Fully.*														
Not applicable.														
Describe Cause of Problem and Remedial Action Taken.*														
The discharge line of the compressor on the Red Light location began to pressure up. As a result, the PRV released gas pressure. The steel braided														
discharge line to the PRV had a small leak which was ignited when the compressor backfired. The well was immediately shut in and extinguished with a fire extinguisher. The braided steel line has been replaced with a steel hard line.														
The oxinguisment. The oxinged seed line has been replaced with a seed hard line.														
Describe Area Affected and Cleanup Action Taken.*														
												-		
No clean up required, repairs have been made to compressor.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and														
							nd perform correc							
public health	or the envi	ronment. The	acceptance	e of a C-141 repo	ort by the	NMOCD n	narked as "Final R	eport" d	loes not rel	ieve the oper	ator of	liability		
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health														
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
						OIL CONSERVATION DIVISION								
Raquel Chacon Signature: Printed Name: Raquel Chacon														
							Approved by Environmental Byecialist /4 Branches							
Title: Sr. HES Environmental Professional						Approval Da	te: 10/24/1		Expiration	Date: 🔨	士			
E-mail Address: rchacon@marathonoil.com						Conditions of Approval:								
Date: October 24 2017						FINAL				Attached				
Date: October 24, 2017 Phone: 281-910-0441(cell) 575-297-0988 (office)							100-445							

Bratcher, Mike, EMNRD

From: Chacon, Raquel (MRO) < rchacon@marathonoil.com>

Sent: Tuesday, October 24, 2017 3:42 PM

To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; agroves@slo.state.nm.us

Subject: C-141 Red Light

Attachments: C-141 Form Marathon Oil 2017 10 16 Red Light Fire.doc

Let me know if you have any questions on this thank you!

Raquel Chacon
HES Environmental Professional
2423 Bonita St.
Carlsbad, NM 88220

Office: (575)297-0988 Cell: (281)910-0441

Weaver, Crystal, EMNRD

From: Van Curen, Jennifer (MRO) <jvancuren@marathonoil.com>

Sent: Wednesday, October 18, 2017 9:27 AM

To: Weaver, Crystal, EMNRD; Chacon, Raquel (MRO)

Cc: Bratcher, Mike, EMNRD **Subject:** RE: Marathon reporting

Attachments: IMG_1972.jpg; IMG_1970.jpg; IMG_1966.jpg

I don't think they have a volume since it was a small pin hole. It did cause a fire though, which is why I called it in. Initially they thought the compressor had an electrical or other issue since it was just placed there.

It was the Red Light 27 34 State Com 2H. A steel line had a pinhole and was leaking small amounts of gas after the line froze. The compressor backfired causing a spark to set this gas on fire. The flowback hand on site shut well down to pull gas off line and took an extinguisher over a to put out the flame. The NOx sensor is damaged and the temp scanner mounted on the left side of the engine received damage from the heat. As soon as I get any other information, I will get that to you. Please see attached photos.

From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]

Sent: Wednesday, October 18, 2017 10:15 AM

To: Van Curen, Jennifer (MRO) < jvancuren@marathonoil.com >; Chacon, Raquel (MRO) < rchacon@marathonoil.com >

Cc: Bratcher, Mike, EMNRD < mike.bratcher@state.nm.us>

Subject: [External] Marathon reporting

Beware of links/attachments.

Hello Jennifer.

I got your voice mail. Since the volume was not stated and you were uncertain of any locational information (well name and/or coordinates) for the spill, I was unable to document Marathon's release. We prefer that all operators disclose releases to us in an email format. I had discussed that with Wendy as well and she was on board with that process. Voice messages are very difficult to document even when all the information is provided. So if Marathon could move to reporting immediate notification and any other notification via email that would ideal.

With that being said if you could send in an email documenting your release you mentioned on the voicemail that would be great. We ask that operators to include as much relevant information that they are aware of at the time that would be asked for on the Initial C-141 form.

Thanks,

Crystal Weaver

Environmental Specialist OCD – Artesia District II 811 S. 1st Street Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963 Fax: 575-748-9720