

Highlander Environmental Corp.

Midland, Texas

June 2, 2005

Mr. Wayne Price New Mexico Energy, Minerals, & Natural Resources Oil Conservation Division, Environmental Bureau 1220 S. St. Francis Drive Santa Fe, New Mexico 87504



RE: Work Plan for the Spill at the Former Texaco South Eunice Gas Plant Remediation System Tank Battery, Located in the NW/4, SW/4, Section 27, Township 22 South, Range 37 East, Lea County, New Mexico, Operated by Chevron Environmental Management Company.

Dear Mr. Price:

Highlander Environmental Corp. (Highlander) was contacted by Chevron Environmental Management Company to assess and to remediate the soil impact from a spill that occurred at the former Texaco Eunice #1 (South) Gas Plant (Site), located approximately 4.5 miles south of Eunice, New Mexico. The Site is situated in the northwest quarter (NW/4) of the southwest quarter (SW/4), Section 27, Township 22 South, Range 37 East, Lea County, New Mexico. Figure 1 presents a site location and topographic map.

The spill occurred on May 26, 2005, when lighting struck an above ground storage tank, and the tanks caught fire. This tank battery is for storage of product and produced water recovered by a groundwater remediation system in operation at the site. Approximately 350 barrels of fluid were spilled and 330 barrels were recovered. The majority of the oil in the tanks was consumed in the fire, but an estimated 1 barrel of oil was contained inside the facility firewall. The produced water was primarily contained inside the facility firewall, however, the firewall was breached on the southwest and northwest corners. The fire was extinguished by the Eunice Volunteer Fire Department. The initial Form C-141 is included in Appendix A.

Site Inspection

On May 26, 2005, Highlander personnel inspected the spill area. The oil had been contained inside the facility firewall and the areas where produced water had breached the firewall measured approximately 50' x 150' and 30' x 50'. The impacted areas are shown on Figure 2. Lacily - PPACO6 15653712 Dincident - nPACO615653800

(432) 682-4559

Fax (432) 682-3946

Groundwater and Regulatory

Based upon the monitor wells located at the facility, the depth to groundwater at this site is 52'-56' below ground surface.

A risk-based evaluation was performed for the Site in accordance with the NMOCD Guidelines for Remediation of Leaks, Spills and Releases, dated August 13, 1993. The guidelines require a risk-based evaluation of the site to determine recommended remedial action levels (RRAL) for benzene, toluene, ethylbenzene and xylene (collectively referred to as BTEX) and total petroleum hydrocarbons (TPH) in soil. The proposed RRAL for benzene was determined to be 10 parts per million (ppm) or milligrams per kilogram (mg/kg) and 50 ppm for total BTEX (sum of benzene, toluene, ethylbenzene and xylene). Based upon the depth to groundwater, the proposed RRAL for TPH is 1000 mg/kg.

Work Plan

Any residual oil staining will be excavated, raked or tilled. Once the damaged tanks have been removed and the location has had ample time to dry, Highlander will sample the spill areas using a stainless steel, bucket-type hand auger. Soil samples will be taken at 1.0' increments for evaluation of TPH by EPA method 8015 DRO/GRO (modified), benzene, toluene, ethylbenzene, and xylene (BTEX) by EPA method 8021B and chloride by EPA method 300.0. All samples will be collected and preserved in laboratory prepared sample containers, shipped under proper chain-of-custody control and analyzed within the standard holding times. The site will then be evaluated for either further investigation or closure. If the RRAL are achieved, the excavation will be backfilled with clean fill material. Once the remedial activities are performed, a closure report will be submitted for your review.

If you require any additional information or have any questions or comments, please contact us at (432) 682-4559.

Highlander Environmental Corp.


Timothy M. Reed, P.G.


Vice President

cc.

Chevron EMC – Scott Toner Secor – Ronnie J. Kallus, Jr. NMOCD, Hobbs – Chris Williams

FIGURES





APPENDIX A

State of New Mexico Form C-141 <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

						OPERA?	TOR		⊠ Initia	al Report		Final Repor	
							Contact Scott Toner						
						Telephone No. 432-687-7318							
Facility Name Eunice South Gas Plant						Facility Type Ground Water Remediation							
Surface Owner Versado LLP Mineral Owner V						Unknown			Lease No. Unknown				
				LOCA	TION	OF RE	LEASE						
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/V	Vest Line	County			
	27	22 S	37 E							Lea			
Latitude N/A Longitude N/A													
NATURE OF RELEASE													
Type of Release Oil / Produced Water							Volume of Release 1 bbl / 350 bbls			Volume Recovered 1 bbl / 250 bbls			
Source of Release Rupture of above ground storage tanks						Date and Hour of Occurrence 5/26/05, 5:00 AM			Date and Hour of Discovery 5/26/05, 5:30 AM				
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Gary Wink							
By Whom? Scott Toner						Date and Hour 5/26/05, 1:26 PM							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. N/A							
10 337						<u></u>							
ii a waierco	urse was im	pacted, Descri	ibe runy.	Watercourse ne	ot impa	ictea.							
Describe Cause of Problem and Remedial Action Taken.* Lightening struck above ground storage tanks and the tanks caught fire. Most of the oil in the tanks burned in the fire, but 1 barrel was released inside the secondary containment. Approximately 350 barrels of produced water was released inside the secondary containment, but damage to the berm allowed some produced water to get outside the secondary containment. The fire was extinguished by the Eunice Volunteer Fire Dept. Highlander Environmental responded and locked out and tagged all equipment that was part of the remediation system to isolate the tanks.													
Describe Area Affected and Cleanup Action Taken.* The area inside the secondary containment held the oil and most of the produced water. The berm was slightly damaged, and some of the produced water got outside of the berm. Tank trucks were called to the site, and they removed the oil and produced water from inside of the berm. The berm was repaired with a backhoe. Tank trucks are currently working to recover produced water outside of the berm. Oil stained soil will be excavated and disposed.													
regulations a public health should their or the enviro	all operators a or the envi operations honment. In a	are required to ronment. The nave failed to a	o report ar acceptance adequately OCD accep	e is true and comple nd/or file certain rel ce of a C-141 repor r investigate and rel stance of a C-141 re	lease no t by the mediate	otifications as NMOCD m contaminati	nd perform correct arked as "Final R on that pose a thre	tive acti eport" d eat to gr	ons for rele oes not reli ound water	eases which in the control of the co	may e ator o ter, hi	ndanger f liability ıman health	
Signature: Signature:						OIL CONSERVATION DIVISION							
						Approved by District Supervisor:							
Title: Remediation Project Manager						Approval Date: E			Expiration Date:				
E-mail Address: stoner@chevrontexaco.com						Conditions of Approval:			Attached				
Date: 5/26/			432-687-7	318				=		<u> </u>			
Attach Addi	itional She	ets If Necess	arv										

116 RELEASE NOTIFICATION AND CORRECTIVE ACTION [1-1-50...2-1-96; A, 3-15-97]

116.A. NOTIFICATION

- (1) The Division shall be notified of any unauthorized release occurring during the drilling, producing, storing, disposing, injecting, transporting, servicing or processing of crude oil, natural gases, produced water, condensate or oil field waste including Regulated NORM, or other oil field related chemicals, contaminants or mixture thereof, in the State of New Mexico in accordance with the requirements of this Rule. [1-1-50...2-1-96; A, 3-15-97]
- (2) The Division shall be notified in accordance with this Rule with respect to any release from any facility of oil or other water contaminant, in such quantity as may with reasonable probability be detrimental to water or cause an exceedance of the standards in 19 NMAC 15.A.19. B(1), B(2) or B(3). [3-15-97]
- 116.B. REPORTING REQUIREMENTS: Notification of the above releases shall be made by the person operating or controlling either the release or the location of the release in accordance with the following requirements: [5-22-73...2-1-96; A, 3-15-97]
 - (1) A Major Release shall be reported by giving both immediate verbal notice and timely written notice pursuant to Paragraphs C(1) and C(2) of this Rule. A Major Release is:
 - (a) an unauthorized release of a volume, excluding natural gases, in excess of 25 barrels;
 - (b) an unauthorized release of any volume which:
 - (i) results in a fire;
 - (ii) will reach a water course;
 - (iii) may with reasonable probability endanger public health; or
 - (iv) results in substantial damage to property or the environment;
 - (c) an unauthorized release of natural gases in excess of 500 mcf; or
 - (d) a release of any volume which may with reasonable probability be detrimental to water or cause an exceedance of the standards in 19 NMAC 15.A.19. B(1), B(2) or B(3). [3/15/97]
- (2) A Minor Release shall be reported by giving timely written notice pursuant to Paragraph C(2) of this Rule. A Minor Release is an unauthorized release of a volume, greater than 5 barrels but not more than 25 barrels; or greater than 50 mcf but less than 500 mcf of natural gases. [3-15-97]

116.C. CONTENTS OF NOTIFICATION

- (1) Immediate verbal notification required pursuant to Paragraph B shall be reported within twenty-four (24) hours of discovery to the Division District Office for the area within which the release takes place. In addition, immediate verbal notification pursuant to Subparagraph B.(1).(d). shall be reported to the Division's Environmental Bureau Chief. This notification shall provide the information required on Division Form C-141. [5-22-73 . 2-1-96; A, 3-15-97]
- (2) Timely written notification is required to be reported pursuant to Paragraph B within fifteen (15) days to the Division District Office for the area within which the release takes place by completing and filing Division Form C-141. In addition, timely written notification required pursuant to Subparagraph B.(1).(d). shall also be reported to the Division's Environmental Bureau Chief within fifteen (15) days after the release is discovered. The written notification shall verify the prior verbal notification and provide any appropriate additions or corrections to the information contained in the prior verbal notification.

 [5-22-73...2-1-96; A, 3-15-97]
- 116.D. CORRECTIVE ACTION: The responsible person must complete Division approved corrective action for releases which endanger public health or the environment. Releases will be addressed in accordance with a remediation plan submitted to and approved by the Division or with an abatement plan submitted in accordance with Rule 19 (19 NMAC 15.A. 19). [3-15-97]