

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Grande Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR		☒ Initial Report ☐ Final Report
Name of Company: John H. Hendrix Corporation	Contact: Marvin Burrows	
Address: 1310 18 th Street, Eunice, New Mexico 88231	Telephone No.: (505) 394-2649	
Facility Name: Linda Federal Tank Battery	Facility Type: Production Tank Battery	
Surface Owner: Bob McCasland	Mineral Owner	Lease No.: NN23777

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Foot from the	North/South Line	Foot from the	East/West Line	County
K	23	20S	38E					Lea

Latitude: North 32° 33' 19.5" Longitude: West 103° 07' 15.4"

NATURE OF RELEASE

Type of Release: Crude Oil and Produced Water	Volume of Release: 1 bbl oil / 3 bbl water	Volume Recovered: 25 bbl oil / 1 bbl water
Source of Release: Transport tank overflow	Date and Hour of Occurrence: 11:00 hrs / 08/03/06	Date and Hour of Discovery: 13:00 hrs / 08/03/06
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Voice mail to Patricia Caperton	
By Whom? Marvin Burrows, Production Superintendent	Date and Hour: 08/03/06 / 14:45 hrs	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully. * N/A		
Describe Cause of Problem and Remedial Action Taken. * Transport truck driver failed to recognize level in tank causing overflow that was carried by wind over area measuring approximately 100 x 150 feet. Transport company (Vista Services) used shovel to contain free liquid and used a vacuum truck to pick up free liquid, which was taken to licensed commercial disposal facility.		
Describe Area Affected and Cleanup Action Taken. * Spill was generally confined to the tank battery location, except for about 10 feet on the west side that migrated into pasture of mesquite and grass. Cleanup actions will include scraping about 2 to 3 inches of soil from the affected area, collection of soil samples for laboratory analysis, backfilling area with clean soil (if necessary) and hauling contaminated soil to operator's permitted centralized surface waste management facility (refer to accompanying letter).		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Mark J. Larson		Approved by District Supervisor:
Title: Sr. Project Manager / President, Larson and Associates, Inc. (agent for John H. Hendrix Corporation)		Approval Date: Expiration Date:
E-mail Address: mark@lacenvironmental.com		Conditions of Approval: Attached ☐
Date: August 4, 2006 Phone: (432) 687-0901		

54'?

Facility - FPAC0627126732
Incident - nPAC0627126827
application - pPAC0627126956

RP# 1044