District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Robinse Soffication and Corrective Agnon-

OPERATOR Initial Report	
Name of Company: Chevron	Contact: Larry Williams
Address:	Telephone No.:
Facility Name: Lovington San Andres Unit #16 Facility Type: Injection well	
Surface Owner: State of New Mexico Mineral Owner: State of New Mexico API No.: 30-025-05360	
\$38 × 130 × 01 (\$4.1 \)	
Unit Letter Section Township Range 37E Feet from the Market Section 16S 37E	orth/South Line Feet from the East/West Line County Lea
Latitude: N 32° 52' 39.83" Longitude: W 103° 17' 19.47" NATHER DERELLASE.	
Type of Release: produced water	Volume of Release: 15 bbls Volume Recovered: 0 bbls
Source of Release: Injection well	Date and Hour of Occurrence: Date and Hour of Discovery:
Was Immediate Notice Given?	22 November 2005 in the a.m. 22 November 2005 @ a.m. If YES. To Whom?
Yes ☐ No ☐ Not Require	
By Whom?	Date and Hour: November 22, 2006 @ a.m.
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse:
☐ Yes ⊠ No	Not Applicable
If a Watercourse was Impacted, Describe Fully.* Not Applicable Depth to Groundwater: ~60 feet Describe Cause of Problem and Remedial Action Taken.* Approximately fifteen (15) barrels of produced water were released when a flow-line on an	
injection well failed. Zero (0) barrels of fluid were recovered. Upon discovery of the release, Chevron contacted EPI for an Emergency Response team. The Emergency Response team worked on the release area continuous from 11/2205 through 11/30/05 and from 37/206 through 3/9/06. Standing liquid was solidified and the impacted material transported to CRI for disposal. Laboratory analyses confirmed removal of impacted soil in sidewalls and bottom. The excavation was backfilled with caliche around the well head to rebuild the well pad. The remaining excavation was backfilled with topsoil, graded for natural drainage and will be seeded with a blend preferred by the land owner.	
Describe Area Affected and Cleanup Action Taken.* Approximately 21,500 equare feet of surface area was affected by the release.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
	OIL CONSERVATION DIVISION
Signature:	5634
Printed Name: Larry Williams	Approved by District Supervisor:
Title:	Approval Date: 3, 23 C7 Expiration Date:
E-mail Address: larry.williams@chevron.com	Conditions of Approval:
Date: Phone:	
Attach Additional Sheets If Necessary	

incident - n PAC 6708525321 application pPACO 708525546