District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003 ubmit 2 Copies to appropriate

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

1220 S. St. Franc	cis Dr., Santa	a re, NM 8/50:	•	S	anta Fe	, NM 875	05					side of form	
			Rele	ase Notific	cation	and Co	rrective A	ction	1				
						OPERA?	M		X Initi	al Report	П	Final Report	
Name of Company McClure Oil Company, Inc.						Contact Terry Pafford							
Address 50		Telephone No. 432-683-2787											
Facility Nan	ne Hobb	F	Facility Type Battery										
Surface Owner Occidental Permian Mineral Owner						Lease No. 030706							
	J.C.L.	dental re	-IIIII au			N OF RELEASE							
Unit Letter	Section	Township	Range			South Line Feet from the			East/West Line County				
	29	T18S	R38E	2000	Nor	rth	2600	West		Lea		1)	
			1301		1		2000	<u> </u>		1 Bea		40	
			Lat	titude		_ Longitud	e				a'	.0	
Latitude Longitude NATURE OF RELEASE													
Type of Relea		eak				Volume of Release 25 Volume Recovered 23							
Source of Release Heater Treater							Date and Hour of Occurrence ? Date and Hour of Discovery 11/23/06						
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? 4:00 PM						
41							Galy Willik						
By Whom? Terry Pafford Was a Watercourse Reached?							lour 11/24/ olume Impacting t		10:00 A	М		- 25	
Was a Water	ouise Roue		Yes 🖫] No		11 120, 10	Tunio Impubung			*	\$	15 6 E	
If a Watercou	irse was Im			L						<u></u>		30 1	
TI LI W LICHOUS	noo was an	puotou, Dosor	ico i uny.								35 C	ONE I	
										14 S	Q.®	40.00	
										(Park	•	(4)	
Describe Cause of Problem and Remedial Action Taken.* Leak occurred as a result of a hole in the fire tube on the heater treater. Wells were shutin.													
Leak occ	curred a	as a resu	ılt of	a hole in	the fi	re tube	on the hea	ter t	reater	. Wells	were	Shutin.	
Free sta	inding o	oil was p	oicked	up & put i	n stoc	k tank i	or treatin	g. Sp	oill wa	s contai	ned	within	
the dike	at the	e battery	7.										
Describe Are							······································	······································					
Only the	area v	vithin th	e dike	was affec	ted. A	rea will	be tilled	& di	irt mix	ed with	fert	ilizer	
to encou	ırage bi	Lo-remedi	ation.										
							knowledge and u						
T			-				nd perform corre				_		
							arked as "Final R on that pose a thr						
							e the operator of						
federal, state,	or local lav	ws and/or regi	ulations.										
						OIL CONSERVATION DIVISION							
Signature:	\mathcal{J}_{i}												
(VIII)						Approved by District Supervisor.							
Printed Name	: Te	rry Paff	ord	····									
Title:	En	gineer				Approval Dat	e: 5/29/07		Expiration	Date: 7	179	107	
		<u> </u>				-PP		<u>-</u>		17			
E-mail Addre	ss:				(Conditions of	Approval:			Attached	1 🗇		
Date:	12/14/	06	Phone	:432-683-2	787	BNAL F	REPORT BY	/					
A 44 T A T Y'-	• 101	. 7037				.,,,	Total Di		····				
100	N.L.	DOMA	1508	C (A)7					~	~ 1110	01		
. Auc		-> r 1000		DH1384									
Whi	down	2				V_{I}							
appli	satisface	-08/A	C071	0697 030764 503084	15								