

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <u>Fasken Oil and Ranch, Ltd.</u>	Contact <u>Jimmy D. Carlile</u>
Address <u>303 W. Wall, Ste 1800 Midland, TX</u>	Telephone No. <u>432 687-1777</u>
Facility Name <u>Cabot Q SWD</u>	Facility Type <u>Battery</u>

Surface Owner <u>State</u>	Mineral Owner <u>State</u>	Lease No.
----------------------------	----------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	7	15S	35E	1980	South	560	West	Lea

58' Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <u>produced water</u>	Volume of Release <u>70</u>	Volume Recovered <u>20</u>
Source of Release <u>battery - tank overflow</u>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Larry Johnson's voice mail</u>	<u>10/16/06 4 pm</u> <u>10/16/06</u>
By Whom? <u>Jimmy D. Carlile</u>	Date and Hour <u>10/17/06 9 am</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
Check valve on pump plugged causing system to back up and tank to overflow. Check valve was cleaned out and put back in service. Plans are to re-plumb piping to solve this problem from occurring again.

Describe Area Affected and Cleanup Action Taken.*
Firewall area 75' x 25' area filled and overflowed. Approximately 10 bbls ran on caliche 10' x 100' on pad site. Plans are to mix in 2 loads of chat into the pad to dilute any residual chlorides.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jimmy D. Carlile</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Jimmy D. Carlile</u>	Approved by District Supervisor: <u>[Signature]</u>	
Title: <u>Regulatory Affairs Coord.</u>	Approval Date: <u>10-31-06</u>	Expiration Date: <u>1-2-07</u>
E-mail Address: <u>jimmyc@forl.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>10/17/06</u> Phone: <u>432 687-1777</u>	<u>CONTAMINATION OUTSIDE OF FIREWALL REMOVED TO DISPOSAL. SAMPLES REQUIRED.</u>	

* Attach Additional Sheets If Necessary

Facility - PAC0715134770
Incident - PAC071534835
Application - PAC071534916

RP# ~~109~~
1376