


District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Mickey Garner
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name VGEU West Battery	Facility Type Oil and Gas
Surface Owner State of New Mexico	Mineral Owner State of New Mexico
	Lease No B-2354-2

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	31	17S	35E					Lea

Latitude **32.797282N** Longitude **-103.489113W**

NATURE OF RELEASE

Type of Release Crude Oil/Produced Water W/Chlorides = Unknown	Volume of Release 160 bbl (5 oil, 155 water)	Volume Recovered (4 oil, 126 water)
Source of Release SWD suction tank thief hatch.	Date and Hour of Occurrence 10/07/2006 0730hrs	Date and Hour of Discovery 10/07/2006 0830hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Patricia A. Caperton's voice mail	
By Whom? Kenneth N. Andersen	Date and Hour 10/09/2006 0700hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The leak was caused by the produced water transfer pump not operating causing the tank to over flow out the thief hatch. The level control switches have been recalibrated. A vacuum truck was called and 130 bbls of fluid were recovered.

Describe Area Affected and Cleanup Action Taken.* **36'X150' of dry caliche production battery pad & 51'X105" of dry black soil/caliche rock pasture with no cows present. The spill site was delineated and remediated in accordance with NMOCD guidelines. Impacted soil totaling 2,244 cubic yards was excavated and disposed of at Sundance's facility. Confirmation samples were taken and are attached. Chris Williams approved closure and the site was backfilled.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Mickey Garner		Approved by District Supervisor: <i>Chris Williams</i>	
Title: HSER Lead		Approval Date: 6/27/07	Expiration Date: 6/27/07
E-mail Address: Mickey.D.Garner@conocophillips.com		Conditions of Approval:	
Date: 06-21-07 Phone: 505.391.3158		Attached <input type="checkbox"/>	

• Attach Additional Sheets If Necessary

RP#1083



ARDINAL LABORATORIES

PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
BBC INTERNATIONAL, INC.
ATTN: CLIFF BRUNSON
P.O. BOX 805
HOBBS, NM 88241
FAX TO: (505) 397-0397


Receiving Date: 04/06/07
Reporting Date: 04/12/07
Project Owner: CONOCO PHILLIPS
Project Name: VACUUM GLORIETTA WEST T.B.
Project Location: BUCKEYE, NM

Sampling Date: 04/05/07
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: LB
Analyzed By: BC/HM

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/Kg)	DRO (>C ₁₀ -C ₂₈) (mg/Kg)	Cl* (mg/Kg)
ANALYSIS DATE		04/11/07	04/11/07	04/07/07
H12436-1	SP1 @ 2'	<10.0	<10.0	608
H12436-2	SP2 @ 2'	<10.0	60.1	880
H12436-3	SP3 @ 2'	<10.0	234	176
H12436-4	SP4 @ 2'	<10.0	63.4	592
H12436-5	SP5 @ 2'	<10.0	16.0	368
H12436-6	BKGND @ 0-6"	<10.0	25.4	<16
Quality Control		724	793	500
True Value QC		800	800	500
% Recovery		90.5	99.1	100
Relative Percent Difference		0.8	1.6	0.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl: Std. Methods 4500-ClB

*Analyses performed on 1:4 w:v aqueous extracts.


Chemist

4/12/07
Date

H12436A BBC

PLEASE NOTE **Liability and Damages** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E MARLAND • HOBBS, NM 88240


ANALYTICAL RESULTS FOR
 BBC INTERNATIONAL, INC.
 ATTN: CLIFF BRUNSON
 P.O. BOX 805
 HOBBS, NM 88241
 FAX TO: (505) 397-0397

Receiving Date: 04/06/07
 Reporting Date: 04/09/07
 Project Owner: CONOCO PHILLIPS
 Project Name: VACUUM GLORIETTA WEST T.B.
 Project Location: BUCKEYE, NM

Sampling Date: 04/05/07
 Sample Type: SOIL
 Sample Condition: COOL & INTACT
 Sample Received By: LB
 Analyzed By: BC

LAB NUMBER	SAMPLE ID	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)
ANALYSIS DATE		04/09/07	04/09/07	04/09/07	04/09/07
H12436-1	SP1 @ 2'	<0.005	<0.005	<0.005	<0.015
H12436-2	SP2 @ 2'	<0.005	<0.005	<0.005	<0.015
H12436-3	SP3 @ 2'	<0.005	<0.005	<0.005	<0.015
H12436-4	SP4 @ 2'	<0.005	<0.005	<0.005	<0.015
H12436-5	SP5 @ 2'	<0.005	<0.005	<0.005	<0.015
H12436-6	BKGND @ 0-6"	<0.005	<0.005	<0.005	<0.015
Quality Control		0.092	0.098	0.095	0.271
True Value QC		0.100	0.100	0.100	0.300
% Recovery		91.9	97.9	94.8	90.5
Relative Percent Difference		2.5	0.8	0.5	<0.1

METHOD: EPA SW-846 8260


 Chemist

4/9/07
 Date

PLEASE NOTE **Liability and Damages** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

