OIL CONSERVATION DIVISION

## Mobil Exploration & Producing U.S. Inc.

in and

October 17, 1990

190-06131923811293017

P.O. BOX 633 MIDLAND, TEXAS 79702

MIDLAND DIVISION

State of New Mexico - E&M Dept Attention: Mr. D. Catanach Oil Conservation Division State Land Office Building - P. O. Box 2088 Santa Fe, New Mexico 87501

2

DUAL BLINEBRY/TUBB GAS WELL UNORTHODOX WELL LOCATION E. O. CARSON WELL NO. 17 BLINEBRY & TUBB POOLS LEA COUNTY, NEW MEXICO

Mobil Exploration & Producing U.S. Inc. (MEPUS), as Agent for Mobil Producing Texas & New Mexico Inc., respectfully requests authority to perforate the Blinebry, and duly complete the subject well in the Blinebry & Tubb Pools at an unorthodox location.

This request is necessary, as required by the Blinebry/Tubb Gas Pool Field Rules, due to the well being less than 660 feet to any outer boundary of such tract.

The following items are being submitted, in triplicate, in support of this request:

- 1. Form C-101 Application for Permit to Drill, Deepen or Plug Back;
- 2. Form C-102 Well location and acreage dedication plat;
- 3. Map showing Offset Operators;
- 4. Copy of Certified letter to Offset Operators.
- 5. Copy of administrative order SD-84-2 dated 5-15-84.

A copy of this letter and attachments are being furnished to the Offset Operators by Certified Mail as notice of this application.

MEPUS requests that this unorthodox location be administratively approved.

Yours very truly, the

G. N. Miller Environmental, Regulatory & Loss Prevention Supervisor

Mobil Exploration & Producing U.S. Inc. as Agent for Mobil Producing Texas & New Mexico Inc.

JWD/fc Enclosure

cc: Oil Conservation Division - Hobbs
Offset Operators (w/Enc.)

## Mobil Exploration & Producing U.S. Inc.

October 17, 1990

P.O. BOX 633 MIDLAND, TEXAS 79702

MIDLAND DIVISION

State of New Mexico - E&M Dept Attention: Mr. D. Catanach Oil Conservation Division State Land Office Building - P. O. Box 2088 Santa Fe, New Mexico 87501

> DUAL BLINEBRY/TUBB GAS WELL UNORTHODOX WELL LOCATION E. O. CARSON WELL NO. 17 BLINEBRY & TUBB POOLS LEA COUNTY, NEW MEXICO

Mobil Exploration & Producing U.S. Inc. (MEPUS), as Agent for Mobil Producing Texas & New Mexico Inc., respectfully requests authority to perforate the Blinebry, and duly complete the subject well in the Blinebry & Tubb Pools at an unorthodox location.

This request is necessary, as required by the Blinebry/Tubb Gas Pool Field Rules, due to the well being less than 660 feet to any outer boundary of such tract.

The following items are being submitted, in triplicate, in support of this request:

- 1. Form C-101 Application for Permit to Drill, Deepen or Plug Back;
- 2. Form C-102 Well location and acreage dedication plat;
- 3. Map showing Offset Operators;
- 4. Copy of Certified letter to Offset Operators.
- 5. Copy of administrative order SD-84-2 dated 5-15-84.

A copy of this letter and attachments are being furnished to the Offset Operators by Certified Mail as notice of this application.

MEPUS requests that this unorthodox location be administratively approved.

Yours very truly, ll

G. N. Miller Environmental, Regulatory & Loss Prevention Supervisor

Mobil Exploration & Producing U.S. Inc. as Agent for Mobil Producing Texas & New Mexico Inc.

JWD/fc Enclosure

D. Werley - Prod Foreman - Buckeye

bcc: D. Elwood - Prod Engr

Central Files Regulatory Files

cc: Oil Conservation Division - Hobbs
Offset Operators (w/Enc.)

State Lease - 6 copies	Energ	y, Minerals and Natural R	esources Department			Form C-101 Revised 1-1-8	
Fee Lease - S'copies	OII	CONSERVATIO	<b>DN DIVISION</b>	ADI NO (-	reigned by OC	Don New Walle	
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088					API NO. (assigned by OCD on New Wells) 30-025-06871		
DISTRICT II	DISTRICT II Santa Fe, New Mexico 87504-2088						
P.O. Drawer DD, Artesia,	NM 88210	,					
DISTRICT III 1000 Rio Brazos Rd., Azt	ec, NM 87410	, · · ·		6. State Oi	il & Gas Lease	No.	
	TION FOR PERMIT	TO DRILL, DEEPEN, O	OR PLUG BACK				
1a. Type of Work: DRIL	l 🗌 re-enti		PLUG BACK	1	0. Cars	greement Name	
b. Type of Well:		SINGLE	MULTIPLE		U. Uars		
WELL WELL	X OTHER	ZONE	20NE XX		·		
2. Name of Operator Mobil Broducing		ito Agont Mobil Fur		8. Well No			
3. Address of Operator	1 A. Q. 11.M. INC., 17	nru its Agent Mobil Exp	JI. & PTOO. U.S. INC.	and a second sec	.17 me or Wildcat		
P.O. Box 633	Midland, Texas	79702			bry & Tu	bb Gas	
4. Well Location	===			1 /		West	
Unit Letter N	: <u>518.6</u> Feet	From The South	Line and 212	Fee	t From The		
Section	28 Tow	vnehip 21S Ra	age 37E	NMPM	Lea	· c	
		10. Proposed Depth		formation inebry δ	ጥ	12. Rotary or C.T	
13. Elevations (Show wheel	<u>/////////////////////////////////////</u>	14. Kind & Status Plug. Bond	15. Drilling Contractor			Rotary	
3451- Gr	•	On File	Unknown		ASAP		
17.	F	PROPOSED CASING AN	ND CEMENT PROGR	RAM			
	SIZE OF CASING	······································				507 TO	
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKSO	F CEMENT	<u>EST. IC</u>	
17-1/4	13-3/8"	48#	338'	300	FCEMENT	Circulated	
17-1/4 11" 7-7/8" This well is presen ual gas well in t	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test	48# 32# 17# of Tubb Gas Pool. Pe Pools.	338' 2900' 8143'	300 1500 950	· · · · · · · · · · · · · · · · · · ·	EST.TC Circulated Circulated 2325' complete as	
17-1/4 11" 7-7/8" his well is presen ual gas well in ti MIRU WO Unit. NI RIH w/RBP + tbg MIRU wireline u MIRU service co REI pkr, run do MIRU D-S and pr REI pkr, POOH w RIH w/bailer +	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to pre- wn over perfs, known epare to SWF Bline /pkr + workstring.	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs bock off RCBS. Reset p bbry. g to ± 5800'.	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% Di	300 1500 950 red to plug	g back and RD wireling	Circulated Circulated 2325' complete as	
17-1/4 11" 7-7/8" This well is presen Jual gas well in the MIRU WO Unit. NE RIH w/RBP + tbg MIRU wireline under MIRU service co REI pkr, run do MIRU D-S and provide MIRU D-S and provide	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to per . Prepare to brea wn over perfs, known epare to SWF Bline /pkr + workstring. workstring, CO csc ol + 189 jts 2-3/8 bry down sales lin level to ±5850'. C	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs bck off RCBS. Reset p bbry. g to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% Di kr @ ± 5350'. rate/ tbg press.	300 1500 950 ed to plug s, 36') R NEFE HCL	g back and RD wireling	Circulated Circulated 2325' complete as	
17-1/4 11" 7-7/8" This well is presen ual gas well in t MIRU WO Unit. N RIH w/RBP + tbg MIRU wireline u MIRU service co RE1 pkr, run do RE1 pkr, run do MIRU D-S and pr Re1 pkr, POOH w RIH w/bailer + RIH w/bailer + RIH w/on/off to 0. Flow test Bline 1. Swab tbg fluid	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to pren- Prepare to brea wn over perfs, known epare to SWF Bline /pkr + workstring. workstring, C0 csg ol + 189 jts 2-3/8 bry down sales lin level to ±5850'. C ry/Tubb on product	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs bck off RCBS. Reset p bbry. g to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% Di kr @ ± 5350'. rate/ tbg press.	300 1500 950 ed to plug s, 36') R NEFE HCL	g back and RD wireling	Circulated Circulated 2325' complete as	
17-1/4 11" 7-7/8" his well is presen ual gas well in the MIRU WO Unit. NU RIH w/RBP + tbg MIRU wireline us MIRU service co RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, POOH w RE1 pkr, POOH w RIH w/on/off to O. Flow test Bline Swab tbg fluid 2. Put dual Blineb Blowout Preventer P IN ABOVE SPACE DES	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to per Prepare to brea wn over perfs, kno epare to SWF Bline /pkr + workstring. workstring, C0 csg ol + 189 jts 2-3/8 bry down sales lir level to ±5850'. C ry/Tubb on product rogram attached: CRIBE PROPOSED PROC	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs bck off RCBS. Reset p bbry. g to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% DI kr @ ± 5350'. rate/ tbg press. se ratation, flow t	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireline + 100 1.1	Circulate Circulate 2325' complete as e unit. sp gr RCBS	
17-1/4 11" 7-7/8" his well is presen ual gas well in ti MIRU WO Unit. NI RIH w/RBP + tbg MIRU wireline u MIRU service co RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, POOH w RIH w/bailer + RIH w/on/off to 0. Flow test Bline 1. Swab tbg fluid 2. Put dual Blineb Blowout Preventer P IN ABOVE SPACE DES ZOME GIVE BLOWOUT PREV	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to pre- prepare to brea wn over perfs, know epare to SWF Bline /pkr + workstring, CO cso ol + 189 jts 2-3/8 bry down sales line level to ±5850'. Co ry/Tubb on product rogram attached: CRIBE PROPOSED PROC ENTER PROGRAM, F ANY.	48# 32# 17# of Tubb Gas Pool. Pe Pools. f Blinebry from 5450- k down Blinebry perfs bock off RCBS. Reset p bbry. to ± 5800'. " prod tbg. he, obtain stabilized open DHSOV w/1 clockwi ion.	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% DI kr @ ± 5350'. rate/ tbg press. se ratation, flow t	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireline + 100 1.1	Circulated Circulated 2325' complete as e unit. sp gr RCBS	
17-1/4 11" 7-7/8" his well is presen ual gas well in ti MIRU WO Unit. NI RIH w/RBP + tbg MIRU wireline u MIRU service co RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, POOH w RIH w/bailer + RIH w/on/off to 0. Flow test Bline 1. Swab tbg fluid 2. Put dual Blineb Blowout Preventer P IN ABOVE SPACE DES ZOME GIVE BLOWOUT PREV	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to pre- prepare to brea wn over perfs, know epare to SWF Bline /pkr + workstring, CO cso ol + 189 jts 2-3/8 bry down sales line level to ±5850'. Co ry/Tubb on product rogram attached: CRIBE PROPOSED PROC ENTER PROGRAM, F ANY.	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs ock off RCBS. Reset p bbry. to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi cion. GRAM: PPROFOSAL IS TO DEEPEN	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% DI kr @ ± 5350'. rate/ tbg press. se ratation, flow t NOR PLUG BACK, GIVE DATA OF belief.	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireling + 100 1.1	Circulated Circulated 2325' complete as e unit. sp gr RCBS	
17-1/4 11" 7-7/8" his well is presen ual gas well in ti MIRU WO Unit. NI RIH w/RBP + tbg MIRU wireline u MIRU service co RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, POOH w RIH w/bailer + RIH w/on/off to 0. Flow test Bline 1. Swab tbg fluid 2. Put dual Blineb Blowout Preventer P IN ABOVE SPACE DES ZOME GIVE BLOWOUT PREV	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to pre- prepare to brea wn over perfs, know epare to SWF Bline /pkr + workstring, CO cso ol + 189 jts 2-3/8 bry down sales line level to ±5850'. Co ry/Tubb on product rogram attached: CRIBE PROPOSED PROC ENTER PROGRAM, F ANY.	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs ock off RCBS. Reset p bbry. to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi cion. GRAM: PPROFOSAL IS TO DEEPEN	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% DI kr @ ± 5350'. rate/ tbg press. se ratation, flow t	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireling + 100 1.1	Circulated Circulated 2325' complete as e unit. sp gr RCBS	
17-1/4 11" 7-7/8" his well is presen ual gas well in ti MIRU WO Unit. NI RIH w/RBP + tbg MIRU wireline u MIRU service co REI pkr, run do REI pkr, run do REI pkr, run do REI pkr, POOH w RIH w/bailer + RIH w/on/off to 0. Flow test Bline 1. Swab tbg fluid 2. Put dual Blineb Blowout Preventer P IN ABOVE SPACE DES ZONE. GIVE BLOWOUT PREV I hereby certify that the inform	13-3/8" 8-5/8" 5-1/2" tly producing out he Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to pre- prepare to brea wn over perfs, know epare to SWF Bline /pkr + workstring, CO cso ol + 189 jts 2-3/8 bry down sales line level to ±5850'. Co ry/Tubb on product rogram attached: CRIBE PROPOSED PROC ENTER PROGRAM, F ANY.	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs ock off RCBS. Reset p bbry. to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi cion. GRAM: PPROFOSAL IS TO DEEPEN	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% DI kr @ ± 5350'. rate/ tbg press. se ratation, flow t NOR PLUG BACK, GIVE DATA OF belief.	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireline + 100 1.1	Circulated Circulated 2325' complete as e unit. sp gr RCBS D PROFOSED NEW PRO TE <u>10/12/90</u> (915)	
17-1/4 11" 7-7/8" his well is presen ual gas well in ti MIRU WO Unit. NI RIH w/RBP + tbg MIRU wireline u MIRU service co RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, POOH w RIH w/bailer + RIH w/on/off to 0. Flow test Bline 1. Swab tbg fluid 2. Put dual Blineb Blowout Preventer P IN ABOVE SPACE DES ZONE GIVE BLOWOUT PREV I hereby certify that the inform SKONATURE	13-3/8" 8-5/8" 5-1/2" tly producing out the Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to per Prepare to brea wn over perfs, kno epare to SWF Bline /pkr + workstring. workstring, CO csg ol + 189 jts 2-3/8 bry down sales lir level to ±5850'. C ry/Tubb on product rogram attached: CRIBE PROPOSED PROC ENTER PROGRAM, F ANY. mation above is true and comp	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs ock off RCBS. Reset p bbry. to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi cion. GRAM: PPROFOSAL IS TO DEEPEN	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% DI kr @ ± 5350'. rate/ tbg press. se ratation, flow t NOR PLUG BACK, GIVE DATA OF belief.	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireline + 100 1.1	Circulated Circulated 2325' complete as e unit. sp gr RCBS p PROPOSED NEW PRA The 10/12/90 (915)	
17-1/4 11" 7-7/8" his well is presen ual gas well in ti MIRU WO Unit. NI RIH w/RBP + tbg MIRU wireline u MIRU service co RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, POOH w RIH w/on/off to 0. Flow test Bline 1. Swab tbg fluid 2. Put dual Blineb Blowout Preventer P IN ABOVE SPACE DESS ZONE GIVE BLOWOUT PREV I hereby certify that the inform SKONATURE TYPE OR PRINT NAME	13-3/8" 8-5/8" 5-1/2" tly producing out the Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to per Prepare to brea wn over perfs, kno epare to SWF Bline /pkr + workstring. workstring, CO csg ol + 189 jts 2-3/8 bry down sales lir level to ±5850'. C ry/Tubb on product rogram attached: CRIBE PROPOSED PROC ENTER PROGRAM, F ANY. mation above is true and comp	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs ock off RCBS. Reset p bbry. to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi cion. GRAM: PPROFOSAL IS TO DEEPEN	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% DI kr @ ± 5350'. rate/ tbg press. se ratation, flow t NOR PLUG BACK, GIVE DATA OF belief.	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireline + 100 1.1	Circulated Circulated 2325' complete as e unit. sp gr RCBS p PROPOSED NEW PRA The 10/12/90 (915)	
17-1/4 11" 7-7/8" his well is presen ual gas well in ti MIRU WO Unit. NI RIH w/RBP + tbg MIRU wireline u MIRU service co RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, run do RE1 pkr, POOH w RIH w/on/off to 0. Flow test Bline 1. Swab tbg fluid 2. Put dual Blineb Blowout Preventer P IN ABOVE SPACE DESS ZONE GIVE BLOWOUT PREV I hereby certify that the inform SKONATURE TYPE OR PRINT NAME	13-3/8" 8-5/8" 5-1/2" tly producing out the Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to per Prepare to brea wn over perfs, kno epare to SWF Bline /pkr + workstring. workstring, CO csg ol + 189 jts 2-3/8 bry down sales lir level to ±5850'. C ry/Tubb on product rogram attached: CRIBE PROPOSED PROC ENTER PROGRAM, F ANY. mation above is true and comp	48# 32# 17# of Tubb Cas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs ock off RCBS. Reset p bbry. to ± 5800'. " prod tbg. he, obtain stabilized Open DHSOV w/1 clockwi cion. GRAM: PPROFOSAL IS TO DEEPEN	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% Dl kr @ ± 5350'. rate/ tbg press. se ratation, flow t NOR PLUG BACK, GIVE DATA OF belief. TE Regulatory Techr	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireline + 100 1.1	Circulated Circulated 2325' complete as e unit. sp gr RCBS p PROPOSED NEW PRA TE 10/12/90 (915) EPHONE NO. 688-	
17-1/4 11" 7-7/8" This well is presendual gas well in the MIRU WO Unit. NU RIH w/RBP + tbg MIRU wireline under MIRU wireline under MIRU service co REL pkr, run do REL pkr, run do NIRU D-S and pr REL pkr, POOH with RIH w/on/off to O. Flow test Bline Some test Bline NABOVE SPACE DES ZONE GIVE BLOWOUT PREV I hereby certify that the inform SKONATURE TYPE OR PRINT NAME	13-3/8" 8-5/8" 5-1/2" tly producing out the Blinebry & Tubb U BOP, Test , set RBP @ ±5850' t. Prepare to prent Prepare to breat wn over perfs, known epare to SWF Bline /pkr + workstring, CO csc ol + 189 jts 2-3/8 bry down sales lir level to ±5850'. CO ry/Tubb on product rogram attached: CRIBE PROPOSED PROP ENTER PROGRAM, F ANY. mation above is true and comp Sudy Dixon	48# 32# 17# of Tubb Gas Pool. Pe Pools. , cap w/10' sd. f Blinebry from 5450- k down Blinebry perfs bock off RCBS. Reset p bbry. g to ± 5800'. " prod tbg. he, obtain stabilized pen DHSOV w/1 clockwi ion. GRAM: IF PROFOSAL IS TO DEEPED where yo the bost of my knowledge and	338' 2900' 8143' rmission is request 5716 (total 72 hole w/4000 gals 15% Dl kr @ ± 5350'. rate/ tbg press. se ratation, flow t NOR PLUG BACK, GIVE DATA OF belief. TE Regulatory Techr	300 1500 950 ed to plug es, 36') R NEFE HCL	g back and RD wireline + 100 1.1 UCTIVE ZONE AN DAT TEL	Circulated Circulated 2325' complete as e unit. sp gr RCBS p PROPOSED NEW PRO TE 10/12/90 (915) EPHONE NO. 688-	

Submit to Appropriate District Office State Lease - 4 copies Fee Lease - 3 copies

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 State of New Mexico Energy, Minerals and Natural Resources Department T

## **OIL CONSERVATION DIVISION**


P.O. Box 2088


Santa Fe, New Mexico 87504-2088

## WELL LOCATION AND ACREAGE DEDICATION PLAT

All Distances must be from the outer boundaries of the section

entor obil Producing	g Tx. & N. M. Inc.	E .	0. Carson	<b>Well No.</b> . 17
it Letter Section	· · · · · · · · · · · · · · · · · · ·	Range		County
ual Footage Location of	28 21	.S 37E	NMP	Lea
	rom the South Producing Formation	line and 2121.4	fect from	n the West line Dedicated Acreage:
3451	Blinebry & Tubb		nebry & Tubb Gas	120 Acres
	reage dedicated to the subject we			120 Auto
2. If more than o	one lease is dedicated to the well,	outline each and identify the o	wnership thereof (both as to work	ting interest and royalty).
unitization, for	list the owners and tract descript	swer is "yes" type of consolid:	ltion	
No allowable wi				on, forced-pooling, or otherwise)
	T-21-S	R-37-E		OPERATOR CERTIFICATION I hereby certify that the information contained herein in true and complete to the best of my knowledge and built. Structure Judy Dixon Printed Name Environmental & Regulatory Position Mobil Producing Texas & New Mexico Company acting by and through its agent Mobil Exploration & Producing U.S Date SURVEYOR CERTIFICATION
₩ <sup>19</sup>	Acreage is Dec	licated		I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervison, and that the same is true and correct to the best of my knowledge and belief. Date Surveyed
¥ 2121:4'				Signature & Seal of Professional Surveyor Certificate No.





TD: 8143' PBTD: 6334' ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION

STATE OF NEW MEXICO



COVERNOR

POST OFFICE BOX 2088 STATE LAND OFFICE BUILDING SANTA FE, NEW MEXICO 87501 (505) 827-5800

May 15, 1984

Mobil Producing Texas & New Mexico Inc. Nine Greenway Plaza - Suite 2700 Houston, Texas 77046

Attention: J. A. Morris, Regulatory Engineering Supervisor

Administrative Order SD-84-2

Gentlemen:

You are hereby authorized to simultaneously dedicate a 120-acre non-standard proration unit comprising the W/2 SW/4 & SE/4 SW/4 of Section 28, Township 21 South, Range 37 East, NMPM, Lea County, to your E. O. Carson Lease Well No. 17 located at a point 518.6 feet from the south line and 2121.4 feet from the west line of Section 28 and your E. O. Carson Lease Well No. 19 located at 1980 feet from the south line and 760 feet from the west line of Section 28, both in Township 21 South, Range 37 East, NMPM, Blinebry and Tubb Gas Pools, Lea County, New Mexico.

Further, you are hereby permitted to produce the Blinebry and Tubb Gas Pools allowables from any of the wells on the proration unit in any proportion.

Done at Santa Fe, New Mexico, on this 8th day of March, 1984.

D. Ramey Øirector

cc: OCD District Office - Hobbs Oil & Gas Engineering Committee - Hobbs