

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa	
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126	
Facility Name SEMU Tubb Well # 104	Facility Type Oil Well	
Surface Owner BLM	Mineral Owner BLM	Lease No. LC 031670B

LOCATION OF RELEASE

Unit Letter K	Section 20	Township 20S	Range 38E	Feet from the 1980	North/South Line South	Feet from the 1650	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude N 32 33.174 Longitude W 103 10.470

API
30 025 26 268

NATURE OF RELEASE

Type of Release Hydrocarbons	Volume of Release 14 BBLs	Volume Recovered 3 BBLs
Source of Release Flowline	Date and Hour of Occurrence 10:40 am 1/25/08	Date and Hour of Discovery 11 am 1/25
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM and NMOCD	
By Whom? Jesse Sosa	Date and Hour 1/28/2008 1:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

FEB - 1 2008



Describe Cause of Problem and Remedial Action Taken.*

Flowline leak on the Semu #104. MSO immediately shut in and isolated leak The flowline was buried under 2 feet of sand. Flowline was dug out and had external corrosion. It was repaired with an emergency clamp. A vacuum truck was called out and 3 BO was picked up.

Describe Area Affected and Cleanup Action Taken.*

Affected area of 20 feet X 50 Feet was on pasture land. No livestock was present. Area will be remediated in accordance with NMOCD & BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	Approved by District Supervisor:  ENVIRONMENTAL ENGINEER	
Title: HSER Lead	Approval Date: 2.4.08	Expiration Date: —
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/28/2008	Phone: (505)391-3126	

* Attach Additional Sheets If Necessary

RP# 1772