

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUN 09 2009

HOBBSD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Chevron	Contact Ricky Heredia	
Address PO Drawer 29 Andrews Tx 79714	Telephone No. 432-523-3655 ex-7603	
Facility Name CC Fristoe AB FED NCT	Facility Type Water injection well	
Surface Owner	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter H	Section 35	Township 24S	Range 37 E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	---------------	-----------------	---------------	---------------	------------------	---------------	----------------	--------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ ADJACENT WELL FRISTOE B FED NCT  
30.025.34262.00.00

NATURE OF RELEASE

Type of Release Water release	Volume of Release 66.07 bbls water	Volume Recovered 60 bbls water
Source of Release 2" injection line	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD	
By Whom? Ricky Heredia	Date and Hour 5/20/2009 15:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Third Party finished for the day routinely rolled up new cable set in the control panel inadvertently turning off power to PLC. Without power to PLC the produce water tanks were not able to run therefore running the produce water tank over.

Describe Area Affected and Cleanup Action Taken.\*

Upon discovery mobilized one call brought in vacuum truck, restored power to pumps and pumped down brine tanks, recovered 60 bbls produce water. Called third party to begin the remediation of release site

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ricky Heredia	Approved by ENV ENGR District Supervisor: 	
Title: HES	Approval Date: 06/08/09	Expiration Date: 08/07/09
E-mail Address: rhrc@chevron.com	Conditions of Approval: DELINEATE TO CLEAN +1. SUBMIT FINAL ISY	Attached <input type="checkbox"/>
Date: 5/20/2009 Phone: 432-523-365 ext 7603		IRP-09.6.2198

\* Attach Additional Sheets If Necessary