

REC'D 8/18/09 002/002
VIA email mab

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-35512 Release Notification and Corrective Action

NMLB0929240146

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Range Resources Corporation 227 588	Contact: Steve Almager
Address: 100 Throckmorton St 1200	Telephone No. (575)394-1485
Facility Name: SCB Injection Facility SCB 23-019	Facility Type: Battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 23	Township 23 S	Range 28 E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude: 32.173350N Longitude: 104.033302W

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 300 bbls	Volume Recovered 290 bbls
Source of Release 2" Nipple Eroded Off Check Valve on the H-Pump	Date and Hour of Occurrence 8-15-09 10:45 Am	Date and Hour of Discovery 8-15-09 10:45 Am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD	
By Whom? Sergio Contreras, SESI	Date and Hour 8/17/09 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 2" nipple eroded off the end of the check valve on the H-Pump. The pump failed to shut off and resulted in water pumping into the lined tank battery and overflowing the firewalls.

Describe Area Affected and Cleanup Action Taken.*

SESI was contacted for assessment. Area will be delineated and an appropriate work plan submitted upon results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Steve Almager

Approved by:  District Supervisor

Title: Production Supervisor II

Approval Date: OCT 19 2009 Expiration Date:

E-mail Address: salmager@rangeresources.com

Conditions of Approval:

Attached ☐

Date: 8/18/09 Phone: (575) 394-1485

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: Remediation proposal

REC'D 10/12/09

2RP-350

NMLB0929240146