

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>Burnett O./Co 3080</i>	Contact <i>Bolton Matthews</i>
Address <i>Box 188 Loca Hills</i>	Telephone No. <i>575. 477. 2313</i>
Facility Name <i>Steam A #10</i>	Facility Type <i>PW</i>

Surface Owner <i>BLM</i>	Mineral Owner	Lease No.
--------------------------	---------------	-----------

30015 32793

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>L</i>	<i>13</i>	<i>17</i>	<i>30</i>					<i>Eddy</i>

Latitude *API 30.025.32793* Longitude *08-07-09*

NATURE OF RELEASE

Type of Release <i>Salt Water</i>	Volume of Release <i>app. 20 b1</i>	Volume Recovered <i>NONE</i>
Source of Release <i>line leak</i>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
line leak, repaired, water sealed on North edge of Steam 10 location

Describe Area Affected and Cleanup Action Taken.*
area 40x40, have been waiting to dry, before excavation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Eddie Sean</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Eddie Sean</i>	Approved by District Supervisor: <i>Eddie Sean</i>	
Title: <i>Agent</i>	Approval Date: <i>10-20-09</i>	Expiration Date: <i>12-31-09</i>
E-mail Address: <i>sean04@leaco.net</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>10/18/09</i> Phone: <i>390.2454</i>	<i>See approved work plan proposal.</i>	<i>2RP-360</i>

* Attach Additional Sheets If Necessary

*nSEB0930354750
iSEB0930355249
SEB0930355300*

RECEIVED
OCT 21 2009
NMOCD ARTESIA

BURNETT OIL CO.
STEVENS A #10
Section 13, T. 17 S., R. 30 E.

WORKPLAN

Prepared By
Eddie Seay Consulting
October 2009

October 16, 2009

NMOCD, Artesia
ATTN: Sherry Bonham
1301 W. Grand Ave.
Artesia, NM 88210

RE: Burnett Oil Co. Inc.
Stevens A #10
Sect. 13, Tws. 17 S., R. 30 E.

Mrs. Bonham:

Burnett Oil has retained my services to perform remedial work on the above listed spill and well area.

As the OCD requires, I have attached a work plan for your approval. Whenever we get approval, we will get the services of a contractor to excavate and haul as work plan suggests.

I appreciate your time on this project and look forward to hearing from you.

If you have any questions, please call.

Sincerely,

A handwritten signature in black ink that reads "Eddie W. Seay". The signature is written in a cursive style with a long, sweeping underline.

Eddie W. Seay, Agent
Eddie Seay Consulting
601 W. Illinois
Hobbs, NM 88242
(575)392-2236
seay04@leaco.net

cc: Burnett Oil (817)332-5108

WORK PLAN

General:

Leak occurred 8/09/09, injection line leak. BLM found leak, a C-141 is attached, also original analytical included.

Groundwater:

According to State Engineer and Groundwater information, the depth of water occurs at approximately 300 feet below surface.

Remediation Proposal:

All available fluids were picked up awaiting remediation. Area will be bladed and excavated, and soil hauled to an OCD approved facility and replaced with clean soil and seeded. Before backfilling, the area will be tested for Chloride to assure we meet OCD guidelines, and only after OCD and BLM approves, we will backfill and level.

The OCD and BLM will be notified of all activities and a report will be filed upon completion.

Ranking Criteria Score - 0

This site has a 5000 ppm TPH cleanup and will cleanup BTEX and Chloride per OCD.

Groundwater







