

RECEIVED OCT 29 2009
EMAIL

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-26891

Release Notification and Corrective Action

NMLB 0930940175

147179

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	575-391-1462
Facility Name	BCR Fed. #1	Facility Type	Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE API #30-015-31376

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	3	23S	28E	640	NORTH	330	EAST	EDDY

Latitude 32.34632 Longitude 104.06715

NATURE OF RELEASE API 30-015-26891

Type of Release	Produced water	Volume of Release	30 BBLS	Volume Recovered	10 BBLS
Source of Release	Flow line ruptured	Date and Hour of Occurrence	10/29/09 7:00 A.M.	Date and Hour of Discovery	10/29/09 90:00 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Cliff Brunson-BBC International, Inc.	Date and Hour	10/29/09 12:10 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A plastic flow line ruptured releasing produced water. Vacuum trucks were used to recover free fluid.

Describe Area Affected and Cleanup Action Taken.*

10 BBLS of fluid was recovered. Soil removal will be done and remedial actions and test results will be furnished with the final C-141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: BRADLEY BLEVINS	Approved by: 	
Title: EHS Specialist	Approval Date: NOV 05 2009	Expiration Date:
E-mail Address: bradley.blevins@chk.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/29/09	Phone: 575-391-1462	

* Attach Additional Sheets If Necessary

NMLB 0930940956

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION
PROPOSAL BY: 12/5/09

2RP-362

Bratcher, Mike, EMNRD

From: Cliff P. Brunson [cbrunson@bbcinternational.com]
Sent: Thursday, October 29, 2009 12:49 PM
To: Bratcher, Mike, EMNRD
Cc: Bradley Blevins; Ken Swinney; Jennifer Gilkey
Subject: Chesapeake BCR Fed. #1 - initial C-141
Attachments: Initial C-141.pdf

Mike,

On behalf of Chesapeake, I am reporting a spill on the BCR Fed. #1. I have attached an initial C-141 signed by Bradley Blevins. This occurred today, Oct. 29, 2009 at 7:00 a.m. I will be in contact with you to discuss this spill.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland Blvd.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397
E-mail: cbrunson@bbcinternational.com
Web: www.bbcinternational.com

Confidentiality Notice This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by collect telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.

Bratcher, Mike, EMNRD

From: Cliff P. Brunson [cbrunson@bbcinternational.com]
Sent: Thursday, October 29, 2009 1:15 PM
To: Bratcher, Mike, EMNRD
Cc: Bradley Blevins; Ken Swinney; Jennifer Gilkey
Subject: BCR Fed #1 - spill pictures
Attachments: 10-29-09_1055.jpg; 10-29-09_1051.jpg; 10-29-09_1048.jpg; 10-29-09_0956.jpg; 10-29-09_0957.jpg

Mike,

Here are the spill pictures from the camera phone of my project manager on site that I just sent an initial C-141 for. The quality is not the best, but I think you can see what has happened. Please get with me when you have reviewed these as we need to discuss this site.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland Blvd.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397
E-mail: cbrunson@bbcinternational.com
Web: www.bbcinternational.com

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by collect telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.

