

**Stogner, Michael**

---

**From:** Stogner, Michael  
**Sent:** Wednesday, January 21, 2004 10:03 AM  
**To:** 'JamesBruc@aol.com'; Williams, Chris  
**Subject:** RE: Nearburg/Minis 1 Fed. No. 3

I will proceed with our application based on this information. Before I finalize any administrative order I will need something from Nearburg that this location has in deed been verified with the Hobbs District Office. A well file paper trail follow-up in other words.

Thanks.

-----Original Message-----

**From:** JamesBruc@aol.com [mailto:JamesBruc@aol.com]  
**Sent:** Wednesday, January 21, 2004 6:59 AM  
**To:** mstogner@state.nm.us  
**Subject:** Nearburg/Minis 1 Fed. No. 3

Mike: I spoke with Nearburg, and they confirmed that the well is 4300 feet FSL §1. Please let me know if you need anything else.

Jim Bruce

**Stogner, Michael**

---

**From:** JamesBruc@aol.com  
**Sent:** Wednesday, January 21, 2004 6:59 AM  
**To:** mstogner@state.nm.us  
**Subject:** Nearburg/Minis 1 Fed. No. 3

Mike: I spoke with Nearburg, and they confirmed that the well is 4300 feet FSL §1. Please let me know if you need anything else.

Jim Bruce

**Stogner, Michael**

---

**From:** Williams, Chris  
**Sent:** Friday, January 16, 2004 8:27 AM  
**To:** Stogner, Michael  
**Subject:** RE: Nearburg's Minus "1" Federal Com. #3

For the well to be at 4300'FSL and 1310FWL the coordinates should be -103.63224 Lat by 32.51201 Long.

-----Original Message-----

**From:** Stogner, Michael  
**Sent:** Thursday, January 15, 2004 5:28 PM  
**To:** Jim Bruce (E-mail)  
**Cc:** Williams, Chris; Kautz, Paul  
**Subject:** Nearburg's Minus "1" Federal Com. #3

Please verify the actual surface location of this well (**30-025-33506**). Everything in your Delaware NSL application shows the well to be 4300' FSL. The well file indicates it to be 4300' on some forms and 3300' FSL on others. Division Order No. R-10607, issued in Case No. 11535 in 1996 approved this unorthodox location in the Morrow formation being 3300' FSL. Have Nearburg contact Hobbs OCD to verify and coordinate the findings. Thanks.

**Stogner, Michael**

---

**From:** JamesBruc@aol.com  
**Sent:** Thursday, January 15, 2004 5:29 PM  
**To:** MSTOGNER@state.nm.us  
**Subject:** Re: Nearburg's Minus "1" Federal Com. #3

Will do.

Jim Bruce

## Stogner, Michael

---

**From:** Stogner, Michael  
**Sent:** Thursday, January 15, 2004 5:28 PM  
**To:** Jim Bruce (E-mail)  
**Cc:** Williams, Chris; Kautz, Paul  
**Subject:** Nearburg's Minus "1" Federal Com. #3

Please verify the actual surface location of this well (30-025-33506). Everything in your Delaware NSL application shows the well to be 4300' FSL. The well file indicates it to be 4300' on some forms and 3300' FSL on others. Division Order No. R-10607, issued in Case No. 11535 in 1996 approved this unorthodox location in the Morrow formation being 3300' FSL. Have Nearburg contact Hobbs OCD to verify and coordinate the findings. Thanks.