

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2007

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company: Samson Resources Company	Contact: Autumn Long
Address: Two West Second Street	Telephone No.: (918) 591-1364
Facility Name: C. S. Caylor	Facility Type: CTB Produced Water Line
Surface Owner: State of New Mexico	Mineral Owner: Samson Resources Company
Lease No.: API #30-02505430	

LOCATION OF RELEASE

Unit Letter D	Section 5	Township 17S	Range 37E	Feet from the 660	North/South Line FNL	Feet from the 665	East/West Line FWL	County Lea
------------------	--------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude: 32.86899 N Longitude: -103.29661 W

WTR 80'

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 50 Barrels	Volume Recovered: 40 Barrels
Source of Release: Weld in Polyline	Date and Hour of Occurrence: 5/22/2010: Unknown	Date and Hour of Discovery: 05/22/2010: 10:00 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoff Leking	
By Whom? Floyd Steed - Production Foreman	Date and Hour: 05/22/2010 1:30 P.M. Central Time	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	
If a Watercourse was Impacted, Describe Fully. N/A		

Describe Cause of Problem and Remedial Action Taken.\*

A fused weld in the above ground 2" poly line came apart causing release of 50 barrels of produced water. Well was shut-in, M&S nucking called in and picked-up 40 barrels water from east side of lease road. Bant Roustabouts re-fused connection in the poly line where leak occurred. Further corrective actions are being identified.

Describe Area Affected and Cleanup Action Taken.\*

Area affected is approximately 131 yards along east side of lease road and approximately six (6) feet wide. All standing fluids were vacuumed-up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health, or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Autumn Long</i>	OIL CONSERVATION DIVISION	
Printed Name: Autumn Long	Approved by District Supervisor <i>[Signature]</i> ENVIRONMENTAL ENGINEER	
Title: Environmental Specialist	Approval Date: 6-8-10	Expiration Date: 8-9-10
E-mail Address: autumnl@samson.com	Conditions of Approval:	
Date: May 24, 2010 Phone: (918) 591-1364	SUBMIT FINAL C-141 w/DOCS BY 10-6-2553	
Attach Additional Sheets If Necessary		

1201 - LOST 6699  
APPS p LOST 7270

LARSON & ASSOC. TO REMEDIATE SITE