RECEIVED

NOV **2 2** 2010

Form C-141

Office in accordance

NMOCD ARTESIA Copies to appropriate

vised October 10, 2003

#### State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr.

with Rule 116 on back District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 side of form Santa Fe, NM 87505 Release Notification and Corrective Action <u>nMLB1032735832</u> **OPERATOR** Initial Report Final Report Name of Company OGRID Number Contact Yates Petroleum Corporation 25575 Amanda Trujillo Address Telephone No. 104 S. 4<sup>TH</sup> Street 575-748-1471 Facility Name API Number Facility Type Order Number Sosa Federal #2 30-015-26087 Oil well 2RP- 445 Surface Owner Mineral Owner Lease No. Federal Federal NM-44532 30-015-26247 LOCATION OF RELEASE East/West Line Unit Letter Section Township Range Feet from the North/South Line Feet from the County SOUTH East EDDY NATURE OF RELEASE Type of Release Volume of Release Volume Recovered OIL & WATER

Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery		
Flowline failure	11/16/2010	11/16/2010 AM		
Was Immediate Notice Given?	If YES, To Whom?			
☑ Yes ☐ No ☐ Not Required	Mike Bratcher – NMOCD/Artesia			
By Whom?	Date and Hour			
Amanda Trujillo – Yates Petroleum Corporation	11/16/2010 pm			
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.			
☐ Yes ⊠ No	N/A			
If a Watercourse was Impacted, Describe Fully.*				
N/A ·				
Describe Cause of Problem and Remedial Action Taken.*				
A plugged flowline pressured up and blew out.				
Describe Area Affected and Cleanup Action Taken.*				
An enpreyimete size of 150' v 1" was imported. The imported area is located on the south side if the location. Sail from the moding areas will be				

excavated and disposed of at an NMOCD approved facility. Vertical and horizontal relineation samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Chlorides analysis upon request Depth to Ground Water: >100' (approx. 100', per New Mexico Chevron Texaco Trend Map); Wellhead Protection Approx. No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Based on site

ground water quality and enclosed analytical result.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health

of the charletinent. In addition, furtoes acceptance of a C-141 report	does not reneve the operator of respon	sibility for cor	upitance with any other
federal, state, or local laws and/or regulations.			
1	OIL CONSERVATION DIVISION  Approved by Dishieren Byison 1/4 Brances		
Signature: A Luyillo			
Printed Name: Amanda Trujillo	Approved by Dishigrend Wiser	1/4 D)KM	aucon_
Title: Environmental Scientist	Approval Date: NOV 2 3 2010	Expiration D	atc:
E-mail Address: atrujillo@yatcspetroleum.com	Conditions of Approval:		Attached
Date: Friday, November 19, 2010 Phone: 575-748-4310	REMEDIATION per OCD	Rules and	

District 1

District III

1625 N. French Dr., Hobbs, NM 88240

1301 W. Grand Avenue, Artesia, NM 88210

1000 Rio Brazos Road, Aztec, NM 87410

\* Attach Additional Sheets If Necessary

\* Attach Additional Sheets If Necessary

Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: 12/23/2010

REMIEDIATION PER GUIDELINE

Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: 12/23/2010

REMIEDIATION PER GUIDELINE

Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: 12/23/2010

REMIEDIATION PER GUIDELINE

Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: 12/23/2010

REMIEDIATION PER GUIDELINE

Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: 12/23/2010

REMIEDIATION PER GUIDELINE

Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: 12/23/2010

REMIEDIATION PER GUIDELINE

GUIDELINE

FROPOSAL BY: 12/23/2010

REMIEDIATION PER GUIDELINE

FROPOSAL BY: 12/23/2010

REMIEDIATION PER GUIDELINE

GUIDELINE

FROPOSAL BY: 12/23/2010

REMIEDIATION

PROPOSAL BY: 12/23/2010

REMIEDIATION

GUIDELINE

GUIDELINE

FROPOSAL BY: 12/23/2010

REMIEDIATION

GUIDELINE

GUIDELINE

FROPOSAL BY: 12/23/2010

REMIEDIATION

FROPOSAL BY: 12/23/

### Bratcher, Mike, EMNRD

From:

Amanda Trujillo [atrujillo@yatespetroleum.com]

Sent:

Monday, November 22, 2010 3:46 PM

To: Subject: Bratcher, Mike, EMNRD FW: Sosa Federal #2

Attachments:

Sosa Federal 2 (11-16-2010 Inital).pdf

C-141 Attached

## Amanda N. Trujillo

Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537

Email atrujillo@yatespetroleum.com

----Original Message-----**From:** Amanda Trujillo

Sent: Wednesday, November 17, 2010 4:53 PM

To: Bratcher, Mike, EMNRD

Cc: Jerry Fanning

Subject: Sosa Federal #2

Mr. Mike Bratcher,

Yates Petroleum reports a release at the following location:

Sosa Federal #2

Sec. 15, Township 26 South, Range 29 East

**Eddy County** 

Date of Release: 11-16-2010

Approximately 3 barrels of Oil and 12 barrels of water were released; 0 barrels recovered

Cause of release has been isolated and repairs are in progress

Vacuum truck on site recovered standing fluids

Site will be evaluated and a work plan for remediation will be submitted for consideration

### Amanda N. Trujillo

Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

#### Bratcher, Mike, EMNRD

From:

Amanda Trujillo [atrujillo@yatespetroleum.com]

Sent:

Wednesday, November 17, 2010 4:53 PM

To:

Bratcher, Mike, EMNRD

Cc:

Jerry Fanning

Subject:

Sosa Federal #2

Mr. Mike Bratcher,

Yates Petroleum reports a release at the following location:

Sosa Federal #2

Sec. 15, Township 26 South, Range 29 East

**Eddy County** 

Date of Release: 11-16-2010

Approximately 3 barrels of Oil and 12 barrels of water were released; 0 barrels recovered

Cause of release has been isolated and repairs are in progress

Vacuum truck on site recovered standing fluids

Site will be evaluated and a work plan for remediation will be submitted for consideration

# Amanda N. Trujillo

Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com