

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-015-36560

AKM 1105-941469

**OPERATOR**

Initial Report  Final Report

Name of Company Devon Energy	6137	Contact <input type="checkbox"/> Ernie Duran
Address P. O. Box 250 Artesia, NM 88211		Telephone No. <input type="checkbox"/> 575-513-1768
Facility Name Cowpens 28 Fed #1		Facility Type <input type="checkbox"/> Gas Well

Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/>
---------------	---------------	------------------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	19S	31E	1650	South	1650	East	Eddy County, NM

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 140 BPW	Volume Recovered <input type="checkbox"/> 140 BPW
Source of Release Drain Line Connection	Date and Hour of Occurrence 2-9-11 8:00 AM	Date and Hour of Discovery 2-9-11 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left msg BLM Jim Amos	
By Whom? <input type="checkbox"/> Ernie Duran	Date and Hour <input type="checkbox"/> 2-10-11 10:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


**RECEIVED**  
FEB 23 2011  
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Drain line connection on the fiberglass water tank had frozen overnight and parted (pulled) away from the tank causing a 140 bbls spill.

Describe Area Affected and Cleanup Action Taken.\*  
The entire 140 bbl produced water spill was contained within the lined containment. All 140 bbls of produced water was recovered causing to environmental impact outside of the lined containment. Called vacuum truck to pick up water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ernie Duran	Signed By  Approved by <input type="checkbox"/> District Supervisor:	
Title: Asst. Production Foreman	Approval Date: 3/3/11	Expiration Date:
Date: 2-11-11 Phone: (575) 513-1768	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

4/3/11

2 RP 6015