District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

10-015-	26694	\hat{o}	Rele	ease Not	tificatio	on and C	orrective A	ction						
KMW 1	10194	7259				OPERA	al Report	П	Final Report					
Name of Co				OPERATOR Initial Report Final Report Contact Dennis Potter										
Address	13694 Lov	ington Hwy.	Telephone No. 505-206-7673											
Facility Nar	ne Turne	er B #104	Facility Type Producing well											
Surface Owner B.L.M. Mineral Owner										No. NMLCD 29395B 0001526696				
LOCATION OF RELEASE														
Unit Letter	ter Section Township Range Feet from the Nor			h/South Line Feet from the E			est Line FWL	County EDDY						
	<u> </u>		La	titude	Longitue	ie								
NATURE OF RELEASE														
Type of Rele						Recovered 7 BBLS								
Source of Release PRODUCING WELL						Date and Hour of Occurrence Date and H 9/17/10 3:00am 9/17/10 8				Hour of Discovery				
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom?							
By Whom? Dennis Potter							Date and Hour 9/17/10 9:00am							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.					The comment		
] No			-1	HE	:CE	IVED					
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.	*						Di	EC 2'	7 2010		
											NMOCD ARTESIA			
Describe Cause of Problem and Remedial Action Taken.* The flow line valve somehow was shut during the night causing the well to pressure up and blow out the stuffing box. Approx. 8 bbls. total fluid was released. I immediately called a vacuum truck to pick up fluids and a backhoe to pick up contaminated soil. Immediately flowing this I notified our office and called the BLM office.														
Describe Area Affected and Cleanup Action Taken.* affected area was the location and a small amount had run off the pad. The fluid was picked up and the contaminated soil was also picked up and placed onto some plastic. Talon LPE was called to come out to get soil samples and they were sent to cardinal labs. Further soil remediation will be determined after tests results are received.														
regulations al public health should their o	Il operators or the envir operations homent. In a	are required to comment. The ave failed to a ddition, NMC	o report as acceptane adequately OCD accep	nd/or file cer ce of a C-141 investigate	tain release I report by and remedi	notifications a the NMOCD n late contaminat	knowledge and und perform correct narked as "Final Rion that pose a three the operator of the correct of the co	ctive acti eport" de eat to gr	ons for rel oes not rel ound wate	eases which ieve the oper r, surface wa	may end rator of ater, hun	danger liability nan health		
Denning. Porth						OIL CONSERVATION DIVISION								
Signature: Approved by Distric® SuperivBsyr: M1/4 A								14 DE)KARULIR_					
Printed Name: Dennis J. Potter Title: Production Specialist / Asst. Production Foreman A							3/4/11			D-4				
E-mail Addre			oreman	Approval Date: 3/4// Expiration Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION				Attached						
							L NOT LATER T	THAN:	IUN	2 RF	2.5.	7/		