

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Targa Midstream Services, L.P.	Contact: Ralph England
Address: P.O. Box 1689, Lovington, NM 88260	Telephone No.: (575) 396-3221
Facility Name: Saunders Plant	Facility Type: Gas Processing

Surface Owner: Eidson Ranch	Mineral Owner	Lease No.
-----------------------------	---------------	-----------

LOCATION OF RELEASE

NEARBY MAUD SAUNDERS #004  
API #30-025-01195-00-00

Unit Letter I	Section 15 27	Township 16S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	------------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

SAUNDERS  
PLANT  
BREAK  
IN  
LINE

Latitude 32.89278 Longitude 103.44018

NATURE OF RELEASE

Type of Release: Gas release	Volume of Release: Unknown	Volume Recovered: 0
Source of Release: 8" steel pipeline	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery:
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Cause: Leaking 8" steel pipeline, external corrosion.

Remedial Action: Pipeline was temporarily repaired, isolated and taken out of service. Work is currently in progress to permanently repair pipeline by inserting 6" polyethylene pipe inside existing 8" steel pipeline. Permanent repair will be complete by 11/9/2010.

Describe Area Affected and Cleanup Action Taken.\*

Upon completion of pipeline repair, excavation will begin to clean leak site. Contaminated soil will be removed to an OCD approved landfarm, soil will be tested and new topsoil brought in to replace contaminated soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ralph England</i>		OIL CONSERVATION DIVISION	
Printed Name: Ralph England		Approved by: ENV ENGINEER: District Supervisor: <i>Jeffrey Leving</i>	
Title: Field Supervisor		Approval Date: 11/10/10	Expiration Date: 01/10/11
E-mail Address: REngland@targaresources.com		Conditions of Approval: SUBMIT FINAL	
Date: 11/8/2010 Phone: (575) 396-3221		Attached <input type="checkbox"/> C-141 BY 01/10/11. IRP-11-10-2648	

\* Attach Additional Sheets If Necessary