STATE OF NEW MEXICO

## ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION



March 4, 1987



POST OFFICE BOX 2086 STATE LAND OFFICE BUILDING SANTA FEINEW MEXICO 187501 (505) 827-5800

Tamarack Petroleum Company, Inc. 1485 One First City Center Midland, Texas 79701

Attn: Randy A. McClay

Re: Injection Pressure Increase

South Pearl Queen Unit Well Nos. 15 & 25, Lea County, New Mexico

Dear Sir:

Reference is made to your request of February 25, 1987 to increase the surface injection pressure on your South Pearl Queen Unit Well Nos. 15 & 25. This request is based on step rate tests conducted on the wells on February 23, 1987. The results of the tests have been reviewed by my staff and we feel an increase in injection pressure on these wells is justified at this time.

You are therefore authorized to increase your surface injection pressure on the following well(s):

Well & Location		Injection Pressure
South Pearl Queen Unit No. 15 660 FSL & 1980 FWL (Unit N) Section 4, T-20S, R-35E	13	310 PSIG
South Pearl Queen Unit No. 25 330 FNL & 660 FWL (Unit D) Section 9, T-20S, R-35E	15	500 PSIG

The Division Director may rescind this injection pressure increase if it becomes apparent that the injected water is not being confined to the injection zone or it is endangering any fresh water aquifers.

Sincerely,

William J. LeMay Director

## WJL/DRC/et

cc: Oil Conservation Division - Hobbs

File WFX - 546

D. McDonald

D. Catanach