

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 South First, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

WELL API NO. 30-025-32196
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Record
8. Well No. 4
9. Pool name or Wildcat Pearl-San Andres
10. Elevation (Show whether DR, RKB, RT, GR., etc.) 3,699' GR

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
 Amtex Energy, Inc.

3. Address of Operator
 P. O. Box 3418, Midland, Texas 79702

4. Well Location
 Unit Letter N : 760 feet from the South line and 2080 feet from the West line
 Section 26 Township 19S Range 35E NMPM County Lea

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

SEE ATTACHED PROCEDURE

BEFORE EXAMINER
 OIL CONSERVATION DIVISION
OCD EXHIBIT NO. 10
 CASE NO. 12758-A

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William J. Savage TITLE President DATE 10/26/01

Type or print name William J. Savage Telephone No. 915/686-0847
 (This space for State use)

APPROVED BY _____ TITLE ORIGINAL SIGNED BY PAUL F. KAUTZ DATE OCT 29 2001
 Conditions of approval, if any: PETROLEUM ENGINEER

see your attached procedure

57

MD

Amtex Energy Inc.
Record #4
Section 26, T19S, R35E
Lea County, New Mexico

Surface casing: 8-5/8" csg in 12 1/4" hole @ 378' w/ 270 sx, circulated
Production csg: 5-1/2" 7-7/8" hole @ 5,510' w/ 750 sx, circulated
Open perms: 4,842 - 4,854'
CIBP w/ 20' sand @ 5,020' on perforations 5,056 - 5,414'

1. Dig and line 200 bbl working pit. Flow well down as needed.
2. MIRU plugging equipment. NU BOP and RIH w/ workstring to PBTD @ +/- 5,000'.
3. RU cementer and displace casing w/ 100 bbls 9.5 #/gal plugging mud, pump 25 sx C cmt @ PBTD.
4. Pump 25 sx C cmt w/ 2% CaCl₂ @ 4,800'. WOC and tag this plug no deeper than 4,700'. *open perforation plug*
5. Pump 25 sx C cmt @ ~~2,500'~~^{3,200'} *estimated base of salt*
6. Pump 25 sx C cmt @ ~~1,200'~~ *estimated top of salt* *flusher 1760 bar of plug @ 1710*
7. Pump 25 sx C cmt @ ~~428'~~ *surface casing shoe* *385' 50' in / 50' out log*
8. Pump 10 sx 50' to surface.
9. RDMO.
10. Cut off wellhead and install dry hole marker. Empty and level pit, cut off anchors, back-drag location.

RECEIVED
Hobbs
020

OPERATOR: AMTEX ENERGY	NAME OF LEASE: RECORD	WELL: No. 4	PROSPECT: EAST PEARL
POOL: Pearl- San Andres	LOCATION: 2380' FWL X 760' FSL SECTION 26, T-19S, R-35E Lea county new Mexico		

