

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-11629
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name State 0
2. Name of Operator Bettis Boyle & Stovall	8. Well No. -1-
3. Address of Operator P O Box 1240, Graham, TX 76450	9. Pool name or Wildcat Langlie Mattix
4. Well Location Unit Letter A : 660 Feet From The N Line and 660 Feet From The E Line Section 16 Township 25S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3131 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>schematic attached</u> <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU PULLING UNIT.
- 2) RU WIRELINE & RIH W/ 4-1/2" CIBP SET @ +/- 3300' DUMP 2 SX CEMENT ON TOP.
- 3) PLACE 5 SX PLUG @ SURFACE
- 4) CUT OFF WELL CSG 4' BELOW GROUND LEVEL, WELD ON PLATE.
- 5) CLEAN UP LOCATION.

100' PLUG 1150 TO 1050

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim Ligon TITLE Regulatory Analyst DATE 4/17/97

TYPE OR PRINT NAME Kim Ligon TELEPHONE NO. 817-549-0780

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

BEFORE EXAMINER	
OIL CONSERVATION DIVISION	
TITLE <u>OCD</u>	EXHIBIT NO. <u>22</u>
CASE NO. <u>12758-A</u>	


APR 28 1997

TC

dp

BETTIS-Boyle: STUBALL
STATE 'O' #1


22-141 50 SHEETS
22-142 100 SHEETS
22-144 200 SHEETS



TOP cmt @ 1404

8" hole (7.20# set
@ 3030) cmt'd
w/ 100 SXS - TOP @ 1404

6 1/8" hole (4 1/2"
9.5#/FT set @ 3789
cmt'd w/ 125 SXS
TOP @ 3061



17" hole (12 3/4" - 40# @ 142')
cmt'd w/ 125 SXS to SURF.

cmt'd w/ Perf hole @ 1128'
w/ 175 SXS TO SURFACE

TOP OF 4 1/2" LINER @ 2800'
cmt @ 3061

3386 - 3639 PERFORATIONS

TD: 3789