## B. Bernard Lankford OGRID 1466 Spears State # 1 30-025-22098 UL F, Section 2, T26S, R37E

7" casing set at 304ft, Cmt circulated 4 ½" casing set at 3650ft, Cmt with 250 sx. TOC calculated at 1263ft Perfs 2661 –2931ft
Top of Anhy at 865ft

- 1. Move in plugging rig
- 2. NU BOP
- 3. Pull production equipment
- 4. Run and set CIBP at 2610ft
- 5. Run tbg to 2610ft
- 6. Displace well with gelled brine water
- 7. Spot 25 sx cmt
- 8. Pull tubing
- 9. Perf at 915ft
- 10. Run and set packer at 750ft
- 11. Squeeze with 25 sx cmt
- 12. Displace cmt to 815ft and WOC
- 13. Tag cmt plug
- 14. Perf at 350ft
- 15. Establish circulation 4 1/2"X 7" annulus
- 16. Cement to surface via 4 ½"casing with estimated 50 sx cmt
- 17. Cut off well head and install PA marker
- 18. Rig down move out SU
- 19. Remove any surface production equipment
- 20. Cut off SU anchors 1ft BGL and clean and level location