



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Wyoming State Office Reservoir Management Group
2987 Prospector Drive
Casper, Wyoming 82604-2968



In Reply Refer To:
3186
(3186.1)
Poker Lake Unit
NMNM71016X

JUN 29 2021

XTO Permian Operating, LLC
Attn: C.R. Salinas
Land Dept., Loc. 115 (W4.4A.288)
22777 Springwoods Village Parkway
Spring, TX 77389-1425

Re: Paying Well Determination
Poker Lake Unit 402H *case 366 R-153*
SHL: SE $\frac{1}{4}$ NE $\frac{1}{4}$, Sec. 33, T.24S., R.31E. (Lease No. NMNM030454)
BHL: NW $\frac{1}{4}$ NE $\frac{1}{4}$, Sec. 29, T.24S., R.31E. (Lease No. NMNM0506A)
Poker Lake Unit
Eddy County, New Mexico

Gentlemen:

We have determined that under existing conditions the Poker Lake Unit No. 402H well is **not** capable of producing unitized substances from the Delaware (Brushy Canyon) Formation in unit paying quantities. The well was completed in the Delaware Formation on July 26, 2016. Since the well was determined to be a nonpaying unit well, a communitization agreement should be submitted to the New Mexico State Office for approval.

If you have any questions, please call the undersigned at (307) 261-7685.

Sincerely,

/S/ J. David Chase

J. David Chase
Chief, Reservoir Management Group

cc: NMSO, Sheila Mallory
ONRR-RRM (email: leases.blm@onrr.gov)
New Mexico State Land Office, Scott Dawson
New Mexico Oil Conservation Division, Leonard Lowe