New Mexico oil Conservation Co. F. M.

T AKA: MR Michael Stagner

O POBOX 2088

SANTA FE NM 87501

SUBJECT

DATA MISSING From Exhibit 17-5, C.

DUGAN PRODUCTION CORP. P. O. BOX 208

P. O. BOX 208 FARMINGTON, N. M. 87401 (505) 325-1821

 the state of the s	×.
DATA MISSING From Exhibit 17-5, CASE 7966 9/28/83	
MESSAGE Affactuad for your file 15 2 copies of Page	
No. 6 of our daily dulling & Completion Report to	,
the Mother Lode #1. Sorry About Leaving it	
of the exhibit prickage.	
	1
John Roe	
- S [*]	The state of the s
copy Also Saf to Frank Chavez. DEGETIVIETT	No. of the control of
SEP 3 0 1983	The second secon
OIL CONSERVATION DIVISION SANTA FE	

SEND WHITE COPY RETAIN YELLOW COPY

7-11-83 Rig up Basin Perforators. Set retrievable bridge plug @ 7600'.

Pressure test to 4000 psi - okay. Dump sand on top of bridge plug.

Perforate Gallup formation as follows:

6765, 89, 6801, 08, 25, 36, 39, 47, 53, 61, 67, 73, 82, 84, 97, 6912, 14, 25, 27, 41, 53, 63, 70, 77, 89, 94, 7011, 19, 22, 27, 29, 38, 45, 54, 70. Total 35 holes.(0.34").

Attempt to break down perfs. Taking fluid @ 1800 psi @ 18 bbl./min.

Drop 52 RCN ball sealers. Ball off with 4000 psi. Run 4½" junk basket. Recovered 5 balls (4 hits).

Frac Gallup as follows:

15,000 gal. J-2 gel water + 25# Aqua seal/1000 - pad 20,000 gal. J-2 gel water + 15# Aqua seal/1000 + 1 ppg 20-40 sand 12,000 gal. J-2 gel water + 10# Aqua seal/1000 + $1\frac{1}{2}$ ppg 20-40 sand 12,000 gal. J-2 gel water + 10# Aqua seal/1000 + 2 ppg 20-40 sand 11,000 gal. J-2 gel water + 10# Aqua seal/1000 + $2\frac{1}{2}$ ppg 20-40 sand 4,404 gal. water flush ISDP - 800 psi 15 min. - 400 psi Maximum treating pressure - 3800 psi Minimum treating pressure - 2550 psi Average treating pressure - 2900 psi @ 50 bbl./min.

Totals:

89,500# - 20-40 sand; 70,000 gal.20#/1000 gal. J-2 gelled water; 70 gal. Aquaflow; 1135# Aqua seal; 70# B-5 breaker;

Left well shut in over night.

- 7-12-83 Open well up. Did not flow back. Went in hole with retrieving head. Tag sand @ 6875'. Clean out 180' sand to 7055'. Tag sand again @ 7500'. Clean out sand to bridge plug. Unseat bridge plug. P.O.H. Shut well in.
- Open well up on vacuum. G.I.H. with tubing. Tag sand ± 8000'. Clean to PBTD. Circulate clean. Land tubing as follows: 256 jts. 2-3/8" O.D., 4.7#, J-55, 8 Rd, EUE Tubing. T.E. 7994.17' set at 8002' RKB with seating nipple at 7969'. ND BOP. NU Wellhead. Shut in. Rig down Monument Service Unit.
- 7-14-83 Move in & Rig up Ponderosa Oil Field Service swabbing unit.
 Casing pressure 75 psi; tubing pressure 0. Made 32 swab runs.
 Swabbed an estimated 180 Bbls. of frac fluid. Fluid level at beginning of day 1500'. Fluid level at end of day 2200'. Show of gas and slight show of oil last 15 swab runs. Casing pressure 140 psi at end of day.

JEROME P. McHUGH Mother Lode #1 Page 6

7-11-83 Rig up Basin Perforators. Set retrievable bridge plug @ 7600'. Pressure test to 4000 psi - okay. Dump sand on top of bridge plug. Perforate Gallup formation as follows: $\frac{6765, 89, 6801, 08, 25, 36}{6912, 14, 25, 27, 41, 53, 63, 70, 77, 89, 94, 7011, 19, 22, 27, 29, 38, 45, 54, 70. Total 35 holes.(0.34"). Attempt to break down perfs. Taking fluid @ 1800 psi @ 18 bbl./min. Drop 52 RCN ball sealers. Ball off with 4000 psi. Run <math>4\frac{1}{2}$ " junk basket. Recovered 5 balls (4 hits).

Frac Gallup as follows:

15,000 gal. J-2 gel water + 25# Aqua seal/1000 - pad 20,000 gal. J-2 gel water + 15# Aqua seal/1000 + 1 ppg 20-40 sand 12,000 gal. J-2 gel water + 10# Aqua seal/1000 + $1\frac{1}{2}$ ppg 20-40 sand 12,000 gal. J-2 gel water + 10# Aqua seal/1000 + 2 ppg 20-40 sand 11,000 gal. J-2 gel water + 10# Aqua seal/1000 + $2\frac{1}{2}$ ppg 20-40 sand 4,404 gal. water flush ISDP - 800 psi 15 min. - 400 psi Maximum treating pressure - 3800 psi Minimum treating pressure - 2550 psi Average treating pressure - 2900 psi @ 50 bbl./min.

Totals:

70,000 gal.20#/1000 gal. J-2 gelled water; 70 gal. Aquaflow; 1135# Aqua seal; 70# B-5 breaker;

Left well shut in over night.

- 7-12-83 Open well up. Did not flow back. Went in hole with retrieving head. Tag sand @ 6875'. Clean out 180' sand to 7055'.

 Tag sand again @ 7500'. Clean out sand to bridge plug. Unseat bridge plug. P.O.H. Shut well in.
- 7-13-83 Open well up on vacuum. G.I.H. with tubing. Tag sand ± 8000'. Clean to PBTD. Circulate clean. Land tubing as follows: 256 jts. 2-3/8" O.D., 4.7#, J-55, 8 Rd, EUE Tubing. T.E. 7994.17' set at 8002' RKB with seating nipple at 7969'. ND BOP. NU Wellhead. Shut in. Rig down Monument Service Unit.
- 7-14-83 Move in & Rig up Ponderosa Oil Field Service swabbing unit.
 Casing pressure 75 psi; tubing pressure 0. Made 32 swab runs.
 Swabbed an estimated 180 Bbls. of frac fluid. Fluid level at beginning of day 1500'. Fluid level at end of day 2200'. Show of gas and slight show of oil last 15 swab runs. Casing pressure 140 psi at end of day.