

DRISPAC

0	HEALTH HAZARD	0	FLAMMABILITY	0	REACTIVITY
---	---------------	---	--------------	---	------------

[illegible]

1. The first step in the process of identifying a problem is to recognize that a problem exists. This involves gathering information about the situation and identifying the specific issue that needs to be addressed. Once the problem is identified, the next step is to define the problem clearly and concisely. This involves stating the problem in a way that is specific and measurable, and identifying the goals that need to be achieved to solve the problem. The third step in the process is to generate potential solutions. This involves brainstorming ideas and considering different approaches to solving the problem. The fourth step is to evaluate the potential solutions and select the best one. This involves comparing the solutions based on their feasibility, effectiveness, and cost. The final step in the process is to implement the selected solution and monitor its progress. This involves putting the solution into action and tracking its performance over time to ensure that it is effective and sustainable.

BEST-80
Printed in U.S.A.

BEST Sheet

IV FIRE AND EXPLOSION DATA

NO FIRE OR EXPLOSION HAZARD.

TREAT AS FLAMMABLE DUST IN THE FINELY DIVIDED AND SUSPENDED STATE

EXTINGUISHING MEDIA: WATER, CO₂, FOAM OR DRY CHEMICAL.

V HEALTH HAZARD INFORMATION

CARCINOGENICITY — NOT ON NTP, IARC OR OSHA LISTS

ACUTE ORAL LD ₅₀	16,000 mg/kg	ACUTE DERMAL LD ₅₀	ND	AQUATIC TOXICITY (LC ₅₀)	2700 ppm
-----------------------------	--------------	-------------------------------	----	--------------------------------------	----------

ROUTES OF EXPOSURE AND EFFECTS

NONTOXIC

NUISANCE DUST TLV = 10 mg/m³

EMERGENCY AND FIRST AID PROCEDURES

TREAT AS INERT OR NUISANCE PARTICLE.

TREAT DUST PARTICLES IN THE EYES BY RINSING WITH RUNNING WATER. NO EMERGENCY PROCEDURES ARE NECESSARY IN OTHER FORMS OF CONTACT.

BEST Sheet

VI REACTIVITY DATA

CONDITIONS CONTRIBUTING TO INSTABILITY

NONE

INCOMPATIBILITY

NONE

HAZARDOUS DECOMPOSITION PRODUCTS

NONE

CONDITIONS CONTRIBUTING TO HAZARDOUS POLYMERIZATION

WILL NOT OCCUR

VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED

SWEEP UP SPILLED MATERIAL AND DISPOSE BY DUMPING, INCINERATION. IN SOLUTION FLUSH WITH WATER TO SEWER OR WASTE TREATMENT FACILITY.

NEUTRALIZING CHEMICALS

NA

WASTE DISPOSAL METHOD

A NONBIODEGRADABLE MATERIAL.
DISPOSE OF IN DESIGNATED LAND FILL.

VIII INDUSTRIAL HYGIENE CONTROL MEASURES

VENTILATION REQUIREMENTS

GENERAL

SPECIFIC PERSONAL PROTECTIVE EQUIPMENT

RESPIRATORY

NIOSH APPROVED RESPIRATOR FOR NONTOXIC DUST

EYE

GOGGLES, FACESHIELD

GLOVES

GENERAL PURPOSE WORK GLOVES

OTHER CLOTHING AND EQUIPMENT

EYEWASH

BEST Sheet

IX SPECIAL PRECAUTIONS

PRECAUTIONARY STATEMENTS

NO PRECAUTIONARY LABELING.

OTHER HANDLING AND STORAGE REQUIREMENTS

TO PROTECT PRODUCT QUALITY STORE IN SEALED CONTAINERS IN A DRY, COOL PLACE, AWAY FROM SUNLIGHT.

DEPARTMENT OF TRANSPORTATION INFORMATION

PROPER SHIPPING NAME: NOT REGULATED

HAZARD CLASS: NOT HAZARDOUS

HAZARDOUS SUBSTANCE: NONE

LABEL: NONE REQUIRED

PREPARED BY **NL Barold**
ENVIRONMENTAL SERVICES

DATE
JULY, 1987