19.15.4.201 WELLS TO BE PROPERLY ABANDONED:

A. The operator of any of the following wells, whether cased or uncased, shall be responsible for the plugging thereof: wells drifled for oil or gas: or service wells including but not limited to seismic, core, exploration or injection wells.

B. A well shall be either properly plugged and abandoned or placed in approved temporary abandonment in accordance with these rules within 90 days after:

(1) a 60 day period following suspension of drilling operations;

(2) a determination that a well is no longer usable for beneficial purposes; or

(3) a period of one year in which a well has been continuously inactive.

[7-12-90...2-1-96; 19.15.4.201 NMAC - Rn, 19 NMAC 15.D.201, 12-14-01; A, 12/15/05]

Case 14055 De Novo C&D Management Company Iba Freedom Ventures Company OCD Exhibit No. 22