dugan production corp.

Application for Downhole Commingling Jerome P. McHugh - Native Son #2 Well <u>T-25-N, R-2-W, NMPM</u> Sec. 27: Unit N, 1020' FSL & 1670' FWL Rio Arriba County, New Mexico Case No. <u>8041</u>, Exhibit No. <u>5</u>

JEROME P: McHUGH Native Son #2 1020 FSL - 1670' FWL Sec. 27, T25N R2W NMPM Rio Arriba County, NM

## MORNING REPORT

10-9-83 230' W.O.C. Spudded 12-1/4" hole at 6:30 p.m. 10-8-83. Drilled to 230'. Rigged up and ran <u>5 jts. 9-5/8" O.D., 47#, 8 Rd, LT&C casing.</u> T.E. 212.18' <u>set at 224' RKB.</u> <u>Cemented with 135 sx class B</u> <u>plus 2% CaCl.</u> P.O.B. at 5:15 a.m. 10-9-83. Circulated good cement to surface. W.O.C.

- 10-10-83 1654' Drilling Wt. 8.9 Vis 29 W.L. 10.0 1° at 512'; 1<sup>1</sup>/<sub>2</sub>° at 790'; 1-3/4° at 1035'; 2° at 1256'; 2<sup>1</sup>/<sub>4</sub>° at 1550'
  - 1 hr. trip 12-1/4 hrs - drilling 1-3/4 hrs - survey 8-1/4 hrs - W.O.C. 3/4 hr. - drilling cement

Pressure tested surface casing and B.O.P. to 1000 psi for 30 min. Held OK.

10-11-83

3003' Drilling Wt. 8.8 Vis 27 W.L. 7.0 2-1/2° @ 1810' 2-3/4° @ 2026'; 3° @ 2235'; 3° @ 2450'; 3°@ 2708'; 2°@ 2963'

l-1/2 hrs - trip 19-1/2 hrs - drilling 1/2 hr - rig service 2-1/2 hrs - surveys

10-12-83 3698' - Drilling Wt. 9.0 Vis 38 W.L. 9.0 2° at 3078' 2° at 3213'; 1-3/4° at 3430'; 2° at 3651'

> 2-3/4 hrs - trip 18-1/4 hrs - drilling 1/2 hr - rig service 2 hrs - surveys 1/2 hr - wash 60' to bottom

709 BLOOMFIELD RD. • P.O. BOX 208 • FARMINGTON, NEW MEXICO 87499 • PHONE: 505-325-1821

Υ.

.

10-13-83	3976' - Drilling 2° at 389 <b>3'</b>	Wt. 9.0	Vis 45	W.L. 8	10% LCM
•	4-1/2 hrs - trip 8-1/4 hrs - drilling 1/2 hr - rig serv 1/4 hr - survey 7-1/2 hrs - pull 15 3 hrs - working trip.	vice stands, mi			
10-14-83	4364' - Drilling 3/4° at 4156'	Wt. 9.0	Vis 42	W.L. 8.0	Trace LCM
	3-3/4 hrs - trip 19-1/4 hrs - drillin 3/4 hr - rig sen 1/4 hr - survey	ו <b>g</b>	• .		
10-15-8 <b>3</b>	4890' - Drilling	Wt. 9.0	Vis 37	W.L. 12	l° at 4444'
•	3-1/2 hrs - trip 19-3/4 hrs - drilli 1/2 hr - rig se 1/4 hr - surve <b>y</b>	rvice		•	
10-16-83	5182' - Waiting on 20% LCM 1° at 49	Magnet .W 48'	lt. 8.7	Vis 42	W.L. 10.5
	2-1/2 hrs - trip 12-1/2 hrs - drilli 1/4 hr - rig se 3/4 hr - survey 1-3/4 hrs - W.O. m 6-1/4 hrs - lost c	n <b>g</b> rvice agnet	32 (lost 56	00 bbls.)	
10-17-83	5182' - Fishin <b>g</b>	Ŵt. 8.7	Vis 42	W.L. 10.5	20% LCM
•	16-1/4 hrs - trip 1 hr - W.O. m 1 hr - wash t 1-1/4 hrs - rig re 3-3/4 hrs - mixing 1/2 hr - trying 1/4 hr - rig se	agnet o bottom pair mud to unplug		lost 650 bl	ols. mud

( .

· (

· ·				
5225' - drilling Wt. 8.8	Vis 42	W.L. 14	14% L.C.M.	. •
17-1/4 hrs - trips 2-1/4 hrs - drilling 1/2 hrs - circ. and cond. 4 hrs - rig repair	mud			• •
5669' - Drilling Wt. 8.7 1½° at 5528'	Vis 45	W.L. 10	8% LCM	
16-1/2 hrs - drilling 1/4 hr - rig service 3/4 hr - rig repairs	•	 		
6191' - Drilling Wt. 8.8 1‡° at 6065'	Vis 48	W.L. 100	4% LCM	· · · · ·
22-3/4 hrs - drilling 3/4 hr - rig service 1/2 hr - survey	• .			·
6643' - Trip Wt. 9.0 Vi	s 45 W.I	L.11 5%	6 LCM	
mud 6556-6611)				1.
6-1/2 hrs - trip 15-3/4 hrs - drilling 3/4 hr - rig service	(Lost 400	bbls. mud at	5 686 <b>8')</b>	
7019' - Drilling Wt. 8.7	Vis 48	W.L. 7.0	30% LCM	
6-1/2 hrs - drilling 1/4 hr - rig service 13-1/2 hrs - mix mud & LCM - Lost 450 bbl. mu pumped mud in ho	d at 6981' le with no	• Pulled 10 returns. F	) stands an <mark>d</mark> Pulled 10 mor and mud i <b>n</b>	e Cont <b>.)</b>
	<pre>17-1/4 hrs - trips 2-1/4 hrs - drilling 1/2 hrs - circ. and cond. 4 hrs - rig repair 5669' - Drilling Wt. 8.7 1½° at 5528' 5-3/4 hrs - trip 16-1/2 hrs - drilling 1/4 hr - rig service 3/4 hr - rig repairs 3/4 hr - cut drilling line 6191' - Drilling Wt. 8.8 1½° at 6065' 22-3/4 hrs - drilling 3/4 hr - rig service 1/2 hr - survey 6643' - Trip Wt. 9.0 Vi 2 hrs - trip 19 hrs - drilling 3/4 hr - rig service 1/4 hr - survey 2 hrs - mix mud and LCM (10 mud 6556-6611) 6868' - mixing mud &amp; LCM W 6% LCM 6-1/2 hrs - trip 15-3/4 hrs - drilling 3/4 hr - rig service 1 hr - mix mud and LCM 7019' - Drilling Wt. 8.7 3-3/4 hrs - trip 6-1/2 hrs - trip 13-1/2 hrs - mix mud &amp; LCM - Lost 450 bb1. mu pumped mud in ho</pre>	<pre>17-1/4 hrs - trips 2-1/4 hrs - drilling 1/2 hrs - circ. and cond. mud 4 hrs rig repain 5669' - Drilling Wt. 8.7 Vis 45 1½° at 5528' 5-3/4 hrs - trip 16-1/2 hrs - drilling 1/4 hr - rig service 3/4 hr - rig repairs 3/4 hr - cut drilling line 6191' - Drilling Wt. 8.8 Vis 48 1Ű at 6065' 22-3/4 hrs - drilling 3/4 hr - rig service 1/2 hr - survey 6643' - Trip Wt. 9.0 Vis 45 W. 2 hrs - trip 19 hrs - drilling 3/4 hr - rig service 1/2 hr - survey 2 hrs - trip 19 hrs - drilling 3/4 hr - rig service 1/4 hr - survey 2 hrs - mix mud and LCM (Tost 200 bb1 mud 6556-6611) 6868' - mixing mud &amp; LCM Wt. 8.9 6% LCM 6-1/2 hrs - trip 15-3/4 hrs - drilling 3/4 hr - rig service 1 hr - mix mud and LCM (Lost 400 7019' - Drilling Wt. 8.7 Vis 48 3-3/4 hrs - trip 6-1/2 hrs - trip 13-1/2 hrs - mix mud &amp; LCM - filling h Lost 450 bb1. mud at 6981' pumped mud in hole with no</pre>	<pre>17-1/4 hrs - trips 2-1/4 hrs - drilling 1/2 hrs - circ. and cond. mud 4 hrs rig repair 5669' - Drilling Wt. 8.7 Vis 45 W.L. 10 14° at 5528' 5-3/4 hrs - trip 16-1/2 hrs - drilling 1/4 hr - rig service 3/4 hr - rig repairs 3/4 hr - rig repairs 3/4 hr - cut drilling line 6191' - Drilling Wt. 8.8 Vis 48 W.L. 100 14° at 6065' 22-3/4 hrs - drilling 3/4 hr - rig service 1/2 hr - survey 6643' - Trip Wt. 9.0 Vis 45 W.L. 11 5% 2 hrs - trip 19 hrs - drilling 3/4 hr - rig service 1/4 hr - survey 2 hrs - trip 19 hrs - drilling 3/4 hr - rig service 1/4 hr - survey 2 hrs - mix mud and LCM (lost 200 bb1. mud 6073-6 mud 6556-6611) 6868' - mixing mud &amp; LCM Wt. 8.9 Vis 48 W. 6% LCM 6-1/2 hrs - trip 15-3/4 hrs - drilling 3/4 hr - rig service 1 hr - mix mud and LCM (Lost 400 bb1s. mud at 7019' - Drilling Wt. 8.7 Vis 48 W.L. 7.0 3-3/4 hrs - trip 6-1/2 hrs - drilling 1/4 hr - rig service 13-1/2 hrs - mix mud &amp; LCM - filling hole and regat Lost 450 bb1. mud at 6981'. Pulled 10 pumped mud in hole with no returns. F</pre>	<pre>2-1/4 hrs - drilling 1/2 hrs - circ. and cond. mud 4 hrs rig repair 5669' - Drilling Wt. 8.7 Vis 45 W.L. 10 8% LCM 14° at 5528' 5-3/4 hrs - trip 16-1/2 hrs - drilling 1/4 hr - rig service 3/4 hr - rig repairs 3/4 hr - cut drilling line 6191' - Drilling Wt. 8.8 Vis 48 W.L. 100 4% LCM 14° at 6055' 22-3/4 hrs - drilling 3/4 hr - rig service 1/2 hr - survey 6643' - Trip Wt. 9.0 Vis 45 W.L. 11 5% LCM 2 hrs - trip 19 hrs - drilling 3/4 hr - rig service 1/4 hr - survey 66643' - mix mud and LCM (lost 200 bb1. mud 6073-6222 &amp; 125 bb mud 6556-6611) 6868' - mixing mud &amp; LCM Wt. 8.9 Vis 48 W.L. 10.0 6% LCM 6-1/2 hrs - trip 15-3/4 hrs - drilling 3/4 hr - rig service 1 hr - mix mud and LCM (Lost 400 bb1s. mud at 6868') 7019' - Drilling Wt. 8.7 Vis 48 W.L. 7.0 30% LCM 3-3/4 hrs - trip 6-1/2 hrs - trip 6-1/2 hrs - drilling 1/4 hr - rig service 13-1/2 hrs - mix mud &amp; LCM - filling hole and regaining circ. Lost 450 bb1. mud at 6981'. Pulled 10 stands and pumped mud in hole with no returns. Pulled 10 mor stands and hole unloaded. Flowed gas and mud in</pre>

.--

10-23-83 (cont.)		flow. Pu Regained attemptir	ulled pipe circulat ng to rega	e to 3399' ion. Pumpe	ed approx. 7 ation. Lost	nd pumped mud. 00 bbl. mud
10-24-83	7314' - Drill 2½° at 7175'	ing Wi	t. 8.7	Vis 42	W.L. 10.0	10% LCM
	23-1/4 hrs - 1/4 hr - 1/2 hr -	rig serv	ice .			
10-25-83	7335' - Mixir	ng mud	Wt. 8.7	Vix 44	Wt. 10	10-12% LCM
	11-3/4 hrs - 3-1/4 hrs - 1/2 hr '- 4 hrs - 4-1/2 hrs -	drilling rig serv rig repa	ice ir	eze.	•	
10-26-83	7335' - Mixin	ng mud	Wt. 8.8	Vis 50	W.L. 10	20% LCM
• • •	4-1/2 hrs - 1/2 hr - 13 hrs - 4-1/2 hrs - 1-1/2 hrs -	rig serv washing mixing m	bridges	· · · · ·		
10-27-83	7335' - 24 h Now triprin l at report ti	hole at 7	circulati 00 <b>0'</b> wash	on. Set o ing to bot	ne salt gel tom. Have f	plug at 3900' ull returns
10-28-8 <b>3</b>	7447' - Wash 3-1/4 hrs - 7-1/2 hrs - 3 hrs - 8 hrs - 2-1/4 hrs -	trip drilling wash to b mix mud	ottom	eze		
10-29-83	7740' - Dril 2° at 7685'	ling W	t. 8.9	Vis 45	W.L. 12.0	20% L.C.M.
•	1/4 hr - 21-1/4 hrs - 1/2 hr - 3/4 hr - 1-1/4 hrs -	drilling rig serv survey	ice	om		

ŗ

10-30-83 7882' - Trip Wt. 8.9 Vis 43 W.L. 11.0 18% LCM 7-1/2 hrs - trip ' 14 hrs - drilling 1 hr - rig service 3/4 hr - cut drilling line 3/4 hr - repair 10-31-83 8035' - Drilling W.L. 12.0 20% L.C.M. Wt. 8.9 Vis 45 7-3/4 hrs - trip 14 hrs - drilling 1 hr - rig service 1-1/4 hrs - wash to bottom 11-1-83 T.D. 8128' - Logging Wt. 9.0 Vis 60 W.L. 12 20% L.C.M. 112° at 8128' 5 hrs - trip ' 6-3/4 hrs - drilling 1/4 hr - rig service 2 hrs - circ. 2 hrs - change drilling line 8 hrs - logging T.D. 8128! - Running 41 casing 11-2-83 Finished running IES, CDL & CNL logs by Welex. T.I.H. with drill . pipe. Circ. bottoms up. Laid down drill pipe and rigged up to run 4½" casing. Now running 4½" casing. Ran 208 jts. 4<sup>1</sup>/<sub>2</sub>" OD, 11.6#, K-55, 8 Rd LT&C csg. T.E. 8154.28'-cemented - set @ 8133' RKB. <u>Cemented first stage</u> with 10 bbls. mud 11-3-83 flush followed by 400 sks 50-50 pos with 2% gel and 64# gilsonite per sk and ½# flocele per sack, followed by 150 sks class "B" neat with 1/4# flocele per sk. (Total cement slurry first stage - 737\_ cu. ft.) Good circulation throughout job. Maximum cementing pressure 800 psi. Reciprocated csg. OK while cementing. Bumped plug with 1500 psi. Float held OK. Dropped opening bomb. Opened stage tool at 5852'. Circulated with rig pump 2½ hrs. Rigged up HOWCO and cemented 2nd stage with 10 bbls. mud flush, followed by 210 sks 65-35 with 12% gel -  $6\frac{1}{4}$  gilsonite per sk. and  $\frac{1}{4}$ flocele per sk., followed by 310 sks 50-50 pos with 2% gel and. ¼# flocele per sk. (Total cement slurry 2nd stage - 885 cu. ft.)

flocele per sk., followed by 310 sks 50-50 pos with 2% gel and. ¼# flocele per sk. (Total cement slurry 2nd stage - 885 cu. ft.) Good circulation throughout job. Maximum cementing pressure 800 psi. Closed stage tool with 2500 psi. Held OK. Dropped opening bomb and opened stage tool at 3570'. Circulated with rig pump l½ hrs. Rigged up HOWCO and cemented 3rd stage with 10 bbls. mud flush, followed by 450 sks 65-35 plus 12% gel and ¼# flocele per sk, followed by 100 sks 50-50 pos with 2% gel and ¼# flocele per sack. (Total cement slurry 3rd stage - 1121 cu. ft.) Maximum cementing pressure 800 psi. Closed stage tool with 2500 psi. Held OK. Circulated

. •			
JEROME P. Native Son Page <b>6</b>			
11-3-83 (Cont.)	mud flush with tr. conta 11-2-83. Nippled down E and released rig at 5:00	OP. Set 4½" csq sl	b complete 3:00 P.M. ips. Cut off csg.
-	DAIL	Y REPORT	
11-4-83	Move in and rig up Pione Nipple up BOP. Set pump not show up.	er Well Service. N and pit. Shut wel	ipple down well head. 1 in. Tubing did
11-5-83	Unload tubing truck. Ru Tag up at 3570'. Drill Circulate clean. Drain	ing 10'_cement. Dri	lling D.V. tool.
11-6-83	Sunday – shut down		
11-7-83	GIH with tbg. Tag up @ Circulate clean. GIH wi to <sup>±</sup> 8019'. Circulate c casing to 4000 psi - OK. <u>HCL</u> . P.O.H. Rig up Bas correlation log. Panel	th tbg. Tag up 0 7 lean. Rig up Weste Spot 250 gallons in Perforators and	980'. Clean out LCM rn Co. Press test 4½" 7½% double inhibited attempt to record GR
11-8-83	Change out perforating <u>PBTD 8044'</u> to 7700', 750 3550 to 3300', 3050 to 2	0 to 7300', 7100 to	
	Perforate Lower Mancos	7326, 94; 7436, 66,	75, 78, 85 (7 holes),
	Perforate Dakota 7886, 8 75, 76, 77 (14 holes) Breakdown perfs with wat RCN ball sealers. Did n Ran 4½" junk basket. Re	er at 2100 psi. IS not ball off. Reach	DP 1300 psi. Drop 31 ed 3900 psi at 5 BPM.
	15,000 gal. Mini-Max	III-30 with 2% dies III-30 with 2% dies III-30 with 2% dies III-30 with 2% dies	
۰.	Max.treating press. 3 Ave. treating press. ISDP 2300 psi	3400 psi at 27 BPM	ating press. 3200 psi O psi

Totals: 60,000 gal. Mini-Max III-30, 67,500# 20-40 sand, 1200 gal. Aqua Flow, 55# B-5 breaker

Could not get 4½" retrievable bridge plug through upper D.V. tool. Shut down.

11-9-83

Opened well up. Flowing back water. GIH with casing scraper and bit. Ream out DV tools at 3570 and 5852'. POH. Rig up Basin Perforators. Set retrievable bridge plug at 7250'. Dump 1 sack of sand on top of bridge plug. Pressure test to 4000 psi. Held OK.

Perforate Mancos as follows: 6802, 16, 36, 44, 49, 53, 69, 71, 73, 75, 81, 98; 6900, 02, 04, 13, 27, 29, 31, 39, 41, 53, 65, 77, 83, 88, 91; 7023, 29, 33, 36, 39, 49, 53, 61, 66, 70, 73, 80, 87. (Total 40 holes, 6802-7087)

Start breakdown - est. rate 50 BPM at 3800 psi. Drop 60 RCN ball sealers. Ball off with 4000 psi. Ran 4½" junk basket. Retrieved 14 balls (9 hits).

Fraced Mancos as follows:

15,000 gal. gelled water pad with 25# Aqua Seal/1000 gal. 20,000 gal. gelled water with 15# Aqua Seal/1000 gal. + 1 ppg

20/40 sand

12,000 gal. gelled water with 10# Aqua Seal/1000 gal. + 1½ ppg 20/40 sand

12,000 gal. gelled water with 10# Aqua Seal/1000 gal. + 2 ppg 20/40 sand

11,000 gal. gelled water with 10# Aqua Seal/1000 gal. + 2½ ppg 20/40 sand

4,410 gal. gelled water flush

ISDP 400 psi Well went on vacuum in 3 min. Max treating press. 3650 psi. Min. treating press. 2900 psi. Ave. treating press 3100 psi at 58 BPM.

Totals: 70,000 gal. gelled water (20# J-2/1000 gal.), 89, 500 # 20/40 sand, 1200# Aqua Seal, 70 gal. Aqua Flow, 70# B-5 breaker, 1400# J-2 gel

## Shut well in for night.

11-10-83 Well on vaccum. T.I.H. with retrieving head to 5000'. Ran in with swab to check fluid level - 3000'. T.I.H. with tbg to 7028'. - Tag sand. Unable to establish circulation. P.O.H. Shut down.

11-11-83 GIH with retrieving head and Depek tubing bailer. Tag sand at 7028'. Clean out to bridge plug and latch onto bridge plug. P.O.H. Lay down bridge plug. G.I.H. with Depek tubing bailer. Tag sand at 7967'. Clean out to 7987'. Bailer quit working. P.O.H. Shut in for night.

11-12-83 Csg. 350 psi. Blew well down. Went in hole with tubing, seating nipple, tubing anchor. Land tubing as follows: 244 jts. 2-3/8" O.D., 4.7#, J-55, 8 Rd, EUE tubing. T.E. 7862.31' set at 7870' RKB with seating nipple at 7838' and tubing anchor at 6554' with 14000# tension. Nipple down BOP. Nipple up well head. Shut in. Rig down Pioneer Well Service.

11-13-83 Shut down.

11-14-83

Moved in and rigged up Basin Service swabbing unit. Casing pressure 515 psi. Tubing pressure 460 psi. Opened well. Did not unload. Swabbed 2-3/8" tubing. Fluid level first run 2800'. Made 18 swab runs. Swabbed estimated 150 bbls. frac water. No show of oil; good show of gas. Casing pressure at end of day 900 psi.


## 11-15-83 Casing pressure 975 psi. Tubing pressure 350 psi. Blew well down. Made 22 swab runs. Fluid level on first run 3200'. Swabbed estimated 175 bbls. frac fluid. Fluid level at end of day 4000'. Casing pressure 1450 psi. No show oil; slight show gas. S.D.O.N.

11-16-83 Casing pressure 1450 psi. Tubing pressure 450 psi. Well did not unload. Fluid level first run 3400'. Made 20 swab runs and swabbed estimated 160 bbls. frac fluid. Fluid level remained at 3400' all day. Very slight show oil last 5 runs of day. Casing pressure at end of day 1460 psi. Good gas show after 10 runs. S.D.O.N.

11-17-83 Casing pressure 1400 psi. Well did not unload. Made two swab runs to pit. Recovered <u>5 bbls. oil</u>. Fluid level at 3400' first run. Made 15 runs to pit. - all frac fluid - estimated 120 bbls. Well kicked off at 3:00 p.m. Flowed well to tank making undetermined amount of oil. Flowed 95 bbls. total fluid in 2 hrs. 15 min. (Will drain off water 11-18-83 a.m.) Casing pressure when well kicked off 1450 psi. After flowing through open 2" line 2 hrs. 15 minutes casing pressure 900 psi. Shut well in overnight.

11-18-83 Casing pressure 1050 psi. Tubing pressure 925 psi. Tank gauge after draining all water 2'1" (42 bbls.) Opened well to tank. Flowed for 40 min. and died. Casing pressure came up to 1400 psi. Made 7 swab runs (fluid level 1st swab run 2400'). Well kicked off and flowed 4 hrs. Drained all frac water from tank. Gauge after draining water 7'1" (142 bbls.). Swabbed and flowed 100 bbls. oil in 7 hrs. - undetermined amount of frac water and no estimate on gas. Shut well in at 4:00 p.m. 11-18-83. Will set production unit Monday 11-21-83 to get I.P. test. Casing pressure 925 psi when well closed in.

11-19-83 SICP 1375 psi. SITP 900 psi. Drained all water from tank - from 7'l" to 5'4" - total oil in tank 106 bbls.



JEROME P. McHUGH Native Son #2 Rio Arriba County, NM

- 1-4-84 Flowed well 2 hrs. thru casing. Made 47 bbl. oil and undetermined amount of water.
- 1-12-84 Flowed well 5½ hrs. thru casing. Made 170 bbls. oil, estimated 50 bbls. frac water and gas at the rate of 350 MCFPD, estimated.
- 1-20-84 Tubing pressure 1280 psi. Casing pressure 1430 psi. Tank #2 - 6". Opened up thru tubing. Would not unload. Opened up casing. Started unloading fluid in 30 min. with 590 psi on casing.

	Casing	Tank Gauge	0il Production
30 min.	605 psi	1' 5"	<pre>18 bbls. 18 bbls. 41 bbls. 43 bbls. 42 bbls. 39 bbls. 37 bbls.</pre>
1 hr.	565 psi	2' 3½"	
2 hrs.	525 psi	4' 4"	
3 hrs.	475 psi	6' 6"	
4 hrs.	425 psi	8' 7½"	
5 hrs.	400 psi	10' 7"	
6 hrs.	375 psi	12' 5"	

238 bbls. total oil

Pitot tube at 4th hr. - 3 psi. Separator started to dump water after flowing 4 hrs. Shut well in at 4:00 p.m. 1-20-84. Gas gauge by Pitot tube was 1200 MCFGPD at end of 4 hrs. with 425 psi flowing casing pressure and 150 psi on production unit. No estimate of water production. JEROME P. McHUGH Native Son #2 Page 2 - Testing

1-25-84 Tubing pressure 260 psi; casing pressure 1415 psi. Tank #1 - 1'5" Tank #2 - 1'11" Flowing casing on at 11:55 a.m.

30 min.	Casing 650 psi	Tank #2 -	2' 8"
1 hr.	795 psi		3' 0"
2 hrs.	745 psi		3' 10"
3 hrs.	655 psi		4'7"
4 hrs.	600 psi		5' 5½"
Final	600 psi		5'7"

Left well flowing overnight.

Gauges at 7:00 a.m. 1-26-84: Tank #1 6' 0" and Tank #2 14' 0" Well flowed 333 bbls. oil in 19 hrs. with 460 psi casing pressure after 19 hrs. flowing on  $\frac{1}{4}$ " choke. Undetermined amount of water and gas production.