or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2'' RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire 10- Submit Subsequent work 11- Prepare to put well on pro- Attach: current wellbord 1 hereby certify that the information ab grade tank has been/will be constructed or the	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipmed over report of C-103 to Oil Conservation Division.	d salt water . ocation. mp in the well. 600 psig. sand. casing string from 8900-surf. casing string to 500 psi ent from well bore. and report results. BEFORE THE OIL CONSERVATION DIVISI Santa Fe, New Mexico Case No. 14189 Exhibit No. Submitted by: <u>Americo Energy Resources, LLC</u> Hearing Date: October 30, 2008 r an (att: $(yc \leftarrow DATE 10-2-co)$).
or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2" RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire 10- Submit Subsequent work 11- Prepare to put well on pro- Attach: current wellbord 11- Prepare to put well on pro- Attach: current wellbord SIGNATURE	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. as & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipmed over report of C-103 to Oil Conservation Division. oduction via electric sub pump. Put well on production e diag.	d salt water . ocation. mp in the well. 600 psig. sand. casing string from 8900-surf. casing string to 500 psi ent from well bore. and report results. BEFORE THE OIL CONSERVATION DIVISI Santa Fe, New Mexico Case No. 14189 Exhibit No. Submitted by: <u>Americo Energy Resources, LLC</u> Hearing Date: October 30, 2008 r an (att: $(yc \leftarrow DATE 10-2-co)$).
or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2'' RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire 10- Submit Subsequent work 11- Prepare to put well on pro- Attach: current wellbord 1 hereby certify that the information ab grade tank has been/will be constructed or the	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up . set Squeeze tools at 11770' . Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipmed over report of C-103 to Oil Conservation Division. boluction via electric sub pump. Put well on production e diag.	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand. casing string from 8900-surf. casing string to 500 psi ent from well bore. and report results. BEFORE THE OIL CONSERVATION DIVISI Santa Fe, New Mexico Case No. 14189 Exhibit No. Submitted by: <u>Americo Energy Resources, LLC</u> Hearing Date: <u>October 30, 2008</u>
or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2'' RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire 10- Submit Subsequent work 11- Prepare to put well on pro- Attach: current wellbord 1 hereby certify that the information ab grade tank has been/will be constructed or the	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up . set Squeeze tools at 11770' . Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipmed over report of C-103 to Oil Conservation Division. boluction via electric sub pump. Put well on production e diag.	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand. casing string from 8900-surf. casing string to 500 psi ent from well bore. and report results. BEFORE THE OIL CONSERVATION DIVISI Santa Fe, New Mexico Case No. 14189 Exhibit No. Submitted by: <u>Americo Energy Resources, LLC</u> Hearing Date: <u>October 30, 2008</u>
or recompletion. INFORM OIL CONSERVATION I- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2'' RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire 10- Submit Subsequent work 11- Prepare to put well on pro-	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipmed over report of C-103 to Oil Conservation Division.	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand. casing string from 8900-surf. casing string to 500 psi ent from well bore. and report results. BEFORE THE OIL CONSERVATION DIVISI Santa Fe, New Mexico Case No. 14189 Exhibit No. A Submitted by:
or recompletion. INFORM OIL CONSERVATION I- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2'' RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire 10- Submit Subsequent work 11- Prepare to put well on pro-	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipmed over report of C-103 to Oil Conservation Division.	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand. casing string from 8900-surf. casing string to 500 psi ent from well bore. and report results. BEFORE THE OIL CONSERVATION DIVISI Santa Fe, New Mexico
or recompletion. INFORM OIL CONSERVATION I- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2'' RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire 10- Submit Subsequent work 11- Prepare to put well on pro-	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipmed over report of C-103 to Oil Conservation Division.	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand. casing string from 8900-surf. casing string to 500 psi ent from well bore. and report results.
or recompletion. INFORM OIL CONSERVATION I- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2" RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire 10- Submit Subsequent work	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipmed over report of C-103 to Oil Conservation Division.	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand. casing string from 8900-surf. casing string to 500 psi ent from well bore.
or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2" RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a 9- If testing casing string is For 30 minutes or as dire	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag set 4-1/2" liner 600 psi from 11770'.8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing. satisfactory. Inform OCD 24 hrs ahead- Final test the cted by OCD agent. Pull and lay down testing equipment	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand. casing string from 8900-surf. casing string to 500 psi
or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2" RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te 8- Prepare to Squeeze off a	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'-8900', and test 7" c ny leak/leaks in the 4-1/2" and/or 7" casing.	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand. casing string from 8900-surf.
or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2" RBP and 5- Set RBP at 11800'. Relea 6- If Bridge plug held OK, of 7- Move up w/packer and te	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag est 4-1/2" liner 600 psi from 11770'-8900', and test 7" c	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand.
or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2" RBP and 5- Set RBP at 11800'. Relead 6- If Bridge plug held OK, of 3	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string. ase & Pick up. set Squeeze tools at 11770'. Test plug dump 200 lb of 20/40 sand on top of Bridge plug. Tag	d salt water . ocation. <u>mp in the well</u> . 600 psig. sand.
or recompletion. INFORM OIL CONSERVATION 1- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N 4- GIH with 4-1/2" RBP and	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on lo /d & N/u- Pooh with production equipment and sub pur d Squeeze packer on tapered string.	d salt water . ocation. mp in the well.
or recompletion. INFORM OIL CONSERVATION I- Move in and rig up work 2- Unload & tally 8900' of 3 3- Kill well if necessary. N	N DIVITION over rig. Spot & rig up reverse unit, fill tank with field 2-7/8" and 2915' of 2-3/8" EUE 8RD, N80 tubing on 10 /d & N/u- Pooh with production equipment and sub put	d salt water . ocation.
or recompletion. INFORM OIL CONSERVATION I- Move in and rig up work	N DIVITION over rig. Spot & rig up reverse unit , fill tank with field	d salt water .
or recompletion.	N DIVITION	
or recompletion.		ch wendore diagram of proposed completion
	,	ich wendore diagram of proposed completion
At crowting any proposed work	G. SEE RUEE 1105. FULWINDIE COMDIEUONS' ANA	
	ted operations. (Clearly state all pertinent details, and g s). SEE RULE 1103. For Multiple Completions: Atta	
OTHER:	OTHER:	
PULL OR ALTER CASING	MULTIPLE COMPL	JOB []
	CHANGE PLANS COMMENCE DRILL MULTIPLE COMPL CASING/CEMENT	
PERFORM REMEDIAL WORK 🛛	PLUG AND ABANDON	ALTERING CASING
NOTICE OF INT	ENTION TO: SUBS	EQUENT REPORT OF:
12. Check Ap	opropriate Box to Indicate Nature of Notice, R	Report or Other Data
Pit Liner Thickness: mil		struction Material
	erDistance from nearest fresh water wellDistan	
Pit or Below-grade Tank Application or		
	3798.65' GL	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Unit Letter N : 9 Section 2	990feet from theSouthline and2310_ Township 15S Range 37E	feet from theWestline ✓ NMPM County Lea
4. Well Location	100 feat from the South line and 2010	fact from the Wast Har
7575 San Felipe, Suite 200, Houston	, TX 77063	Denton (Devonian) 🗸
3. Address of Operator		10. Pool name or Wildcat
2. Name of Operator Americo Energy Resources, LLC		9. OGRID Number
	las well [] Ouler - Ingention well	
PROPOSALS)	TION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number #7
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	State T
01505	F	7. Lease Name or Unit Agreement Name
District IV 1220 S. S. Financis Diff. Solution M	Sama rc, inivi 07303	6. State Oil & Gas Lease No.
	1220 South St. Francis Dr.	STATE S FEE BLM
1000 Rio Brazos Rd , Aztec, NM 87410	R OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1301 W. Grand Avc, Aftesta, 01382200 District III 1000 Rio Brazos Rd , Aztec, NM 87410		30-025-05232
1625 N. French B. L. Lisaber N. A. 88240 District 11 1301 W. Grand Ave Artes a. 5/1382200 District 111 1000 Rio Brazos Rd , Aztec, NM 87410		WELL API NO. /
District II 1301 W. Grand Ave, Aftesta, 01382200 District III 1000 Rio Brazos Rd, Aztec, NM 87410		Form C-103 May 27, 2004 WELL API NO.

Denton State T #7 API # 30-025-05232

GL.,3798.65' KB., 3807.65'

DF

TOC at **250'** By Temp log.

D&C 2/28/1953 Measurements 9' above GL.

Base USDW @

Location: 990' FSL & 2310' FWL of Section 2, T-15 S, R-37 E Lea County , New Mexico.

CBL/VDL run on 3/13/1979 No Cement above approx.3000' perf. At 2970' w/4 holes & sqeezed w/ 720 sx.cement.WOC 16 hours, Ran temp.survey log, indicated the top of cement to be at 250', below surface.(between 7"& 9-5/8" Cement did not circulate to surface

3/22/2003,&

3/24/2003 : Merit Energy: RIH w/ 4-1/2" Packer & Plug, set RBP at 9105' & Plug at 9100' Test Plug to 1000 psig. OK Note, RBP & Plug was below top of 4-1/2" Liner which is at 8985' Top of liner was good at 1000 psig. Released Packer. Pumped 50 Bbls. water into tubing at injection rate of 2.5 bbls at 200 psig.

のないである

3/31/2003: R/U B J & Pumped 100 sxs. On top of Liner squeezed at 1600 psig. pressure dropped 50 # in 5 minutes. Repress. to 1600 # and held for15 minutes No bleed off Moved packer to 8140' & set. Pressred up to 500 # and left shut-in.till

4/2/03: Continued operation on 4/4/2003 Tagged cement at 8715'.cleaned to top of liner at 8989' & inside 4-1/2" Liner, 7' of cement inside Liner. Pressure tested 7 0" & 4-1/2' liner to 500 psig. 4/5/2003.Final page Report by Merit energy

4/27/2003: R/U Computa Log. Logged from 9100' to 7100' Log indicated no cement on top of the 4-1/2". Have cement behind 7.0" Casing

TD 12418'

Shut- in since 2003 after unsuccessful workover.

Not Producting at this time (4/3/2006) TOC @ 250' below surface. After Squeeze job. 9-5/8" casing @ 2110' in 17-1/2" hole. w/ 1300 sxs. Cement circulated liquid level above pump at 6311' some 2640' above pump. 3/11/1979: To repair 7.0" casing. 5 SQZD HOLES AT 2970' Details of the pump are not known. ESP pump set at 8951' Top of liner 4-1/2" at 8985' Old wolfcamp Perfs. 9064- to 9124' Squuzed off. 7" casing set at 9232' Cement used 600 sxs,Top ? 0 - 69' 26# S-95 69' - 715' 23 # N-80 715' - 4996' 23 # J-55 4996' - 7099' 23 # S-95 7099' - 9232' 26 # S-95 DV Tool ran & set at 7002' cemented with 400 sxs. Top of cement behind 4-1/2" unknown. Perfs @ 11955' - 12034', 21 holes (B zone) or 11993'- 12034' ? By DevonEnergy,(10/16/98) 11/17/1974: Devonian, Perforated,& Acidized. Perfs @ 12216'-12275', 8 holes(D zone perfs) RBP stuck at 12308' ? 11/17/1974: Devonian, Perforated,& Acidized. Perfs @ 12333' -12366', 6 holes,(D Zones perfs) PI, 257 BOPD , 46.4 API gravity oil Flowing Tbg Pressure 2,750 psig 4 1/2" Liner set @ 12418', w/ 375 sxs.Cmnt. 8985' - 9152' 11.5 # K-55, 9152' - 12418' 15 5 # N-80

<u>AmeriCo</u>

Energy Resources, LLC

October 28, 2008

To: Working Interest Owners

Re:

Notice of Proposed Operations State T No. 007 990 FSL & 2310 FWL Sec, 2 Township 15 South, Range 37 East Denton Field, Lea County, NM

Gentlemen:

Americo Energy Resources, LLC, as Operator, hereby respectfully submits the attached AFE for operations to be conducted on the referenced well. The <u>estimated</u> cost for the AFE is \$348,462.

Also attached is a well diagram of the proposed operation for your review and consideration.

Please review and sign below indicating your approval of this AFE, and then return one executed copy of this notice. Also in accordance with the existing JOA we are requesting that you include a check for your portion of the AFE with this approval letter. Since this type of operation is considered regulatory work, your prompt attention to this matter is greatly appreciated.

Please contact me if you have any questions or require further information. Since $rel \chi$

Oscar Norrati Vice President of Operations

Approved by. _____

Company Name:_____

By;_____

Title:_____

	Prenared h	v :	Oscar Noer	ati	nati	EISSUED		TOCIOSE	PAGE	
AUTHORIZA	Prepared by: Oscar Nosrati DATE ISSUED HORIZATION FOR EXPENDITURE - WELLS 10/						DATE AFE TO CLOSE PAGE 8/2008 1			
AFE NO.	TYPE	AFE NAME	State	T well #7			OPERATOR Americo Energy			
COMPANY DIVISION							DIVISION / SUB			
DISTRICT /	Americo E ORG	nergy		DISTRICT /		COUNTRY				
L	NEW MEXICO FIELD						U.S.A.			
STATE	Texas COUNTY OR PARISH					TAX DISTRICT				
NEW MEXICO STATE FIELD OR AREA PRIMARY RESERVOIR					SECONDARY RESERVOIR					
DENTON FIELD										
DENTON FIL	ELD, NEW MI	EXICO			ASSOCIAT	ED AFE	AFE CLASS COST PROPERTY			
PROJECT D	ESCRIPTION	MECHANIC	AL INTEGRITY	TEST TO BR	ING THE WE		ENCE AS REC	UIRED	L	
BY STATE O	OF NEW MEX	ICO "OCD".								
DATE TO ST	DATE TO C	OMPLETE	WELL NO.	PLAY	PROJ	CT DAYS	PROJ.GROU	Est Depth TD	Est Depth TVD	
	}						Ĺ			
						ENVIRO	NMENTAL CO	ST		
								CASED & COMPLETE		
							DRY HOLE	D	TOTAL	
041 479777	14/4 0000			s						
SALARIES & PAYROLL BI		ipervisor 12 da	ys@ 1400/day			+				
LOCATION F	REPARATIO	N & RECLAMA	TION			1				
CEMENT & C		SERVICE						25,000	25,000	
MUD LOGGI		ICALS, COMPL	ETION FLUID	S. & MUD EN	GINEERING					
		EVALUATION				1			·	
PERFORATI	NC					<u></u>	<u>Concern</u>	4 500		
		NT - GRAVEL I	PACKING, FRA	ACS, ETC.		+	100000	4,500	4,500	
		TESTING SE								
DIRECTIONA		& MWD b DSA, Elev. B		2 20212 000				45.000	45.000	
DRILLING CO			IT & SURAFER	COPS-RDP				15,000	15,000	
COMPLETIO	N RIG DAY R									
		12 days at \$	5000 a day		TOTAL			60,000	60,000	
FLOAT EQUI	PMENT & CE	MENTING AID	s		10176					
BITS,& SCRA										
ABOR SUDE		5 \$ \$1400 a day						16,800	16,800	
		3 DOWN-CON	TRACT					10,000	10,000	
UEL, WATE										
Reverse unit, pump and tank.								25,000	25,000	
Acid treatment										
ISHING SER		OCIATED EQU	DMENT					30,000	30,000	
SOLIDS CON	TROL & MOO	JOINTED EQU								
TESTING TU	BING IN THE	HOLE						3,000	3,000	
	VIRE LINE TK-run guage ring, set CIBP, dump 25' cmt mp trk load casing w/ pkr fluid & run T/A test for OCD									
mp trk load d	asing w/ pkr		OTAL INTANO	BLES		·		4,500	4,500	
	한 수 1 2 3	974 B 4 3	51	در الح	-ta 1		· · · · ·			
CASING	FT.	IN.	LB.	GR.		T				
Drive Pipe	<u> </u>		L8.	GR.	@\$	{}ł				
Conductor	·									
Surface ntermediate									0	
LINER 1						<u>├</u>			0	
LINER 2									0	
Production TUBING										
, oping										
ASINGHEAD	>									
MAS TREE	PETC							3,000	3,000	
	AND EQUIP.	-ESP equip				<u>├</u>	0000000	100,000	100,000	
TOTAL TANGIBLES							0	103,000	103,000	
TOTAL WELL COST 100.0000%								286,800	286,800	
RODUCTION EQUIPMENT (Detail Attached) 100.0000% THER COSTS - NET (Detail Attached) 100.0000%									0	
			Tax	006.50				18,642	18,642	
			Contingency	015.00				43,020	43,020	
O OWNERSH			Oscar Nosra	COMPANY (COST	I		348,462	348,462	
roject Recon	mnended by									
	COMPANY NAME: Americo Energy									

1

. . .

Denton State T #7 API # 30-025-05232

GL.,3798.65' KB., 3807.65'

DF

TOC at 250' By Temp.log.

D&C 2/28/1953 Measurements 9' above GL.

Base USDW @

Location: 990' FSL & 2310' FWL of Section 2, T-15 S, R-37 E Lea County, New Mexico.

CBL/VDL run on 3/13/1979 No Cement above approx.3000' perf. At 2970' w/4 holes & sqeezed w/ 720 sx.cement.WOC 16 hours, Ran temp.survey log, indicated the top of cement to be at 250', below surface.(between 7"& 9-5/8" Cement did not circulate to surface

3/22/2003,&

3/24/2003 : Merit Energy: RIH w/ 4-1/2" Packer & Plug, set RBP at 9105' & Plug at 9100' Test Plug to 1000 psig. OK. Note, RBP & Plug was bellow top of 4-1/2" Liner which is at 8985' Top of liner was good at 1000 psig. Released Packer. Pumped 50 Bbls. water into tubing at injection rate of 2.5 bbls at 200 psig.

3/31/2003: R/U B.J & Pumped 100 sxs. On top of Liner squeezed at 1600 psig. pressure dropped 50 # in 5 minutes. Repress. to 1600 # and held for15 minutes. No bleed off. Moved packer to 8140' & set. Pressred up to 500 # and left shut-in till

4/2/03: Continued operation on 4/4/2003 Tagged cement at 8715' cleaned to top of liner at 8989' & inside 4-1/2" Liner, 7' of cement inside Liner. Pressure tested 7.0" & 4-1/2' liner to 500 psig. 4/5/2003. Final page Report by Merit energy.

4/27/2003: R/U Computa Log. Logged from 9100' to 7100'. Log indicated no cement on top of the 4-1/2". Have cement behind 7.0" Casing.

TD 12418'

G. Bayat 4/2/2006

H. Dashti

Drilled in 1953 as a Wolfcamp Producer. Then deepened in Aug. 1974 4/2/2006 Wolfcamp TD 9231, PBTD 9226'. Perfs. 9064'- 9124'. These Perfs. Squeezed off before deepening. In 2003 Merit Energy Co. attempted a casing leak repair, after squeeze job, both 4-1/2" & 7.0" Pressure tested to 500 psig. Ok.

シージェムにようたかから

いたであ

Shut- in since 2003 after unsuccessful workover.

Not Producting at this time.(4/3/2006)

TOC @ 250' below surface. After Squeeze job.

9-5/8" casing @ 2110' in 17-1/2" hole. w/ 1300 sxs. Cement circulated

liquid level above pump at 6311' some 2640' above pump. 3/11/1979: To repair 7.0" casing. 5 SQZD HOLES AT 2970'

Details of the pump are not known.

ESP pump set at 8951'

Top of liner 4-1/2" at 8985'

Old wolfcamp Perfs. 9064- to 9124' Squuzed off.

7" casing set at 9232' Cement used 600 sxs,Top ? 0 - 69' 26# S-95 69' - 715' 23 # N-80 715' - 4996' 23 # J-55 4996' - 7099' 23 # S-95 7099' - 9232' 26 # S-95

DV Tool ran & set at 7002' cemented with 400 sxs.

Top of cement behind 4-1/2" unknown.

Perfs @ 11955' - 12034', 21 holes (B zone) or 11993'- 12034' ? By DevonEnergy,(10/16/98)

11/17/1974: Devonian, Perforated,& Acidized. Perfs @ 12216'-12275', 8 holes(D zone perfs)

RBP stuck at 12308' ?

11/17/1974: Devonian, Perforated,& Acidized. Perfs @ 12333' -12366', 6 holes,(D Zones perfs) PI, 257 BOPD, 46.4 API gravity oil. Flowing Tbg.Pressure 2,750 psig

4 1/2" Liner set @ 12418', w/ 375 sxs.Cmnt. 8985' - 9152' 11.5 # K-55, 9152' - 12418' 15.5 # N-80