

**EXHIBIT "A"**  
**CASE NO. 12333**  
**ORDER NO. R-11334**

**103     SIGN ON WELLS**

All wells and related facilities regulated by the Division shall be identified by a sign, which sign shall remain in place until the well is plugged and abandoned and the related facilities are closed. For drilling wells, the sign shall be posted on the derrick or not more than 20 feet from the well. The sign shall be of durable construction and the lettering shall be legible and large enough to be read under normal conditions at a distance of 50 feet. The wells on each lease or property shall be numbered in non-repetitive, logical and distinctive sequence. An operator will have 90 days from the effective date of an operator name change to change the operator name on the well sign unless an extension of time, for good cause shown along with a schedule for making the changes, is granted. Each sign shall show the:

1.    number of well;
  2.    name of property;
  3.    name of operator;
  4.    location by footage, quarter-quarter section, township and range (or Unit Letter can be substituted for the quarter-quarter section); and
  5.    API number.
- 

**202     PLUGGING AND PERMANENT ABANDONMENT**

**202.B. PLUGGING**

(2)    The operator shall mark the exact location of plugged and abandoned wells with a steel marker not less than four inches (4") in diameter set in cement and extending at least four feet (4') above mean ground level. The operator name, lease name and well number and location, including unit letter, section, township and range, shall be welded, stamped or otherwise permanently engraved into the metal of the marker. No permanent structures preventing access to the wellhead shall be built over a plugged and abandoned well without written approval of the OCD. No plugged and abandonment marker shall be removed without the written permission of the OCD.

(5)    Below-ground plugged and abandonment markers can be used only with written permission of the OCD when an above-ground marker would interfere with agricultural endeavors. The below-ground marker shall have a steel plate welded onto the surface or conductor pipe of the abandoned well and shall be at least 3 feet below the ground surface and of sufficient size so that all the information required by Rule 103 can be stenciled into the steel or welded onto the surface of the steel plate. The OCD may require a re-survey of the well location.