




5/25/2000

Mr. Mark Ashley, Examiner
NMOCD
2040 South Pacheco Street
Santa Fe, NM 87505

Re: Order No. R-11381, West Bisti Unit 153, Conversion to SWD
CASE # 12365

Dear Mr. Ashley:

In the order above, a transposition of numbers resulted in an incorrect depth. Page 2, items (9) and (10) show casing holes at 2,379 to 2,747'. The correct depth for the upper hole is 2,739'. I wanted to let you know, should a correction be necessary.

Sincerely Yours,

John Alexander
Vice President