

# KERSEY AND COMPANY

P.O. Box 1248

Fredericksburg, TX 78624

830-997-7519

January 12, 2001

Tim Gum  
District II Supervisor  
Oil Conservation Division



Dear Mr. Gum;


When I visited with you back in October, I mentioned that we were unable to obtain a Pulling Unit to work on any wells, including those that have been in production recently. Since that time things have only gotten worse, as I now have several producing wells off. I regularly call all of the Pulling Unit Operators in S.E. New Mexico to stay current on their lists.

However, we are trying to use other methods to return the shut in wells to production. We have been able to contract with an operator of a cable tool drilling rig to start working on this group of wells. This work however, is only being done on a "when time is available" basis, and is rather slow. We have returned one well to production and are currently working on another that was not on your list that the BLM is pressuring us to return to production.

Please find enclosed Forms C-103 on all wells listed, with a plan of action.

Sincerely,

Kenneth R. Wade  
Kersey & Company



ASW-A-1 - PXA INTENT - 1/10/01

Federal ASW-1 RETURNED TO PROD 1/30/2000?

FEDERAL ASW-2 INTENT TO GO TO PRODUCTION - IF NOT PXA - APPROVED BY BLM 1/10/01

Y.D. FEDERAL-3 - NO INTENT - APPROVED BY BLM 1/10/01

FEDERAL-1 - SAME AS ASW-2

KERSEY INACT 111600.xls

API #	Type	Last Production/ Injection	Well Name and Number	Operator	U/STR	FNS	FEW
30-015-01306	G	03-1985	A S U A #001	KERSEY & CO	M-02-17S-28E	660S	660W
30-015-01337	G	10-1998	A S U #001	KERSEY & CO	A-10-17S-28E	660N	660E
30-015-10227	G	12-1993	A S U #002	KERSEY & CO	D-11-17S-28E	660N	660W
30-015-03471	O	09-1997	Y D #003	KERSEY & CO & E A HANSON	K-28-18S-29E	2310S	1980W
30-015-01310	G	12-1992	FEDERAL #001	KERSEY & DONOHUE	20-03-17S-28E	990S	990E

