

- H Centritugal pump and explosion proof electric motor
- I 3" Inst. Inc. Inline BS & W Monitor Probe
- J 3" Smith Strainer
- K 3" Smith Deareator
- L 2" Smith S-I2 positive displacement meter with automatic temperature compensator, horizontal non-reset counter, set stop counter, motor control switch and impulse transmitter to give one pulse per barrel
- M Texsteam Type 3700 Sample Pump and shop made sample container
- N 3" Plug Valve in Prover Manifold
- P 3" L -K Automatic Shut off & Back Pressure Valve with Diaphragm Head



PLAN VIEW

DETAIL SCHEMATIC DIAGRAM OF METERING SKID SOUTH VACUUM AUTOMATIC CUSTODY TRANSFER SYSTEM SOUTH VACUUM UNIT-LEA COUNTY, NEW MEXICO



EXIIBIT3