

Page 2482

WELL NAME	LOCATION	COMPANY	FORMATION	FIELD
Canyon Largo No. 111 (DK)	NE 1-24-1	EPNG	DK	Basin
Florance No. 10-D	NE 17-27-8	EPNG	MV	Blanco
Heaton No. 9 (MV)	NE 32-31-11	EPNG	MV	Blanco
Jicarilla No. 13-B	SE 34-25-4	EPNG	PC	S. Blanco
Jicarilla No. 12-F	SW 16-26-5	EPNG	PC	S. Blanco
Lackey No. 14-B	NE 30-28-9	EPNG	DK	Basin
Ludwick No. 10 (MV)	NE 29-30-10	EPNG	MV	Blanco
Ludwick No. 10 (PC)	NE 29-30-10	EPNG	PC	Aztec
Ludwick No. 18	NE 6-29-10	EPNG	DK	Basin
Mudge No. 6	SW 11-31-11	EPNG	MV	Blanco
Rincon No. 21	SW 16-27-6	EPNG	MV	Blanco
Rincon No. 80	NE 18-27-6	EPNG	MV	Blanco
Rincon No. 81	SW 17-27-6	EPNG	MV	Blanco
Rincon No. 99 (MV)	NE 27-27-6	EPNG	MV	Blanco
Rincon No. 150 (DK)	NE 6-26-6	EPNG	DK	Basin
Rosa No. 34	NE 36-32-6	EPNG	MV	Blanco
Russell No. 5	NE 25-28-8	EPNG	MV	Blanco
S.J.U. 27-4 No. 18	SW 4-27-4	EPNG	MV	Blanco
S.J.U. 27-5 No. 61	NE 5-27-5	EPNG	MV	Blanco
S.J.U. 28-4 No. 13	SW 20-28-4	EPNG	MV	Blanco
S.J.U. 28-6 No. 54	SW 7-27-6	EPNG	MV	Blanco
S.J.U. 28-7 No. 78	NE 19-27-7	EPNG	MV	Blanco
S.J.U. 29-5 No. 11	SW 19-29-5	EPNG	MV	Blanco
S.J.U. 29-6 No. 36	NE 15-29-6	EPNG	MV	Blanco
S.J.U. 32-9 No. 20	NE 18-31-9	EPNG	MV	Blanco
Schumacker No. 11	SW 18-30-10	EPNG	DK	Basin
Schwerdtfeger No. 12-A	SW 6-27-8	EPNG	MV	Blanco
Wilson No. 6	SW 35-30-7	EPNG	MV	Blanco
Schwerdtfeger No. 3	SW 5-27-11	Aztec O & G	PC	W. Kutz
N.C.R.A. State No. 1	NE 3-26-7	EP Products	DK	Basin
Foster No. 2	NE 17-26-7	J. Foster	PC	S. Blanco
Apache Fed. No. 10	SE 18-24-5	Gulf	DK	Basin
W No. 2-6	NE 6-26-5	Occidental	PC	S. Blanco
Jicarilla 146-10	SW 9-25-5	Pan Am.	DK	Basin
Jicarilla 146-11	SW 4-25-5	Pan Am.	DK	Basin
Jicarilla 153-13	SE 30-26-5	Pan Am.	DK	Basin
Jicarilla 155-12	SW 32-26-5	Pan Am.	DK	Basin
State G.U. J-1	NE 36-30-9	Pan Am.	MV	Blanco
Valentine G.U. No. 1	NE 32-32-10	Pan Am.	MV	Blanco
Walker No. 1	NW 3-29-12	Pioneer	DK	Basin
Marron No. 42 (DK)	SW 22-27-8	R & G	DK	Basin
Marron No. 42 (MV)	SW 22-27-8	R & G	MV	Blanco
N.M. Fed. Deep U No. 1	NE 19-29-10	Tidewater	DK	Basin

PAN AMERICAN PETROLEUM CORPORATION
~~XXXXXXXXXXXXXXXXXXXX~~
SAN JUAN & RIO ARriba COUNTIES, NEW MEXICO

Wells Not Completing 1961 Deliverability Tests

	<u>Well Name</u>	<u>Location</u>
1.	El Paso System	
	Jicarilla Contract 146 No. 10	N- 9-25-5
	Jicarilla Contract 146 No. 11	K- 4-25-5
	Jicarilla Contract 155 No. 12	K-32-26-5
	Jicarilla Contract 155 No. 13	I-30-26-5
2.	Southern Union System	
	Johnson "B"	H-21-27-10
	Fred Feasel "G"	K- 2-27-10
	Fred Feasel "H"	H-33-28-10
	J. F. Day "E"	L-17-28-10
	R. P. Hargrave "H"	B- 9-27-10
	E. H. Pipkin No. 5	B-36-28-11
	Davidson "F"	M-28-28-10
	Davidson "G"	H-21-28-10
	Fred Feasel "J"	G-34-28-10
	M. N. Galt "H"	L- 1-27-10
3.	El Paso System	
	State Gas Unit "J"	A-36-30-9
4.	El Paso System	
	Jicarilla Contract 155 No. 5	D-31-26-5

BEFORE EXAMINER UTZ
OIL CONSERVATION COMMISSION

Pan Am. EXHIBIT NO. 1
CASE NO. 2482

PAN AMERICAN PETROLEUM CORPORATION

SAN JUAN & RIO ARriba COUNTIES, NEW MEXICO

335 total
Wells Not Completing 1961 Deliverability Tests

<u>Well Name</u>	<u>Location</u>	
1. El Paso System		
Jicarilla Contract 146 No. 10	N- 9-25-5	<i>PR</i> <i>Con. late in 1961</i>
Jicarilla Contract 146 No. 11	K- 4-25-5	<i>sc. Nov.</i>
Jicarilla Contract 155 No. 12	K-32-26-5	<i>Sub P. last test.</i>
Jicarilla Contract 155 No. 13	I-30-26-5	
2. Southern Union System		
Johnson "B"	H-21-27-10	<i>Angels P. h area</i>
Fred Feasel "G"	K- 2-27-10	<i>2nd discov.</i>
Fred Feasel "H"	H-33-28-10	<i>no isched. or</i>
J. F. Day "E"	L-17-28-10	<i>sect.</i>
R. P. Hargrave "H"	B- 9-27-10	<i>last off test.</i>
E. H. Pipkin No. 5	B-36-28-11	<i>Jan 5, 62</i>
Davidson "F"	M-28-28-10	
Davidson "G"	H-21-28-10	
Fred Feasel "J"	G-34-28-10	
M. N. Galt "H"	L- 1-27-10	
3. El Paso System		
State Gas Unit "J"	A-36-30-9	<i>W.O. 11-23-61</i>
		<i>black topped</i>
4. El Paso System		
Jicarilla Contract 155 No. 5	D-31-26-5	<i>S.B. 4-30-61-5e</i>
		<i>SIP, com. 1-25-62</i>

2-10-62

EL PASO NATURAL GAS COMPANY

Well Name and Number	Location	Pool and Formation	See Page 2.
Florance 10-D	B 17-27-8	Blanco MV	6, 1
Heaton 8 (MV)	B 30-31-11	Blanco MV	2, 7, 6
Howell 1 C	B 1-29-8	Blanco MV	5, 9, 7
Rincon 21	L 16-27-6	Blanco MV	6, 1
Rincon 80	B 18-27-6	Blanco MV	5, 4
Rincon 81	K 17-27-6	Blanco MV	6, 4
Rincon 99 (MV)	A 27-27-6	Blanco MV	6, 1
Rosa 34	B 36-32-6	Blanco MV	3, 6, 7, 7, 3
Russell 5	G 25-28-8	Blanco MV	6, 8
SJU 27-5 #61	G 5-27-5	Blanco MV	1, 1
SJU 28-4 #13	N 20-28-4	Blanco MV	6, 4
SJU 28-7 #51	B 24-28-7	Blanco MV	6, 1
SJU 28-7 #82 (MV)	A 4-27-7	Blanco MV	6, 1
SJU 30-5 #30	L 21-30-5	Blanco MV	6, 7, 3
SJU 32-8 #17	M 23-31-8	Blanco MV	6, 4
SJU 32-9 #30	H 36-32-10	Blanco MV	6, 4
SJU 32-9 #50	A 25-32-10	Blanco MV	6, 4
Wilson 6	N 35-30-7	Blanco MV	8, 7
SJU 28-6 #54	N 7-27-6	Blanco MV	7, 1
SJU 30-5 #33	A 20-30-5	Blanco MV	7, 3
<i>Harlie C^d1</i>	<i>G 19-29-7</i>	<i>Blanco MV</i>	
Jicarilla 13-B	P 34-25-4	South Blanco PC	6, 4
Jicarilla 12-F	K 16-26-5	South Blanco PC	<i>Broke Test in Dec.</i>
Jicarilla 13-F	E 16-26-5	South Blanco PC	1
SJU 28-6 #92 (PC)	G 2-27-6	South Blanco PC	<i>Tubing leak</i>
<i>Jicarilla 8-B</i>	<i>G 28-28-4</i>	<i>South Blanco PC</i>	1
Heaton 8 (PC)	B 30-31-11	Aztec PC	2, 7, 7
Ludwick 18	B 6-29-10	Basin DK	5, 5, 6
Schumacker 11	K 18-30-10	Basin DK	6, 10

REASONS FOR FAILURE TO COMPLETE DELIVERABILITY TESTS DURING 1961

1. Freezing conditions.
2. Line blowouts.
3. Impassable roads.
- ? 4. Retest required by NMOCC.
5. Location equipment failure.
- ? 6. Poor test.
7. Failed to turn well on at appropriate time.
8. Failed to turn well off at appropriate time. *Due to high demand*
- ? 9. Failure to obtain shut-in pressures.
- ? 10. Well loaded up with fluids.
11. *Widow unfamiliar with procedure.*
12. *Clock stopped*
13. *Well caught fire*
14. *Chart lost in mail*
15. *Switches got stuck. (if cold enough)*